Register entry, as of 27 October 2026 Listed for sale Record ID 1fce52983f74

2016 Lincoln MKC Premier

2.0 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5LM	CJ1D9	2	G	U	J02890
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Lincoln · FORD MOTOR CO…	MKC · 2.0 L	Verified	2016	Louisville	Build sequence

§1 IDENTITY [1]

Model year	2016	Engine	2.0 L, 4 cylinders
Make	Lincoln	Fuel	Gasoline
Model	MKC	Drive	4WD
Trim	Premier	Maker	FORD MOTOR COMPANY
Body	Sport Utility Vehicle	Plant	Louisville, Kentucky, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/lincoln/mkc/2016

6 recalls listed by Transport Canada for this model year

Electrical — 2026005 — 9 Jan 2026

Issue: On certain vehicles, the engine block heater could leak coolant. If this happens, the block heater could short circuit when it's plugged in. Note: This recall replaces Transport Canada recall no. 2025-554. Vehicles that were repaired under that recall don't require this repair. Safety Risk: A short circuit can create the risk of a fire. Corrective Actions: To reduce the safety risk, Ford advises you not to use the engine block heater until the recall repairs have been completed. Ford will notify owners by mail and advise you to take your vehicle to a dealership to replace the block heater. Alternatively, owners can choose to have the dealership permanently disable the engine block heater.

Electrical — 2026004 — 9 Jan 2026

Issue: On certain vehicles, the engine block heater could leak coolant. If this happens, the block heater could short circuit when it's plugged in. Note: This recall only affects certain vehicles equipped with a 2.0 L engine. Safety Risk: A short circuit can create the risk of a fire. Corrective Actions: To reduce the safety risk, Ford advises you not to use the engine block heater until the recall repairs have been completed. Ford will notify owners by mail and advise you to take your vehicle to a dealership to replace the block heater. Alternatively, owners can choose to have the dealership permanently disable the engine block heater.

Electrical — 2025554 — 10 Oct 2025

This recall was replaced by Transport Canada recall no. 2026-005. Issue: On certain vehicles, the engine block heater could leak coolant. If this happens, the block heater could short circuit when it's plugged in. Safety Risk: A short circuit can create the risk of a fire. Corrective Actions: To reduce the safety risk, Ford advises you not to use the engine block heater until the recall repairs have been completed. Ford will notify owners by mail and advise you to take your vehicle to a dealership to replace the block heater.

Visual system

2025449 3 Sep 2025

Issue: On certain vehicles, there could be a problem with the connections inside the rearview camera. As a result, the rearview camera image may not display correctly or at all when the transmission is shifted into reverse. Note: For certain models, this recall also affects incomplete vehicles. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the rearview camera.

Electrical

2023310 29 May 2023

Issue: On certain vehicles, the battery monitor sensor could be damaged during servicing. If this happens, the battery monitor system could short circuit. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Ford will notify owners by mail and instruct you to bring your vehicle to a Ford dealership to install an in-line fuse for the battery monitor sensor. Ford advises to park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.

Engine

2016138 31 Mar 2016

On certain vehicles equipped with a 2.3 litre GTDI engine and an engine block heater, due to the engine’s orientation, the block heater could be susceptible to overheating. An overheated engine block heater may result in engine coolant leakage, or heat damage to the electrical connector of the block heater. Overheating of the engine block heater may increase the risk of an underhood fire causing injury and/or property damage. Correction: Dealers will replace the engine block heater element with one of a different design, and will inspect the block heater's electrical cord, and replace if required. In the interim, owners are advised to stop using their block heater until the campaign is completed. Note: This risk only exists when the block heater is plugged in and the vehicle is parked.

Listed for the model year, not checked against your VIN. Lincoln confirms which apply.
Check your VIN with Lincoln Canada or call a Lincoln dealer with your VIN.
www.lincolncanada.com/support/recalls/

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $9,995[5], $2,440 under the median of $12,435[4].



Lowest ask	$8,998
Middle half	$11,792 – $14,930
Median ask	$12,435
This car	$9,995

Same model year · 10 live listings · as of 27 Oct 2026

OTHER 2016 LINCOLN MKC LISTINGS [5]

Guelph, ON · 133,303 km	$14,999
Gatineau, QC · 148,813 km	$12,880
Ottawa, ON · 146,883 km	$14,871
North Vancouver District, BC · 156,846 km	$11,731
Saint-Georges, QC · 166,396 km	$8,998
Mirabel, QC · 153,160 km	$11,977

§4 EVENTS

2016	Model year 2016[1] Assembly plant Louisville, Kentucky, United States
31 Mar 2016	Transport Canada recall 2016138[2] Issued for the model year · Engine
29 May 2023	Transport Canada recall 2023310[2] Issued for the model year · Electrical
3 Sep 2025	Transport Canada recall 2025449[2] Issued for the model year · Visual system
10 Oct 2025	Transport Canada recall 2025554[2] Issued for the model year · Electrical
9 Jan 2026	Transport Canada recall 2026005[2] Issued for the model year · Electrical
9 Jan 2026	Transport Canada recall 2026004[2] Issued for the model year · Electrical
26 Oct 2026	Listed for sale, Lévis, QC[5] autosrivesud.ca · asking $9,995
27 Oct 2026	Listing last updated[5] asking $9,995

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 10 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.