Register entry, as of 29 October 2026 Listed for sale Record ID 1ba3ed32ba4e

2021 Lincoln Navigator Reserve

3.5 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5LM	JJ2LT	7	M	E	L05161
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Lincoln · FORD MOTOR CO…	Navigator · 3.5 L	Verified	2021	Jefferson County	Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	3.5 L, 6 cylinders
Make	Lincoln	Fuel	Gasoline
Model	Navigator	Drive	4WD
Trim	Reserve	Maker	FORD MOTOR COMPANY
Body	Sport Utility Vehicle	Plant	Jefferson County, Kentucky, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/lincoln/navigator/2021

13 recalls listed by Transport Canada for this model year

Powertrain

2026311 24 Jun 2026

Issue: On certain vehicles, a problem in the transmission could cause the parking pawl to become damaged. As a result, when the transmission is shifted to Park, the vehicle could move if the parking brake is not applied. Safety Risk: A parked vehicle that rolls away could create the risk of an injury or a crash. Corrective Actions: To reduce the safety risk, Ford recommends that you should always use the parking brake when you park until the recall repairs are completed. Ford will notify owners by mail and advise you to take your vehicle to a dealership to update the powertrain control module (PCM) software. The dealer will also inspect and, if necessary, replace any damaged transmission components.

Seats and restraints

2026257 27 May 2026

Issue: On certain vehicles, there could be a problem with the driver and/or front passenger seatbelt pretensioner(s). As a result, the airbag warning light could turn on, and the seatbelt pretensioners could deploy without a crash. Note: This recall replaces Transport Canada recall nos. 2024-084 and 2025-164. Vehicles that were repaired under those recalls also require this inspection or repair. Safety Risk: Seat belt pretensioners that don't work properly could create an increased risk of injury. Additionally, seat belt pretensioners that deploy without a crash could startle the driver and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the driver and front passenger seatbelt retractors.

Visual system

2026161 1 Apr 2026

Issue: On certain trucks, the windshield wiper arms may not have been manufactured correctly. As a result, the wiper arm(s) could break or become detached and may not wipe the windshield properly. Safety Risk: Windshield wipers that do not work properly could affect a driver's visibility. Windshield wiper(s) that detach from the vehicle could create a road hazard for others. Both issues could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail. The corrective actions for this recall are under development.

Structure

2025587 24 Oct 2025

Issue: On certain vehicles, the moonroof wind deflector may not have been attached properly. As a result, the deflector could detach from the vehicle. Note: This recall also affects certain Super Duty incomplete vehicles. Safety Risk: A moonroof wind deflector that detaches from the vehicle could create a hazard for others and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, repair the moonroof wind deflector.

Fuel system

2025366 8 Jul 2025

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to update the powertrain control module software. For Super Duty models, the dealer will replace the fuel pump.

Visual system

2025360 27 Jun 2025

Issue: On certain vehicles, a software problem could cause the rearview camera image not to display when the transmission is shifted into reverse. Canadian regulations require the rearview image to display when the vehicle is reversing. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to update the SYNC software.

7 more on the model-year record, cardog.app/tools/recalls/lincoln/navigator/2021

> Listed for the model year, not checked against your VIN. Lincoln confirms which apply.
> Check your VIN with Lincoln Canada or call a Lincoln dealer with your VIN.
> www.lincolncanada.com/support/recalls/

United States: 12 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $52,900[5], $3,001 over the median of $49,899[4].

Lowest ask	$33,950
Middle half	$45,718 – $59,497
Median ask	$49,899
This car	$52,900

Same configuration · 8 live listings · as of 29 Oct 2026

OTHER 2021 LINCOLN NAVIGATOR LISTINGS [5]

Tillsonburg, ON · 140,111 km	$43,389
Edmonton, AB · 145,012 km	$46,898
Regina, SK · 145,012 km	$52,291
Campbell River, BC · 80,787 km	$62,998
Mississauga, ON · 76,386 km	$58,700
Leamington, ON · 76,386 km	$58,700

§4 EVENTS

2021 **Model year 2021**[1]
Assembly plant Jefferson County, Kentucky, United States

18 Oct 2021	Transport Canada recall 2021638[2] Issued for the model year · Airbag
14 Apr 2022	Transport Canada recall 2022197[2] Issued for the model year · Visual system
17 May 2022	Transport Canada recall 2022257[2] Issued for the model year · Electrical
9 Jun 2023	Transport Canada recall 2023341[2] Issued for the model year · Seats and restraints
28 Aug 2023	Transport Canada recall 2023477[2] Issued for the model year · Visual system
11 Apr 2025	Transport Canada recall 2025199[2] Issued for the model year · Visual system
24 Apr 2025	Transport Canada recall 2025223[2] Issued for the model year · Visual system
27 Jun 2025	Transport Canada recall 2025360[2] Issued for the model year · Visual system
8 Jul 2025	Transport Canada recall 2025366[2] Issued for the model year · Fuel system
24 Oct 2025	Transport Canada recall 2025587[2] Issued for the model year · Structure
1 Apr 2026	Transport Canada recall 2026161[2] Issued for the model year · Visual system
27 May 2026	Transport Canada recall 2026257[2] Issued for the model year · Seats and restraints
24 Jun 2026	Transport Canada recall 2026311[2] Issued for the model year · Powertrain
29 Oct 2026	Listed for sale, Montréal-Nord, QC[5] Circuit Ford Lincoln · asking $52,900

§5 DOCUMENTS

Window sticker — We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 8 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.