

Register entry, as of 27 October 2026

Listed for sale

Record ID 6f3482ec291e

2025 Lincoln Corsair Grand Touring

2.5 L, 4 cylinders · 4WD · Sport Utility Vehicle · Electric

VEHICLE IDENTIFICATION NUMBER [1]

5LM TJ5DZ 6 S U L02431

WMI 1-3

Lincoln · FORD MOTOR CO...

DESCRIPTOR 4-8

Corsair · 2.5 L

CHECK 9

Verified

YEAR 10

2025

PLANT 11

Louisville

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2025	Engine	2.5 L, 4 cylinders
Make	Lincoln	Fuel	Electric
Model	Corsair	Drive	4WD
Trim	Grand Touring	Maker	FORD MOTOR COMPANY
Body	Sport Utility Vehicle	Plant	Louisville, Kentucky, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/lincoln/corsair/2025

6 recalls listed by Transport Canada for this model year

Engine 2026094 3 Mar 2026

Issue: On certain vehicles, the exhaust gas recirculation (EGR) valve may not have been manufactured properly. As a result, the EGR valve could fail and cause a loss of power to the wheels. Note: This recall only affects certain vehicles equipped with a 1.5 L engine, 2.0 L gas or hybrid engine or 2.3 L engine. Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail. The corrective actions for this recall are under development.

High voltage 2026070 18 Feb 2026

Issue: On certain vehicles, the software update installed by a Ford dealer during recall 24S79 (Transport Canada recall no. 2024-781) may not be effective. As a result, a second repair is required. On certain vehicles, a problem inside the high-voltage battery could cause a short circuit. If this happens, there could be a loss of power to the wheels and/or the high-voltage battery could overheat. Note: This recall replaces Transport Canada recall no. 2025-628. This recall only affects certain plug-in hybrid vehicles (PHEV) equipped with a 2.5 L engine. Safety Risk: A loss of power to the wheels could increase the risk of a crash. A battery that overheats can create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: To reduce the safety risk, Ford advises that you set the maximum charge setting of your vehicle at 80% and to only use normal EV mode until the recall repairs have been completed. Ford will notify owners by mail. The corrective actions for this recall are under development.

Seats and restraints 2025690 12 Dec 2025

Issue: On certain vehicles, the left and right rear seat belt retractors may not have been secured properly. As a result, the seat belts may not work properly in a crash. Safety Risk: A seat belt that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and secure or replace the rear seat belt retractor bolts, as necessary.



Visual system

2025583 24 Oct 2025

Issue: On certain vehicles, the windshield glass may not have been manufactured properly. As a result, air bubbles could appear in the windshield glass. Safety Risk: Air bubbles in the windshield glass could cause reduced visibility and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the windshield glass.

Lights and instruments

2025551 11 Oct 2025

Issue: On certain vehicles, the rear combination lamps may have been damaged during production. As a result, water could enter the rear combination lamps and cause the reverse lamps, brake lamps, taillamps and rear turn signals not to work. Safety Risk: Brake lights, reverse lights and/or turn signals that don't work could cause a person not to recognize that a vehicle ahead is braking, backing up or about to turn. Tail lights that don't work could make the vehicle less visible to others. All these issues could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the rear combination lamps.

Engine

2025281 23 May 2025

Issue: On certain vehicles, the engine block heater could overheat when the block heater is plugged in. Note: This recall only affects certain vehicles equipped with a 1.5 L or 2.0 L engine and a factory-installed block heater. Safety Risk: An engine block heater and/or wiring that overheats or melts could create the risk of a fire. Corrective Actions: To reduce the safety risk, Ford advises you not to plug in the engine block heater until the recall repairs have been completed. Ford will notify owners by mail. You can choose to have the dealer remove the block heater, or once the final repair is available, Ford will send you another notice to advise you to take your vehicle to a dealership to replace the block heater element. The dealer will also inspect and, if necessary, replace the block heater electrical cord.

Listed for the model year, not checked against your VIN. Lincoln confirms which apply.

Check your VIN with Lincoln Canada or call a Lincoln dealer with your VIN.

www.lincolncanada.com/support/recalls/

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$61,716^[5], \$5,816 over the median of \$55,900^[4].



Lowest ask	\$49,990
Middle half	\$52,988 – \$61,716
Median ask	\$55,900
This car	\$61,716

Same configuration · 9 live listings · as of 27 Oct 2026

OTHER 2025 LINCOLN CORSAIR LISTINGS [5]

Toronto, ON · 22,058 km	\$52,488
Wetaskiwin, AB · 40,496 km	\$46,550
Toronto, ON · 22,058 km	\$52,488
Edmonton, AB · 59,983 km	\$43,000
Edmonton, AB · 59,983 km	\$43,000
Wetaskiwin, AB · 34,539 km	\$49,990

§4 EVENTS

2025

Model year 2025^[1]

Assembly plant Louisville, Kentucky, United States



23 May 2025	Transport Canada recall 2025281 ^[2] Issued for the model year · Engine
11 Oct 2025	Transport Canada recall 2025551 ^[2] Issued for the model year · Lights and instruments
24 Oct 2025	Transport Canada recall 2025583 ^[2] Issued for the model year · Visual system
12 Dec 2025	Transport Canada recall 2025690 ^[2] Issued for the model year · Seats and restraints
18 Feb 2026	Transport Canada recall 2026070 ^[2] Issued for the model year · High voltage
3 Mar 2026	Transport Canada recall 2026094 ^[2] Issued for the model year · Engine
25 Oct 2026	Listed for sale, Laval, QC ^[5] 440 Lincoln Laval · asking \$61,716
27 Oct 2026	Listing last updated ^[5] asking \$61,716

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same configuration, 9 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

