

Register entry, as of 27 October 2026

Listed for sale

Record ID a9a6f03f1f08

# 2018 Nissan Murano

3.5 L, 6 cylinders · 4WD · Crossover Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER <sup>[1]</sup>**5N1** **AZ2MH** **1** **J** **N** **134523**

WMI 1-3

Nissan North America, Inc.

DESCRIPTOR 4-8

Murano · 3.5 L

CHECK 9

Verified

YEAR 10

2018

PLANT 11

Canton

SERIAL 12-17

Build sequence

## §1 IDENTITY <sup>[1]</sup>

|            |                           |        |                                    |
|------------|---------------------------|--------|------------------------------------|
| Model year | 2018                      | Engine | 3.5 L, 6 cylinders                 |
| Make       | Nissan                    | Fuel   | Gasoline                           |
| Model      | Murano                    | Drive  | 4WD                                |
| Trim       | Not in the decode         | Maker  | NISSAN NORTH AMERICA, INC.         |
| Body       | Crossover Utility Vehicle | Plant  | Canton, Mississippi, United States |

## §2 OBLIGATIONS <sup>[2]</sup>

[cardog.app/tools/recalls/nissan/murano/2018](https://cardog.app/tools/recalls/nissan/murano/2018)

## 2 recalls listed by Transport Canada for this model year

### Brakes

2019567 11 Nov 2019

Issue: On certain vehicles, the antilock brake system (ABS) actuator pump may leak brake fluid and malfunction. This would cause the ABS warning lamp to turn on. If this problem is not fixed, damage to the ABS actuator could result in a short circuit. Note: This is a replacement and expansion of Transport Canada recall 2018-486. All vehicles that did not have the ABS actuator pump replaced under that recall require this repair. Safety Risk: A short circuit could increase the risk of a fire, even while parked. Corrective Actions: The company will notify owners by mail with an interim notice. A final repair is not yet available. If the ABS warning light stays on for 10 seconds or longer, you should park your vehicle outdoors away from other vehicles or structures. You should also call Nissan or Infiniti Roadside assistance to have your vehicle towed to a dealer for repair. A second notice will be sent to you once the final repair parts are available. This letter will advise you to take their vehicle to a dealer to replace the ABS actuator.

### Visual system

2019459 13 Sep 2019


Issue: On certain vehicles, the rear view camera system does not return to the default setting when the transmission is shifted to reverse. This could cause a reduction in rear visibility if a driver had previously adjusted the camera display. Canadian regulations require that the rear view image returns to its original setting each time the camera is turned on. Safety Risk: Reduced rear visibility could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to update the software for the rear view camera.

Listed for the model year, not checked against your VIN. Nissan confirms which apply.  
Check your VIN with Nissan Canada or call a Nissan dealer with your VIN.

[www.nissan.ca/service/vin-recall.html](https://www.nissan.ca/service/vin-recall.html)United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

## §3 VALUE [4]

This car asks \$12,777<sup>[5]</sup>, \$2,693 under the median of \$15,470<sup>[4]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$6,995             |
| Middle half | \$12,495 – \$18,988 |
| Median ask  | \$15,470            |
| This car    | \$12,777            |

Same configuration · 48 live listings · as of 27 Oct 2026

## OTHER 2018 NISSAN MURANO LISTINGS [5]

|                             |          |
|-----------------------------|----------|
| London, ON · 127,748 km     | \$17,021 |
| London, ON · 127,748 km     | \$20,258 |
| Gatineau, QC · 146,731 km   | \$15,444 |
| Airdrie, AB · 158,738 km    | \$18,955 |
| Georgetown, ON · 127,748 km | \$20,258 |
| London, ON · 127,748 km     | \$20,258 |

## §4 EVENTS

|             |                                                                                             |
|-------------|---------------------------------------------------------------------------------------------|
| 2018        | Model year 2018 <sup>[1]</sup><br>Assembly plant Canton, Mississippi, United States         |
| 13 Sep 2019 | Transport Canada recall 2019459 <sup>[2]</sup><br>Issued for the model year · Visual system |
| 11 Nov 2019 | Transport Canada recall 2019567 <sup>[2]</sup><br>Issued for the model year · Brakes        |
| 26 Oct 2026 | Listed for sale, Ottawa, ON <sup>[5]</sup><br>CarCity · asking \$12,777                     |
| 27 Oct 2026 | Listing last updated <sup>[5]</sup><br>asking \$12,777                                      |

## §5 DOCUMENTS

Window sticker      We have not collected this label yet.

## SOURCES

- |                                                                     |                                                                                  |
|---------------------------------------------------------------------|----------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same configuration, 48 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     | [5] Live public dealer listings on Cardog, as of 27 Oct 2026                     |
| [3] NHTSA recall records (United States), listed for the model year |                                                                                  |



---

**STATEMENT OF SCOPE**

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

