Register entry, as of 29 October 2026 Listed for sale Record ID 1d793b5c6ace

2015 Nissan Murano

3.5 L, 6 cylinders · 4WD · Crossover Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5N1	AZ2MH	8	F	N	286046
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Nissan North America, Inc.	Murano · 3.5 L	Verified	2015	Canton	Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	3.5 L, 6 cylinders
Make	Nissan	Fuel	Gasoline
Model	Murano	Drive	4WD
Trim	Not in the decode	Maker	NISSAN NORTH AMERICA, INC.
Body	Crossover Utility Vehicle	Plant	Canton, Mississippi, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/nissan/murano/2015

5 recalls listed by Transport Canada for this model year

Brakes

2019567 11 Nov 2019

Issue: On certain vehicles, the antilock brake system (ABS) actuator pump may leak brake fluid and malfunction. This would cause the ABS warning lamp to turn on. If this problem is not fixed, damage to the ABS actuator could result in a short circuit. Note: This is a replacement and expansion of Transport Canada recall 2018-486. All vehicles that did not have the ABS actuator pump replaced under that recall require this repair. Safety Risk: A short circuit could increase the risk of a fire, even while parked. Corrective Actions: The company will notify owners by mail with an interim notice. A final repair is not yet available. If the ABS warning light stays on for 10 seconds or longer, you should park your vehicle outdoors away from other vehicles or structures. You should also call Nissan or Infiniti Roadside assistance to have your vehicle towed to a dealer for repair. A second notice will be sent to you once the final repair parts are available. This letter will advise you to take their vehicle to a dealer to replace the ABS actuator.

Brakes

2018486 10 Sep 2018

On certain vehicles, the antilock brake system (ABS) actuator pump may leak brake fluid onto an electronic circuit board, causing it to malfunction. This would cause the illumination of the ABS warning lamp on the instrument panel. If the vehicle continues to be operated, damage to the ABS module could lead to a fire, creating a risk of injury and/or damage to property. Correction: Dealers will inspect and replace the ABS actuator as necessary. Note: This replaces recall 2016-424. Vehicles repaired under that campaign require a second repair under this campaign.

Brakes

2016424 1 Sep 2016

Certain vehicles equipped with Intelligent Cruise Control may have ABS actuators that may have been manufactured out of specification. This could cause the ABS actuator pump seal to leak brake fluid. This would cause the ABS warning light to illuminate, and if ignored, and the vehicle continues to be operated in this condition, the brake fluid leak could create an electrical short in the actuator circuit. This could lead to a fire, which could increase the risk of injury and/or damage to property. Correction: Dealers will inspect the ABS actuator, and will replace as necessary.

Seats and restraints

2016179 25 Apr 2016

On certain vehicles, a defect in the occupant classification system could allow an adult sitting in the front passenger seat to be classified as a child or an “empty seat”. This would suppress the airbag, which could increase the risk of injury in a crash. Correction: For affected Altima, Maxima, Murano, Rogue and Sentra vehicles, dealers will reprogram the airbag control unit and the occupant classification system control unit. For affected Leaf, NV200, Pathfinder, Q50 and JX35/QX60 vehicles, dealers will replace the occupant classification system electronic control unit.

Brakes

2015248 4 Jun 2015

Certain vehicles may have been manufactured with a defective Anti-Lock Braking System (ABS) actuator. This could cause pressure control to be delayed when the Anti-Lock Brakes are activated, resulting in loss of vehicle stability, increasing the risk of a crash causing in injury and/or damage to property. Correction: Dealers will inspect the ABS actuator and, if affected, replace the defective ABS actuator.

> Listed for the model year, not checked against your VIN. Nissan confirms which apply.
> Check your VIN with Nissan Canada or call a Nissan dealer with your VIN.
> www.nissan.ca/service/vin-recall.html

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $13,788[5], $3,948 over the median of $9,840[4].



Lowest ask	$5,500
Middle half	$7,999 – $10,995
Median ask	$9,840
This car	$13,788

Same configuration · 18 live listings · as of 29 Oct 2026

OTHER 2015 NISSAN MURANO LISTINGS [5]

Sault Ste Marie, ON · 187,000 km	$7,549
Ottawa, ON · 163,804 km	$10,987
Lorrainville, QC · 240,674 km	$8,500
Edmonton, AB · 308,227 km	$5,500
Surrey, BC · 152,497 km	$9,980
Trois-Rivières, QC · 202,000 km	$6,995

§4 EVENTS

2015	Model year 2015[1] Assembly plant Canton, Mississippi, United States
4 Jun 2015	Transport Canada recall 2015248[2] Issued for the model year · Brakes
25 Apr 2016	Transport Canada recall 2016179[2] Issued for the model year · Seats and restraints
1 Sep 2016	Transport Canada recall 2016424[2] Issued for the model year · Brakes

10 Sep 2018	Transport Canada recall 2018486[2] Issued for the model year · Brakes
11 Nov 2019	Transport Canada recall 2019567[2] Issued for the model year · Brakes
11 Jul 2026	Listed for sale, Surrey, BC[5] Sukhi Bath Motors · asking $13,788
28 Oct 2026	Listing last updated[5] asking $13,788

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 18 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.