

Register entry, as of 28 October 2026

Listed for sale

Record ID 002ec084f6a6

2017 Infiniti QX60

3.5 L, 6 cylinders · 4WD · Crossover Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5N1 **DL0MM** **3** **H** **C** **526232**

WMI 1-3

Infiniti · NISSAN NORTH AM...

DESCRIPTOR 4-8

QX60 · 3.5 L

CHECK 9

Verified

YEAR 10

2017

PLANT 11

Smyrna

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2017	Engine	3.5 L, 6 cylinders
Make	Infiniti	Fuel	Gasoline
Model	QX60	Drive	4WD
Trim	Not in the decode	Maker	NISSAN NORTH AMERICA, INC.
Body	Crossover Utility Vehicle	Plant	Smyrna, Tennessee, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/infiniti/qx60/2017

3 recalls listed by Transport Canada for this model year

Powertrain

2021613 5 Oct 2021

Issue: On certain hybrid vehicles, a software error with the hybrid powertrain control module (HPCM) may cause the powertrain to shut down. If this happens, both the engine and electric motor can turn off, and cause a loss of power to the wheels. Safety Risk: A loss of power to the wheels could increase the risk of a crash. Corrective Actions: Nissan will notify owners by mail and instruct you to take your vehicle to a dealer to reprogram the HPCM.

Brakes

2019567 11 Nov 2019

Issue: On certain vehicles, the antilock brake system (ABS) actuator pump may leak brake fluid and malfunction. This would cause the ABS warning lamp to turn on. If this problem is not fixed, damage to the ABS actuator could result in a short circuit. Note: This is a replacement and expansion of Transport Canada recall 2018-486. All vehicles that did not have the ABS actuator pump replaced under that recall require this repair. Safety Risk: A short circuit could increase the risk of a fire, even while parked. Corrective Actions: The company will notify owners by mail with an interim notice. A final repair is not yet available. If the ABS warning light stays on for 10 seconds or longer, you should park your vehicle outdoors away from other vehicles or structures. You should also call Nissan or Infiniti Roadside assistance to have your vehicle towed to a dealer for repair. A second notice will be sent to you once the final repair parts are available. This letter will advise you to take their vehicle to a dealer to replace the ABS actuator.

Brakes

2018486 10 Sep 2018

On certain vehicles, the antilock brake system (ABS) actuator pump may leak brake fluid onto an electronic circuit board, causing it to malfunction. This would cause the illumination of the ABS warning lamp on the instrument panel. If the vehicle continues to be operated, damage to the ABS module could lead to a fire, creating a risk of injury and/or damage to property. Correction: Dealers will inspect and replace the ABS actuator as necessary. Note: This replaces recall 2016-424. Vehicles repaired under that campaign require a second repair under this campaign.



Listed for the model year, not checked against your VIN. Infiniti confirms which apply.
 Check your VIN with Infiniti Canada or call a Infiniti dealer with your VIN.
www.infiniti.ca/service/vin-recall.html

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$13,498^[5], \$1,486 under the median of \$14,984^[4].



Lowest ask	\$6,795
Middle half	\$12,996 – \$17,308
Median ask	\$14,984
This car	\$13,498

Same configuration · 30 live listings · as of 28 Oct 2026

OTHER 2017 INFINITI QX60 LISTINGS ^[5]

Edmonton, AB · 120,200 km	\$18,266
Winnipeg, MB · 120,200 km	\$18,266
Winnipeg, MB · 120,200 km	\$18,266
Regina, SK · 120,200 km	\$18,266
Victoria, BC · 144,341 km	\$13,995
Brantford, ON · 239,998 km	\$6,900

§4 EVENTS

2017	Model year 2017 ^[1] Assembly plant Smyrna, Tennessee, United States
10 Sep 2018	Transport Canada recall 2018486 ^[2] Issued for the model year · Brakes
11 Nov 2019	Transport Canada recall 2019567 ^[2] Issued for the model year · Brakes
5 Oct 2021	Transport Canada recall 2021613 ^[2] Issued for the model year · Powertrain
21 Aug 2026	Listed for sale, Newmarket, ON ^[5] Newmarket Mitsubishi · asking \$13,498
28 Oct 2026	Listing last updated ^[5] asking \$13,498

§5 DOCUMENTS

Window sticker We have not collected this label yet.



SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same configuration, 30 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

