Register entry, as of 27 October 2026 Listed for sale Record ID 1d7b22eb5772

2018 Infiniti QX60

3.5 L, 6 cylinders · 4WD · Crossover Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5N1	DL0MM	X	J	C	506002
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Infiniti · NISSAN NORTH AM…	QX60 · 3.5 L	Verified	2018	Smyrna	Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	3.5 L, 6 cylinders
Make	Infiniti	Fuel	Gasoline
Model	QX60	Drive	4WD
Trim	Not in the decode	Maker	NISSAN NORTH AMERICA, INC.
Body	Crossover Utility Vehicle	Plant	Smyrna, Tennessee, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/infiniti/qx60/2018

1 recall listed by Transport Canada for this model year

Brakes

2019567 11 Nov 2019

Issue: On certain vehicles, the antilock brake system (ABS) actuator pump may leak brake fluid and malfunction. This would cause the ABS warning lamp to turn on. If this problem is not fixed, damage to the ABS actuator could result in a short circuit. Note: This is a replacement and expansion of Transport Canada recall 2018-486. All vehicles that did not have the ABS actuator pump replaced under that recall require this repair. Safety Risk: A short circuit could increase the risk of a fire, even while parked. Corrective Actions: The company will notify owners by mail with an interim notice. A final repair is not yet available. If the ABS warning light stays on for 10 seconds or longer, you should park your vehicle outdoors away from other vehicles or structures. You should also call Nissan or Infiniti Roadside assistance to have your vehicle towed to a dealer for repair. A second notice will be sent to you once the final repair parts are available. This letter will advise you to take their vehicle to a dealer to replace the ABS actuator.

Listed for the model year, not checked against your VIN. Infiniti confirms which apply.
Check your VIN with Infiniti Canada or call a Infiniti dealer with your VIN.
www.infiniti.ca/service/vin-recall.html

United States: 1 NHTSA record for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $11,975[5], $5,922 under the median of $17,897[4].

Lowest ask	$11,975
Middle half	$15,248 – $19,942
Median ask	$17,897
This car	$11,975

Same configuration · 14 live listings · as of 27 Oct 2026

OTHER 2018 INFINITI QX60 LISTINGS [5]

Mcmasterville, QC · 165,489 km	$11,995
Sherbrooke, QC · 136,784 km	$14,988
London, ON · 109,907 km	$16,888
Calgary, AB · 145,516 km	$18,799
Calgary, AB · 124,540 km	$19,799
New Westminster, BC · 165,326 km	$16,995

§4 EVENTS

2018	Model year 2018[1] Assembly plant Smyrna, Tennessee, United States
11 Nov 2019	Transport Canada recall 2019567[2] Issued for the model year · Brakes
25 Oct 2026	Listed for sale, Sherbrooke, QC[5] Sherbrooke Honda · asking $11,975
26 Oct 2026	Listing last updated[5] asking $11,975

§5 DOCUMENTS

Window sticker — We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 14 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.