Register entry, as of 27 October 2026 Listed for sale Record ID 64b9ed8443ea

# 2017 Nissan Pathfinder

3.5 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 5N1 | DR2MM | 0 | H | C | 633409 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Nissan North America, Inc. | Pathfinder · 3.5 L | Verified | 2017 | Smyrna | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2017 | Engine | 3.5 L, 6 cylinders |
| Make | Nissan | Fuel | Gasoline |
| Model | Pathfinder | Drive | 4WD |
| Trim | Not in the decode | Maker | NISSAN NORTH AMERICA, INC. |
| Body | Sport Utility Vehicle | Plant | Smyrna, Tennessee, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/nissan/pathfinder/2017

**2** recalls listed by Transport Canada for this model year

### Brakes

2019567 11 Nov 2019

Issue: On certain vehicles, the antilock brake system (ABS) actuator pump may leak brake fluid and malfunction. This would cause the ABS warning lamp to turn on. If this problem is not fixed, damage to the ABS actuator could result in a short circuit. Note: This is a replacement and expansion of Transport Canada recall 2018-486. All vehicles that did not have the ABS actuator pump replaced under that recall require this repair. Safety Risk: A short circuit could increase the risk of a fire, even while parked. Corrective Actions: The company will notify owners by mail with an interim notice. A final repair is not yet available. If the ABS warning light stays on for 10 seconds or longer, you should park your vehicle outdoors away from other vehicles or structures. You should also call Nissan or Infiniti Roadside assistance to have your vehicle towed to a dealer for repair. A second notice will be sent to you once the final repair parts are available. This letter will advise you to take their vehicle to a dealer to replace the ABS actuator.

### Brakes

2018486 10 Sep 2018

On certain vehicles, the antilock brake system (ABS) actuator pump may leak brake fluid onto an electronic circuit board, causing it to malfunction. This would cause the illumination of the ABS warning lamp on the instrument panel. If the vehicle continues to be operated, damage to the ABS module could lead to a fire, creating a risk of injury and/or damage to property. Correction: Dealers will inspect and replace the ABS actuator as necessary. Note: This replaces recall 2016-424. Vehicles repaired under that campaign require a second repair under this campaign.

> Listed for the model year, not checked against your VIN. Nissan confirms which apply.
> Check your VIN with Nissan Canada or call a Nissan dealer with your VIN.
> www.nissan.ca/service/vin-recall.html

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $7,950[5], $5,942 under the median of $13,892[4].

| | |
|---|---|
| Lowest ask | $7,950 |
| Middle half | $11,521 – $14,995 |
| Median ask | $13,892 |
| This car | $7,950 |

Same configuration · 24 live listings · as of 27 Oct 2026

### OTHER 2017 NISSAN PATHFINDER LISTINGS [5]

| | |
|---|---|
| Orangeville, ON · 144,966 km | $7,992 |
| Orangeville, ON · 144,966 km | $7,992 |
| Orangeville, ON · 144,966 km | $7,992 |
| London, ON · 166,500 km | $15,888 |
| Moncton, NB · 159,711 km | $14,694 |
| Maple Ridge, BC · 121,510 km | $15,750 |

## §4 EVENTS

| | |
|---|---|
| 2017 | Model year 2017[1]<br>Assembly plant Smyrna, Tennessee, United States |
| 10 Sep 2018 | Transport Canada recall 2018486[2]<br>Issued for the model year · Brakes |
| 11 Nov 2019 | Transport Canada recall 2019567[2]<br>Issued for the model year · Brakes |
| 16 Sep 2026 | Listed for sale, Charlesbourg, QC[5]<br>Automobiles Desjardins · asking $7,950 |
| 27 Oct 2026 | Listing last updated[5]<br>asking $7,950 |

## §5 DOCUMENTS

Window sticker — We have not collected this label yet.

### SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 24 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.