

Register entry, as of 28 October 2026

Listed for sale

Record ID b64fff5e9adc

2018 Nissan Pathfinder

3.5 L, 6 cylinders · 4WD · Crossover Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5N1 DR2MM 8 J C 639626

WMI 1-3

Nissan North America, Inc.

DESCRIPTOR 4-8

Pathfinder · 3.5 L

CHECK 9

Verified

YEAR 10

2018

PLANT 11

Smyrna

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	3.5 L, 6 cylinders
Make	Nissan	Fuel	Gasoline
Model	Pathfinder	Drive	4WD
Trim	Not in the decode	Maker	NISSAN NORTH AMERICA, INC.
Body	Crossover Utility Vehicle	Plant	Smyrna, Tennessee, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/nissan/pathfinder/2018

3 recalls listed by Transport Canada for this model year

Brakes

2019567 11 Nov 2019

Issue: On certain vehicles, the antilock brake system (ABS) actuator pump may leak brake fluid and malfunction. This would cause the ABS warning lamp to turn on. If this problem is not fixed, damage to the ABS actuator could result in a short circuit. Note: This is a replacement and expansion of Transport Canada recall 2018-486. All vehicles that did not have the ABS actuator pump replaced under that recall require this repair. Safety Risk: A short circuit could increase the risk of a fire, even while parked. Corrective Actions: The company will notify owners by mail with an interim notice. A final repair is not yet available. If the ABS warning light stays on for 10 seconds or longer, you should park your vehicle outdoors away from other vehicles or structures. You should also call Nissan or Infiniti Roadside assistance to have your vehicle towed to a dealer for repair. A second notice will be sent to you once the final repair parts are available. This letter will advise you to take their vehicle to a dealer to replace the ABS actuator.

Visual system

2019459 13 Sep 2019

Issue: On certain vehicles, the rear view camera system does not return to the default setting when the transmission is shifted to reverse. This could cause a reduction in rear visibility if a driver had previously adjusted the camera display. Canadian regulations require that the rear view image returns to its original setting each time the camera is turned on. Safety Risk: Reduced rear visibility could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to update the software for the rear view camera.

Brakes

2018486 10 Sep 2018

On certain vehicles, the antilock brake system (ABS) actuator pump may leak brake fluid onto an electronic circuit board, causing it to malfunction. This would cause the illumination of the ABS warning lamp on the instrument panel. If the vehicle continues to be operated, damage to the ABS module could lead to a fire, creating a risk of injury and/or damage to property. Correction: Dealers will inspect and replace the ABS actuator as necessary. Note: This replaces recall 2016-424. Vehicles repaired under that campaign require a second repair under this campaign.



Listed for the model year, not checked against your VIN. Nissan confirms which apply.
Check your VIN with Nissan Canada or call a Nissan dealer with your VIN.
www.nissan.ca/service/vin-recall.html

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$13,995^[5], \$938 under the median of \$14,933^[4].



Lowest ask	\$6,800
Middle half	\$12,900 – \$15,699
Median ask	\$14,933
This car	\$13,995

Same configuration · 37 live listings · as of 28 Oct 2026

OTHER 2018 NISSAN PATHFINDER LISTINGS ^[5]

Calgary, AB · 194,053 km	\$14,990
Stouffville, ON · 207,055 km	\$6,800
Saint-Félicien, QC · 102,021 km	\$16,980
Baie-Comeau, QC · 102,021 km	\$16,980
Edmonton, AB · 120,697 km	\$17,922
St-Félicien, QC · 102,021 km	\$16,980

§4 EVENTS

2018	Model year 2018 ^[1] Assembly plant Smyrna, Tennessee, United States
10 Sep 2018	Transport Canada recall 2018486 ^[2] Issued for the model year · Brakes
13 Sep 2019	Transport Canada recall 2019459 ^[2] Issued for the model year · Visual system
11 Nov 2019	Transport Canada recall 2019567 ^[2] Issued for the model year · Brakes
24 Oct 2026	Listed for sale, Calgary, AB ^[5] Bowcity Motors · asking \$13,995

§5 DOCUMENTS

Window sticker We have not collected this label yet.



SOURCES

- [1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year
- [4] Cardog market quote, same configuration, 37 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

