Register entry, as of 29 October 2026 Listed for sale Record ID 8715ae7f09ed

2024 Hyundai Santa Fe Calligraphy

2.5 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5NM	P5DGL	0	R	H	011620
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Hyundai Motor Manufactur…	Santa Fe · 2.5 L	Verified	2024	Montgomery	Build sequence

§1 IDENTITY [1]

Model year	2024	Engine	2.5 L, 4 cylinders
Make	Hyundai	Fuel	Gasoline
Model	Santa Fe	Drive	4WD
Trim	Calligraphy	Maker	HYUNDAI MOTOR MANUFACTURING ALABAMA LLC (HMMA)
Body	Sport Utility Vehicle	Plant	Montgomery, Alabama, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/santa-fe/2024

7 recalls listed by Transport Canada for this model year

Seats and restraints

2026170 6 Apr 2026

Issue: On certain vehicles, the lower anchor for the front seat belt(s) may have been damaged during service. As a result, the seat belt(s) could detach in a crash. Note: For the 2026 model year Santa Fe, this recall only affects the Santa Fe hybrid (HEV) model. Safety Risk: A seat belt that detaches in a crash could increase the risk of injury. Corrective Actions: The company will notify owners in writing and advise you to take your vehicle to a dealership to inspect and reinforce the lower seat belt anchors. The seat belt assemblies will be replaced, as necessary.

Electrical

2025529 2 Oct 2025

Issue: On certain vehicles, the starter motor's terminal cover may not have been installed properly. As a result, the positive terminal could be exposed and contact nearby components in a crash. If this happens, there could be a short circuit. Safety Risk: A short circuit could create the risk of a fire and/or injury. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, reinstall the starter motor positive terminal cover.

Other

2024683 7 Nov 2024

Issue: On certain vehicles, the sunshade switch in the overhead console may not have been designed properly. As a result, the switch may not meet certain requirements of Canadian regulations that exist to reduce the risk of activating the sunshade unintentionally. Note: This recall affects both Santa Fe and Santa Fe Hybrid models. Safety Risk: A sunshade that closes unexpectedly could pinch a person and create a risk of injury. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to replace the sunshade switch knobs in the overhead console.

Label

2024552 23 Sep 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the compliance label for all new vehicles.

Airbag

2024430 25 Jul 2024

Issue: On certain vehicles, the floor wiring harness may not have been secured properly and could become damaged. As a result, the airbags may not deploy in a crash and/or the airbags could deploy without a crash. Note: This problem would cause the airbag warning light to turn on. This recall affects both the Santa Fe and Santa Fe hybrid models. Safety Risk: An airbag that doesn't work properly could increase the risk of injury in a crash. Additionally, an airbag that deploys without a crash could create a risk of injury. Corrective Actions: Hyundai will notify owners in writing and advise you to take your vehicle to a dealership to inspect and, if necessary, secure the floor wiring harness. If damage is found, the wiring harness will be replaced.

Powertrain

2024404 11 Jul 2024

Issue: On certain vehicles, a software problem could cause the transmission to become damaged. As a result, the vehicle could move when it's parked and the parking brake isn't applied. Safety Risk: A parked vehicle that moves suddenly could create the risk of an injury or a crash. Corrective Actions: Hyundai will notify owners in writing and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the transmission. The dealer will also update the transmission control unit software. To reduce the safety risk, Hyundai recommends that you should always use the parking brake when you park.

1 more on the model-year record, cardog.app/tools/recalls/hyundai/santa-fe/2024

> Listed for the model year, not checked against your VIN. Hyundai confirms which apply.
> Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.
> www.hyundaicanada.com/en/owners-section/recalls

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $41,298[5], $698 under the median of $41,996[4].



Lowest ask	$35,889
Middle half	$39,999 – $44,220
Median ask	$41,996
This car	$41,298

Same configuration · 39 live listings · as of 29 Oct 2026

OTHER 2024 HYUNDAI SANTA FE LISTINGS [5]

Mississauga, ON · 65,909 km	$40,999
Victoria, BC · 25,224 km	$45,604
Victoria, BC · 34,539 km	$39,404
Matane, QC · 52,090 km	$42,000
Brantford, ON · 58,608 km	$39,998
Winnipeg, MB · 32,726 km	$45,991

§4 EVENTS

2024	Model year 2024[1] Assembly plant Montgomery, Alabama, United States
2 Apr 2024	Transport Canada recall 2024206[2] Issued for the model year · Visual system
11 Jul 2024	Transport Canada recall 2024404[2] Issued for the model year · Powertrain
25 Jul 2024	Transport Canada recall 2024430[2] Issued for the model year · Airbag
23 Sep 2024	Transport Canada recall 2024552[2] Issued for the model year · Label
7 Nov 2024	Transport Canada recall 2024683[2] Issued for the model year · Other
2 Oct 2025	Transport Canada recall 2025529[2] Issued for the model year · Electrical
6 Apr 2026	Transport Canada recall 2026170[2] Issued for the model year · Seats and restraints
26 Oct 2026	Listed for sale, Maple, ON[5] Maple Hyundai · asking $41,298

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 39 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.