Register entry, as of 29 October 2026 Listed for sale Record ID 4f8e657198bb

# 2025 Hyundai Santa Fe Calligraphy

2.5 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 5NM | P5DGL | 3 | S | H | 138531 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Hyundai Motor Manufactur… | Santa Fe · 2.5 L | Verified | 2025 | Montgomery | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2025 | Engine | 2.5 L, 4 cylinders |
| Make | Hyundai | Fuel | Gasoline |
| Model | Santa Fe | Drive | 4WD |
| Trim | Calligraphy | Maker | HYUNDAI MOTOR MANUFACTURING ALABAMA LLC (HMMA) |
| Body | Sport Utility Vehicle | Plant | Montgomery, Alabama, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/santa-fe/2025

**3** recalls listed by Transport Canada for this model year

### Seats and restraints

2026170 6 Apr 2026

Issue: On certain vehicles, the lower anchor for the front seat belt(s) may have been damaged during service. As a result, the seat belt(s) could detach in a crash. Note: For the 2026 model year Santa Fe, this recall only affects the Santa Fe hybrid (HEV) model. Safety Risk: A seat belt that detaches in a crash could increase the risk of injury. Corrective Actions: The company will notify owners in writing and advise you to take your vehicle to a dealership to inspect and reinforce the lower seat belt anchors. The seat belt assemblies will be replaced, as necessary.

### Visual system

2025648 20 Nov 2025

Issue: On certain vehicles, the wiring harness for the rearview camera may not have been manufactured properly. As a result, the wiring could become damaged and cause the rearview camera image not to display when the transmission is shifted into reverse. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Hyundai will notify owners in writing and advise you to take your vehicle to a dealership to replace the camera wiring harness.

### Electrical

2025529 2 Oct 2025

Issue: On certain vehicles, the starter motor's terminal cover may not have been installed properly. As a result, the positive terminal could be exposed and contact nearby components in a crash. If this happens, there could be a short circuit. Safety Risk: A short circuit could create the risk of a fire and/or injury. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, reinstall the starter motor positive terminal cover.

> Listed for the model year, not checked against your VIN. Hyundai confirms which apply.
> Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.
> www.hyundaicanada.com/en/owners-section/recalls

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $59,644[5], $11,744 over the median of $47,900[4].

| | |
|---|---|
| Lowest ask | $39,950 |
| Middle half | $46,574 – $57,099 |
| Median ask | $47,900 |
| This car | $59,644 |

Same configuration · 49 live listings · as of 29 Oct 2026

### OTHER 2025 HYUNDAI SANTA FE LISTINGS [5]

| | |
|---|---|
| Victoria, BC · 38,217 km | $43,019 |
| Victoria, BC · 31,256 km | $41,904 |
| Victoria, BC · 35,157 km | $41,258 |
| Boischatel, QC · 28,994 km | $39,800 |
| Orangeville, ON · 22,732 km | $47,510 |
| Edmonton, AB · 30,869 km | $46,209 |

## §4 EVENTS

| | |
|---|---|
| 2025 | Model year 2025[1]<br>Assembly plant Montgomery, Alabama, United States |
| 2 Oct 2025 | Transport Canada recall 2025529[2]<br>Issued for the model year · Electrical |
| 25 Oct 2025 | Listed for sale, Calgary, AB[5]<br>Hyundai Gallery · asking $59,644 |
| 20 Nov 2025 | Transport Canada recall 2025648[2]<br>Issued for the model year · Visual system |
| 6 Apr 2026 | Transport Canada recall 2026170[2]<br>Issued for the model year · Seats and restraints |
| 29 Oct 2026 | Listing last updated[5]<br>asking $59,644 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

## SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 49 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.