Register entry, as of 29 October 2026 Listed for sale Record ID 45166409eef4

2021 Hyundai Santa Fe SEL w/ Premium Pkg

2.5 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5NM	S3DAJ	9	M	H	327582
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Hyundai Motor Manufactur…	Santa Fe · 2.5 L	Verified	2021	Montgomery	Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	2.5 L, 4 cylinders
Make	Hyundai	Fuel	Gasoline
Model	Santa Fe	Drive	4WD
Trim	SEL w/ Premium Pkg	Maker	HYUNDAI MOTOR MANUFACTURING ALABAMA LLC (HMMA)
Body	Sport Utility Vehicle	Plant	Montgomery, Alabama, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/santa-fe/2021

10 recalls listed by Transport Canada for this model year

Other

2025636 17 Nov 2025

Issue : Hyundai Auto Canada is conducting an extended warranty campaign for certain vehicles as water could enter the horn assembly and cause the horn's electrical contacts to corrode. As a result, the horn may not work properly or at all. Safety risk: A horn that doesn't work properly could prevent a driver from warning others of a danger and create an unsafe situation. Corrective Actions: To reduce the safety risk, Hyundai advises you to test the horn regularly. Hyundai will notify owners in writing and advise you to contact a dealership if your horn doesn't work properly. Hyundai will provide an extended warranty of 10 years/200 000 km to replace the horn for free if it fails.

Visual system

2024709 20 Nov 2024

Issue: On certain vehicles, the rearview camera may not have been manufactured properly. Over time, the camera could fail and cause the rearview camera image not to display. Canadian regulations require the rearview image to display when the vehicle is reversing. Note: For the Santa Fe model, this recall affects both Santa Fe and Santa Fe Hybrid models. For the Elantra model, this recall affects both Elantra and Elantra Hybrid models. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Hyundai will notify owners in writing and advise you to take your vehicle to a dealership to replace the rearview camera.

Label

2024552 23 Sep 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the compliance label for all new vehicles.

Electrical

2023147 17 Mar 2023

Issue: Certain vehicles may be equipped with a 4-pin accessory trailer wiring harness kit that could fail. Over time, this could result in a short circuit that can cause the control module to overheat. Note: This recall only affects Hyundai Genuine 4-pin tow hitch wiring harness kits with the part number S2F67-AC401. These kits may have been ordered at the time of a vehicle purchase or purchased separately from a dealer as an aftermarket accessory. Safety Risk: A short circuit can create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Hyundai will notify owners by mail and instruct you to bring your vehicle to a dealership to inspect the vehicle for a trailer wiring harness kit. If necessary, the dealer will install a 15A fuse and a wire extension kit. Hyundai advises that if your vehicle has a tow hitch harness installed, you should park it outdoors, and away from other vehicles or structures until the recall repairs have been completed.

Electrical

2022727 16 Dec 2022

Issue: Certain vehicles may have a programming error. As a result, the vehicles don't meet some of the anti-theft requirements in Canadian regulations. Safety Risk: A vehicle theft could create a safety risk. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealership to update the vehicle software.

Seats and restraints

2022623 31 Oct 2022

Issue: On certain vehicles, there may be a problem with the driver and front passenger seat belt pretensioners. As a result, the seat belt pretensioners could explode in a crash. If this happens, small pieces of metal could hit people in the vehicle. Note: This recall only affects Santa Fe Hybrid (HEV) and Santa Fe Plug-In Hybrid (PHEV) models. Safety Risk: A seat belt pretensioner that explodes could create a risk of injury. Corrective Actions: Hyundai will notify owners by mail and instruct you to bring your vehicle to a dealership to install protective caps over the driver and front passenger's seat belt pretensioners.

4 more on the model-year record, cardog.app/tools/recalls/hyundai/santa-fe/2021

> Listed for the model year, not checked against your VIN. Hyundai confirms which apply.
> Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.
> www.hyundaicanada.com/en/owners-section/recalls

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $18,999[5], $1,982 under the median of $20,981[4].



Lowest ask	$16,095
Middle half	$18,999 – $22,988
Median ask	$20,981
This car	$18,999

Same configuration · 35 live listings · as of 29 Oct 2026

OTHER 2021 HYUNDAI SANTA FE LISTINGS [5]

Victoria, BC · 125,988 km	$29,627
Victoria, BC · 87,774 km	$26,908
Victoria, BC · 70,899 km	$26,404
Carignan, QC · 80,160 km	$21,998
Blainville, QC · 140,153 km	$19,987
Blainville, QC · 78,549 km	$22,987

§4 EVENTS

2021	Model year 2021[1] Assembly plant Montgomery, Alabama, United States
15 Feb 2021	Transport Canada recall 2021065[2] Issued for the model year · Fuel system
9 Jul 2021	Transport Canada recall 2021426[2] Issued for the model year · Fuel system
27 Dec 2021	Transport Canada recall 2021791[2] Issued for the model year · Structure
6 Oct 2022	Transport Canada recall 2022568[2] Issued for the model year · Powertrain
31 Oct 2022	Transport Canada recall 2022623[2] Issued for the model year · Seats and restraints
16 Dec 2022	Transport Canada recall 2022727[2] Issued for the model year · Electrical
17 Mar 2023	Transport Canada recall 2023147[2] Issued for the model year · Electrical
23 Sep 2024	Transport Canada recall 2024552[2] Issued for the model year · Label
20 Nov 2024	Transport Canada recall 2024709[2] Issued for the model year · Visual system
17 Nov 2025	Transport Canada recall 2025636[2] Issued for the model year · Other
25 Oct 2026	Listed for sale, Kitchener, ON[5] Auto Expo Inc. · asking $18,999
27 Oct 2026	Listing last updated[5] asking $18,999

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 35 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.