Register entry, as of 27 November 2026 Listed for sale Record ID 0c9cd0dd2768

2011 Hyundai Elantra GLS (Middle grade)

1.8 L, 4 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5NP	DH4AE	1	B	H	053081
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Hyundai-Kia America Tech…	Elantra · 1.8 L	Verified	2011	Alabama	Build sequence

§1 IDENTITY [1]

Model year	2011	Engine	1.8 L, 4 cylinders
Make	Hyundai	Fuel	Gasoline
Model	Elantra	Drive	Not in the decode
Trim	GLS (Middle grade)	Maker	HYUNDAI-KIA AMERICA TECHNICAL CENTER INC (HATCI)
Body	Sedan	Plant	Alabama, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/elantra/2011

7 recalls listed by Transport Canada for this model year

Brakes 2024080 8 Feb 2024

Issue: On certain vehicles, brake fluid could leak into the control module for the antilock brake system (ABS) and cause it to short circuit. Note: This recall replaces recall R0246 (Transport Canada recall number 2023-527). For the Sonata model, only the Sonata Hybrid model is affected by this recall. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuse for the ABS module. Hyundai recommends that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.

Brakes 2023527 22 Sep 2023

This recall was replaced by Transport Canada Recall No. 2024-080. Issue: On certain vehicles, brake fluid could leak into the control module for the antilock brake system (ABS) and cause it to short circuit. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuse for the ABS module. Hyundai recommends that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.

Brakes 2023125 8 Mar 2023

Issue: Hyundai is conducting a special service campaign that provides anti-corrosion treatment to certain underbody components. Over time, components under the vehicle, including brake lines could corrode. If this happens, a brake line could fail and leak. A brake fluid leak can result in reduced braking. Safety Risk: Reduced braking can cause an extended stopping distance and increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to inspect the underbody, including the brake lines. The dealer will apply an anti-corrosion treatment to certain parts, and replace the brake lines if necessary.

Other

2019420 21 Aug 2019

Issue: This recall is for aftermarket replacement rear window glass produced by Vitro Automotriz. Certain rear window glass may not have been properly tempered. If the window breaks, the glass may separate into large pieces instead of very small ones. Note: This is a voluntary recall that is not being conducted under the requirements of the Motor Vehicle Safety Act. Safety Risk: Glass that breaks in to large pieces could create a risk of injury. Corrective Actions: The company will notify consumers by mail and instruct them to inspect the designation code marked on the rear window glass. Products affected by this recall have the designation “DOT 287” along with the lettering “VMR” (Replacement Market) and a date code that is before July 2019. This information is printed on the bottom corner of the glass. Consumers should contact Vitro's customer service at 1-412-995-6457 or argbacklites@vitro.com to arrange for replacement of the glass.

Suspension

2016310 16 Jun 2016

On certain vehicles, the front suspension coil springs may be susceptible to corrosion. Over time, corrosion could cause the springs to fail, potentially damaging front tires and causing rapid air loss and/or tire failure, which could increase the risk of a crash causing injury and/or property damage. Correction: Dealers will inspect and repair or replace coil springs as necessary. Note: This recall supersedes recall 2015-469. Vehicles repaired under the previous recall will require re-inspection and repair.

Brakes

2015623 31 Dec 2015

On certain sedan models, a defect in the electronic stability control (ESC) yaw sensor could cause cause the ESC light in the instrument panel to illuminate as well as cause unwarranted activation of the stability control system. This could result in reduced engine power and brake application on one or more wheels, which could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will verify proper operation of the yaw sensor and update vehicle software.

1 more on the model-year record, cardog.app/tools/recalls/hyundai/elantra/2011

> Listed for the model year, not checked against your VIN. Hyundai confirms which apply.
> Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.
> www.hyundaicanada.com/en/owners-section/recalls

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $1,500[5], $3,499 under the median of $4,999[4].



Lowest ask	$1,500
Middle half	$3,499 – $6,494
Median ask	$4,999
This car	$1,500

Same model year · 13 live listings · as of 27 Nov 2026

OTHER 2011 HYUNDAI ELANTRA LISTINGS [5]

London, ON · 187,148 km	$5,495
Brampton, ON · 142,899 km	$1,995
Cochrane, AB · 416,071 km	$3,888
Yarmouth, NS · 278,911 km	$1,995
Scarborough, ON · 183,000 km	$4,999
Laval, QC · 148,000 km	$3,499

§4 EVENTS

2011	Model year 2011[1] Assembly plant Alabama, United States
15 Oct 2015	Transport Canada recall 2015469[2] Issued for the model year · Suspension
31 Dec 2015	Transport Canada recall 2015623[2] Issued for the model year · Brakes
16 Jun 2016	Transport Canada recall 2016310[2] Issued for the model year · Suspension
21 Aug 2019	Transport Canada recall 2019420[2] Issued for the model year · Other
8 Mar 2023	Transport Canada recall 2023125[2] Issued for the model year · Brakes
22 Sep 2023	Transport Canada recall 2023527[2] Issued for the model year · Brakes
8 Feb 2024	Transport Canada recall 2024080[2] Issued for the model year · Brakes
22 Nov 2026	Listed for sale, Kelowna, BC[5] Buy Direct Truck Centre · asking $1,500
26 Nov 2026	Listing last updated[5] asking $1,500

§5 DOCUMENTS

Window sticker	We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 13 live listings, as of 27 Nov 2026

[5] Live public dealer listings on Cardog, as of 27 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.