Register entry, as of 29 October 2026 Listed for sale Record ID 61d33c399fef

2013 Hyundai Elantra GLS/GLS Preferred/ Limited/Limited Tech GS/SE/SE Tech

1.8 L, 4 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5NP	DH4AE	9	D	H	360730
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Hyundai-Kia America Tech…	Elantra · 1.8 L	Verified	2013	Alabama	Build sequence

§1 IDENTITY [1]

Model year	2013	Engine	1.8 L, 4 cylinders
Make	Hyundai	Fuel	Gasoline
Model	Elantra	Drive	Not in the decode
Trim	GLS/GLS Preferred/ Limited/Limited Tech GS/SE/SE Tech	Maker	HYUNDAI-KIA AMERICA TECHNICAL CENTER INC (HATCI)
Body	Sedan	Plant	Alabama, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/elantra/2013

5 recalls listed by Transport Canada for this model year

Brakes

2024080 8 Feb 2024

Issue: On certain vehicles, brake fluid could leak into the control module for the antilock brake system (ABS) and cause it to short circuit. Note: This recall replaces recall R0246 (Transport Canada recall number 2023-527). For the Sonata model, only the Sonata Hybrid model is affected by this recall. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuse for the ABS module. Hyundai recommends that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.

Brakes

2023527 22 Sep 2023

This recall was replaced by Transport Canada Recall No. 2024-080. Issue: On certain vehicles, brake fluid could leak into the control module for the antilock brake system (ABS) and cause it to short circuit. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuse for the ABS module. Hyundai recommends that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.

Brakes

2023125 8 Mar 2023

Issue: Hyundai is conducting a special service campaign that provides anti-corrosion treatment to certain underbody components. Over time, components under the vehicle, including brake lines could corrode. If this happens, a brake line could fail and leak. A brake fluid leak can result in reduced braking. Safety Risk: Reduced braking can cause an extended stopping distance and increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to inspect the underbody, including the brake lines. The dealer will apply an anti-corrosion treatment to certain parts, and replace the brake lines if necessary.

Other

2019420 21 Aug 2019

Issue: This recall is for aftermarket replacement rear window glass produced by Vitro Automotriz. Certain rear window glass may not have been properly tempered. If the window breaks, the glass may separate into large pieces instead of very small ones. Note: This is a voluntary recall that is not being conducted under the requirements of the Motor Vehicle Safety Act. Safety Risk: Glass that breaks in to large pieces could create a risk of injury. Corrective Actions: The company will notify consumers by mail and instruct them to inspect the designation code marked on the rear window glass. Products affected by this recall have the designation “DOT 287” along with the lettering “VMR” (Replacement Market) and a date code that is before July 2019. This information is printed on the bottom corner of the glass. Consumers should contact Vitro's customer service at 1-412-995-6457 or argbacklites@vitro.com to arrange for replacement of the glass.

Brakes

2017614 8 Dec 2017

On certain vehicles, the brake pedal stopper pad material could deteriorate over time and allow the stop lamp switch plunger to remain extended when the brake pedal is released. This could result in the stop lamps illuminating continuously, which would result in following road users being unaware of the driver's intentions. Additionally, it could result in activation of the engine management system's brake pedal override feature, the illumination of the traction control warning lamp, and/or the ability to move the shift lever without depressing the brake pedal, which could result in unintended vehicle movement. These conditions could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the brake pedal stopper pad.

> Listed for the model year, not checked against your VIN. Hyundai confirms which apply.
> Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.
> www.hyundaicanada.com/en/owners-section/recalls

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $6,995[5], $5 over the median of $6,990[4].

Lowest ask	$2,495
Middle half	$4,999 – $7,998
Median ask	$6,990
This car	$6,995

Same configuration · 55 live listings · as of 28 Oct 2026

OTHER 2013 HYUNDAI ELANTRA LISTINGS [5]

Longueuil, QC · 119,435 km	$7,955
Sherbrooke, QC · 94,925 km	$4,988
Ingersoll, ON · 218,311 km	$1,870
St-Basile-Le-Grand, QC · 237,011 km	$4,990
St-Hubert, QC · 205,337 km	$3,977
Québec, QC · 86,498 km	$6,950

§4 EVENTS

2013	Model year 2013[1] Assembly plant Alabama, United States
8 Dec 2017	Transport Canada recall 2017614[2] Issued for the model year · Brakes
21 Aug 2019	Transport Canada recall 2019420[2] Issued for the model year · Other
8 Mar 2023	Transport Canada recall 2023125[2] Issued for the model year · Brakes
22 Sep 2023	Transport Canada recall 2023527[2] Issued for the model year · Brakes
8 Feb 2024	Transport Canada recall 2024080[2] Issued for the model year · Brakes
25 Oct 2026	Listed for sale, London, ON[5] Tiger Auto Sales Ltd. · asking $6,995
28 Oct 2026	Listing last updated[5] asking $6,995

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 55 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.