Register entry, as of 28 October 2026 Listed for sale Record ID 9bdeb09a5853

2015 Hyundai Sonata SE, ECO

2.4 L, 4 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5NP	E24AF	8	F	H	201506
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Hyundai-Kia America Tech…	Sonata · 2.4 L	Verified	2015	Alabama	Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	2.4 L, 4 cylinders
Make	Hyundai	Fuel	Gasoline
Model	Sonata	Drive	Not in the decode
Trim	SE, ECO	Maker	HYUNDAI-KIA AMERICA TECHNICAL CENTER INC (HATCI)
Body	Sedan	Plant	Alabama, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/sonata/2015

15 recalls listed by Transport Canada for this model year

Brakes

2024080 8 Feb 2024

Issue: On certain vehicles, brake fluid could leak into the control module for the antilock brake system (ABS) and cause it to short circuit. Note: This recall replaces recall R0246 (Transport Canada recall number 2023-527). For the Sonata model, only the Sonata Hybrid model is affected by this recall. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuse for the ABS module. Hyundai recommends that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.

Electrical

2023104 1 Mar 2023

Issue: Hyundai is conducting a special service campaign to upgrade the safety plug fuse. On certain Sonata Hybrid (HEV) models, the safety plug fuse in the power relay assembly could blow and cause a sudden loss of hybrid system power. Safety Risk: A loss of hybrid system power may increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealership to replace the 125-A safety plug with one that has a 150-A rating.

Engine

2021612 1 Oct 2021

Issue: Hyundai Auto Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure would cause a sudden loss of power with an inability to restart. Note: This only affects vehicles equipped with a 2.4 L MPI engine. For the Sonata model, only the Sonata Hybrid is affected by this campaign. All vehicles previously included in TC # 2021-033 are now part of this new campaign. Vehicles that were previously repaired under campaign R0181 (Transport Canada #2021-033) do not require this software update. Safety Risk: A sudden loss of engine power could increase the risk of an accident. An engine failure could also create the risk of a fire. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to update the software for the engine control module. Note: Hyundai recommends that you should always follow the correct vehicle maintenance schedule, which is printed in the Owner's Manual. If you experience unusual engine noise, reduced power, or a check engine/oil warning light, Hyundai advises you to immediately visit a Hyundai dealership to have your vehicle diagnosed.

Lights and instruments

2021589 24 Sep 2021

Issue: On certain vehicles, an intermittent problem could cause the turn signals to activate in the opposite direction from what a driver intends. For example, when the driver uses the right turn signal, the left signal could turn on. Note: For 2016 and 2017 models, the Sonata Hybrid and Sonata Plug-In Hybrid (PHEV) models are also affected by this recall. Safety Risk: Turn signals that do not work properly may cause confusion and could increase the risk of a crash. Corrective Action: Hyundai will notify owners by mail and instruct you to bring your vehicle to a dealer to update the Smart Junction Box software.

Engine

2019640 16 Dec 2019

Issue: Hyundai Auto Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure would cause a sudden loss of power with an inability to restart. Note: This affects Sonata and Santa Fe Sport equipped with a 2.4 L GDI or 2.0 L Turbo GDI engine, as well as Tucson equipped with a 2.4 L GDI engine. Safety Risk: A sudden loss of engine power could increase the risk of an accident. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to update the software for the engine control module. Note: Vehicles previously repaired under Product Improvement Campaign R0153 (TC # 2019-130) do not require this software update. Owners can find additional information at www.hyundaiengineinfo.ca.

Engine

2019130 11 Mar 2019

Issue: Hyundai Auto Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure would cause a sudden loss of power with an inability to restart. Note: This affects Sonata and Santa Fe Sport equipped with a 2.4 L GDI or 2.0 L Turbo GDI engine, as well as Tucson equipped with a 2.4 L GDI engine. Safety Risk: A sudden loss of engine power could increase the risk of an accident. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to update the software for the engine control module. Note: Vehicles repaired under Service Campaigns, C0336, C0344, or C0347, already have this software update. Owners can find additional information at www.hyundaiengineinfo.ca.

9 more on the model-year record, cardog.app/tools/recalls/hyundai/sonata/2015

> Listed for the model year, not checked against your VIN. Hyundai confirms which apply.
> Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.
> www.hyundaicanada.com/en/owners-section/recalls

United States: 12 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $6,999[5], $2,000 under the median of $8,999[4].



Lowest ask	$4,699
Middle half	$7,995 – $10,995
Median ask	$8,999
This car	$6,999

Same configuration · 17 live listings · as of 28 Oct 2026

OTHER 2015 HYUNDAI SONATA LISTINGS [5]

Sherwood Park, AB · 209,943 km	$4,980
Sherwood Park, AB · 209,943 km	$4,980
Moncton, NB · 147,921 km	$6,441
Whitby, ON · 243,151 km	$6,367
Sherbrooke, QC · 183,010 km	$9,795
Edmonton, AB · 209,943 km	$4,980

§4 EVENTS

2015	Model year 2015[1] Assembly plant Alabama, United States
27 Jun 2014	Transport Canada recall 2014259[2] Issued for the model year · Brakes
27 Jun 2014	Transport Canada recall 2014252[2] Issued for the model year · Electrical
6 Jul 2015	Transport Canada recall 2015302[2] Issued for the model year · Seats and restraints
29 Oct 2015	Transport Canada recall 2015516[2] Issued for the model year · Brakes
21 Apr 2016	Transport Canada recall 2016174[2] Issued for the model year · Airbag
17 Oct 2016	Transport Canada recall 2016507[2] Issued for the model year · Structure
15 Mar 2017	Transport Canada recall 2017146[2] Issued for the model year · Seats and restraints
28 Apr 2017	Transport Canada recall 2017235[2] Issued for the model year · Lights and instruments
10 Jan 2019	Transport Canada recall 2019012[2] Issued for the model year · Engine

11 Mar 2019	Transport Canada recall 2019130[2] Issued for the model year · Engine
16 Dec 2019	Transport Canada recall 2019640[2] Issued for the model year · Engine
24 Sep 2021	Transport Canada recall 2021589[2] Issued for the model year · Lights and instruments
1 Oct 2021	Transport Canada recall 2021612[2] Issued for the model year · Engine
1 Mar 2023	Transport Canada recall 2023104[2] Issued for the model year · Electrical
8 Feb 2024	Transport Canada recall 2024080[2] Issued for the model year · Brakes
5 Sep 2026	Listed for sale, Mississauga, ON[5] Streetsville Hyundai · asking $6,999
28 Oct 2026	Listing last updated[5] asking $6,999

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 17 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.