Register entry, as of 29 October 2026 Listed for sale Record ID 650679e91f0b

# 2024 Toyota Grand Highlander

2.4 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 5TD | AAAB5 | 6 | R | S | 030050 |
|---|---|---|---|---|---|
| WMI 1-3 | DESCRIPTOR 4-8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12-17 |
| Toyota Motor Manufacturi… | Grand Highlander · 2.4 L | Verified | 2024 | Princeton | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2024 | Engine | 2.4 L, 4 cylinders |
| Make | Toyota | Fuel | Gasoline |
| Model | Grand Highlander | Drive | 4WD |
| Trim | Not in the decode | Maker | TOYOTA MOTOR MANUFACTURING, INDIANA, INC. |
| Body | Sport Utility Vehicle | Plant | Princeton, Indiana, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/grand-highlander/2024

**3** recalls listed by Transport Canada for this model year

### Visual system

2025594 30 Oct 2025

Issue: Under certain conditions, a software problem could cause the rearview camera image to freeze or not to display. If this happens, the rearview image may not display when the transmission is shifted into reverse. Canadian regulations require the rearview image to display when the vehicle is reversing. Note: This recall only affects certain vehicles equipped with a panoramic view monitor system. Safety Risk: A rearview camera image that doesn't display correctly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: The company will notify owners in writing and advise you to take your vehicle to a dealership to update the parking assist ECU software.

### Visual system

2025469 11 Sep 2025

Issue: On certain vehicles, a software problem could cause the combination meter in the instrument panel not to display when the vehicle is started. As a result, you may not be able to see certain information about the vehicle, including the speedometer, fuel gauge, warning lights and malfunction tell-tales. Note: This recall only affects vehicles equipped with a 12.3-inch display. Safety Risk: Warnings, tell-tales and gauges that don't display could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to update the combination meter software. Alternatively, certain eligible vehicles will be sent a wireless over-the-air software update, which you can install yourself. For certain vehicles, the dealer will also inspect and, if necessary, replace the combination meter.

### Airbag

2024358 20 Jun 2024

Issue: On certain vehicles, the side curtain airbag(s) may not inflate properly in a crash if the driver's or front passenger's windows are rolled down. Note: For the Grand Highlander model, this recall affects both Grand Highlander and Grand Highlander Hybrid models. Safety Risk: A side curtain airbag that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace both side curtain airbag assemblies.

> Listed for the model year, not checked against your VIN. Toyota confirms which apply.
> Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
> www.toyota.ca/en/owners/recalls/

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $57,995[5], $8,010 over the median of $49,985[4].




| | |
|---|---|
| Lowest ask | $38,999 |
| Middle half | $46,900 – $53,999 |
| Median ask | $49,985 |
| This car | $57,995 |

Same configuration · 29 live listings · as of 28 Oct 2026

### OTHER 2024 TOYOTA GRAND HIGHLANDER LISTINGS [5]

| | |
|---|---|
| Port Hawkesbury, NS · 69,723 km | $47,990 |
| Port Hawkesbury, NS · 60,600 km | $47,990 |
| Vaughan, ON · 18,137 km | $58,288 |
| Newmarket, ON · 40,640 km | $53,999 |
| Wetaskiwin, AB · 49,418 km | $52,500 |
| Wetaskiwin, AB · 54,150 km | $51,990 |

## §4 EVENTS

| | |
|---|---|
| 2024 | Model year 2024[1]<br>Assembly plant Princeton, Indiana, United States |
| 20 Jun 2024 | Transport Canada recall 2024358[2]<br>Issued for the model year · Airbag |
| 11 Sep 2025 | Transport Canada recall 2025469[2]<br>Issued for the model year · Visual system |
| 30 Oct 2025 | Transport Canada recall 2025594[2]<br>Issued for the model year · Visual system |
| 26 Oct 2026 | Listed for sale, Owen Sound, ON[5]<br>Baywest Toyota · asking $57,995 |
| 28 Oct 2026 | Listing last updated[5]<br>asking $57,995 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

## SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 29 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.