

Register entry, as of 28 October 2026

Listed for sale

Record ID 4d62874ddc1a

# 2014 Toyota Highlander Base/Hybrid

3.5 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**5TD BCRFH 8 E S 004528**

WMI 1-3

Toyota Motor Manufacturi...

DESCRIPTOR 4-8

Highlander · 3.5 L

CHECK 9

Verified

YEAR 10

2014

PLANT 11

Princeton

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |                       |        |                                           |
|------------|-----------------------|--------|-------------------------------------------|
| Model year | 2014                  | Engine | 3.5 L, 6 cylinders                        |
| Make       | Toyota                | Fuel   | Gasoline                                  |
| Model      | Highlander            | Drive  | 4WD                                       |
| Trim       | Base/Hybrid           | Maker  | TOYOTA MOTOR MANUFACTURING, INDIANA, INC. |
| Body       | Sport Utility Vehicle | Plant  | Princeton, Indiana, United States         |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/toyota/highlander/2014](https://cardog.app/tools/recalls/toyota/highlander/2014)

## 4 recalls listed by Transport Canada for this model year

### Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

### Accessories

2019428 23 Aug 2019

Issue: On certain vehicles, the hook and loop material used to attach the carpet to its underpadding may not be flame resistant. As a result, when it is tested alone, the loop fasteners do not meet the requirements of Canadian regulations. Safety Risk: As the carpet is always assembled, and the loop fasteners are very small, this problem does not create a safety risk. Corrective Action: This is not a recall. The company has made production changes to ensure that all new vehicles meet the requirements of Canadian regulations.



**Fuel system**

2014409 18 Sep 2014

On certain vehicles, the end cap on the right-hand side fuel delivery pipe, located in the engine compartment, could have been improperly welded at time of manufacture. This could result in a fuel leak which, in the presence of an ignition source, could result in a fire causing injury and/or property damage. Correction: Dealers will inspect the fuel delivery pipe and replace with a revised part if necessary.

**Seats and restraints**

2014187 22 May 2014

Certain vehicles may not comply with the requirements of Canada Motor Vehicle Safety Standard (CMVSS) 208 – Occupant Protection. A defect in the programming of the occupant classification system could limit the seat belt loading to the front passenger seat occupant in a crash, which could result in non-compliance to the standard and increase the risk of injury. Correction: Dealers will reprogram the occupant classification module.

Listed for the model year, not checked against your VIN. Toyota confirms which apply.

Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.

[www.toyota.ca/en/owners/recalls/](http://www.toyota.ca/en/owners/recalls/)

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

**§3 VALUE** <sup>[4]</sup>

This car asks \$18,995<sup>[5]</sup>, \$303 over the median of \$18,692<sup>[4]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$13,950            |
| Middle half | \$18,086 – \$19,709 |
| Median ask  | \$18,692            |
| This car    | \$18,995            |

Same model year · 10 live listings · as of 28 Oct 2026

**OTHER 2014 TOYOTA HIGHLANDER LISTINGS** <sup>[5]</sup>

|                                |          |
|--------------------------------|----------|
| Cranbrook, BC · 213,595 km     | \$19,947 |
| Cranbrook, BC · 213,595 km     | \$19,947 |
| Victoriaville, QC · 234,000 km | \$18,495 |
| Toronto, ON · 139,891 km       | \$22,988 |
| Richmond, BC · 256,413 km      | \$16,995 |
| Mississauga, ON · 150,742 km   | \$19,995 |

**§4 EVENTS**

|             |                                                                                                    |
|-------------|----------------------------------------------------------------------------------------------------|
| 2014        | Model year 2014 <sup>[1]</sup><br>Assembly plant Princeton, Indiana, United States                 |
| 22 May 2014 | Transport Canada recall 2014187 <sup>[2]</sup><br>Issued for the model year · Seats and restraints |
| 18 Sep 2014 | Transport Canada recall 2014409 <sup>[2]</sup><br>Issued for the model year · Fuel system          |
| 23 Aug 2019 | Transport Canada recall 2019428 <sup>[2]</sup><br>Issued for the model year · Accessories          |



|             |                                                                                          |
|-------------|------------------------------------------------------------------------------------------|
| 24 Nov 2021 | Transport Canada recall 2021723 <sup>[2]</sup><br>Issued for the model year · Electrical |
| 25 Oct 2026 | Listed for sale, Hilden, NS <sup>[5]</sup><br>RuralWorx Auto Sales · asking \$18,995     |
| 28 Oct 2026 | Listing last updated <sup>[5]</sup><br>asking \$18,995                                   |

## §5 DOCUMENTS

Window sticker      We have not collected this label yet.

## SOURCES

- |                                                                     |                                                                               |
|---------------------------------------------------------------------|-------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same model year, 10 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     | [5] Live public dealer listings on Cardog, as of 28 Oct 2026                  |
| [3] NHTSA recall records (United States), listed for the model year |                                                                               |

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

