

Register entry, as of 26 October 2026

Listed for sale

Record ID 86ef650e4e07

2011 Toyota Sequoia

5.7 L, 8 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5TD

WMI 1-3

Toyota Motor Manufacturi...

DY5G1

DESCRIPTOR 4-8

Sequoia · 5.7 L

6

CHECK 9

Verified

B

YEAR 10

2011

S

PLANT 11

Princeton

040900

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2011	Engine	5.7 L, 8 cylinders
Make	Toyota	Fuel	Gasoline
Model	Sequoia	Drive	4WD
Trim	Not in the decode	Maker	TOYOTA MOTOR MANUFACTURING, INDIANA, INC.
Body	Sport Utility Vehicle	Plant	Princeton, Indiana, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/sequoia/2011

2 recalls listed by Transport Canada for this model year

Electrical 2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

Electrical 2015493 21 Oct 2015

On certain vehicles, inconsistent application of grease during the manufacturing process could cause the driver's side power window master switch to stick or become inoperative due to electrical contact point wear. This could cause debris to accumulate between the contact points, potentially resulting in an electrical short circuit. If a short circuit occurs, the switch assembly may overheat, produce smoke, melt and/or potentially lead to a fire causing injury and/or property damage. Correction: Dealers will inspect the driver's power window master switch and apply a specialized grease that inhibits heat build-up, or replace the power window master switch circuit board, as necessary. Note: This is an expansion of recall 2012-338.



Listed for the model year, not checked against your VIN. Toyota confirms which apply.
Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
www.toyota.ca/en/owners/recalls/

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$18,999^[5], \$2,355 under the median of \$21,354^[4].



Lowest ask	\$18,999
Middle half	\$20,176 – \$22,531
Median ask	\$21,354
This car	\$18,999

Same model year · 2 live listings · as of 26 Oct 2026

OTHER 2011 TOYOTA SEQUOIA LISTINGS ^[5]

Medicine Hat, AB · 256,728 km \$23,708

§4 EVENTS

2011	Model year 2011 ^[1] Assembly plant Princeton, Indiana, United States
21 Oct 2015	Transport Canada recall 2015493 ^[2] Issued for the model year · Electrical
24 Nov 2021	Transport Canada recall 2021723 ^[2] Issued for the model year · Electrical
19 Oct 2026	Listed for sale, Headingley, MB ^[5] SS Auto Sales · asking \$18,999
26 Oct 2026	Listing last updated ^[5] asking \$18,999

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 2 live listings, as of 26 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 26 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |



STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

