Register entry, as of 29 October 2026 Listed for sale Record ID d4aeb705dad6

2017 Toyota Sienna Ltd/Ltd Premium/XLE/XLE Premium

3.5 L, 6 cylinders · 4WD · Minivan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5TD	DZ3DC	6	H	S	173057
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Toyota Motor Manufacturi…	Sienna · 3.5 L	Verified	2017	Princeton	Build sequence

§1 IDENTITY [1]

Model year	2017	Engine	3.5 L, 6 cylinders
Make	Toyota	Fuel	Gasoline
Model	Sienna	Drive	4WD
Trim	Ltd/Ltd Premium/XLE/XLE Premium	Maker	TOYOTA MOTOR MANUFACTURING, INDIANA, INC.
Body	Minivan	Plant	Princeton, Indiana, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/sienna/2017

7 recalls listed by Transport Canada for this model year

Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

Fuel system

2020514 28 Oct 2020

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall is an expansion of recalls SRC R95/SRC R96 and SRC RA2/SRC RA3 (Transport Canada Recall Numbers 2020-005 and 2020-088). Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump.

Fuel system
2020088 4 Mar 2020

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall is an expansion of recall SRC R95/SRC R96 (Transport Canada Recall No. 2020-005) Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump.

Steering
2019355 22 Jul 2019

Issue: On certain vans converted to a mobility vehicle by BraunAbility, the steering shaft extension could break. If this happens, there would be a sudden loss of steering control. Safety Risk: A loss of steering control could create the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a BraunAbility dealer to replace the steering shaft extension with an improved part.

Brakes
2019317 27 Jun 2019

Issue: On certain vans converted to a rear-entry mobility vehicle by BraunAbility, the fittings for the brake line extensions may be incorrect. This could cause a brake fluid leak that may result in reducing braking. Note: This problem affects conversions that were built between January 9, 2018, and May 20, 2019. Safety Risk: Reduced braking could cause extended stopping distances and increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a BraunAbility dealer to inspect the brake line connections. If necessary, an adapter fitting will be installed and the brake system will be bled.

Brakes
2018155 3 Apr 2018

On certain vehicles, an oil passage in the rotor of the vacuum pump may not have been machined properly and could result in oil not being distributed throughout the pump. This could lead to the illumination of a warning light and message, an audible tone, and a sudden loss of braking assist, which could increase stopping distances and increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the vacuum pump with a new one.

1 more on the model-year record, cardog.app/tools/recalls/toyota/sienna/2017

> Listed for the model year, not checked against your VIN. Toyota confirms which apply.
> Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
> www.toyota.ca/en/owners/recalls/

United States: 10 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $23,995[5], $1,253 over the median of $22,742[4].

Lowest ask	$8,888
Middle half	$18,246 – $24,984
Median ask	$22,742
This car	$23,995

Same model year · 26 live listings · as of 29 Oct 2026

OTHER 2017 TOYOTA SIENNA LISTINGS [5]

Montréal, QC · 191,322 km	$19,995
Calgary, AB · 257,611 km	$17,900
Milton, ON · 126,158 km	$23,998
Gatineau, QC · 137,816 km	$22,495
Quebec, QC · 126,500 km	$24,950
Dieppe, NB · 388,141 km	$8,888

§4 EVENTS

2017	Model year 2017[1] Assembly plant Princeton, Indiana, United States
20 Jul 2017	Transport Canada recall 2017363[2] Issued for the model year · Electrical
3 Apr 2018	Transport Canada recall 2018155[2] Issued for the model year · Brakes
27 Jun 2019	Transport Canada recall 2019317[2] Issued for the model year · Brakes
22 Jul 2019	Transport Canada recall 2019355[2] Issued for the model year · Steering
4 Mar 2020	Transport Canada recall 2020088[2] Issued for the model year · Fuel system
28 Oct 2020	Transport Canada recall 2020514[2] Issued for the model year · Fuel system
24 Nov 2021	Transport Canada recall 2021723[2] Issued for the model year · Electrical
28 Oct 2026	Listed for sale, High River, AB[5] High River Toyota · asking $23,995
29 Oct 2026	Listing last updated[5] asking $23,995

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 26 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.