

Register entry, as of 29 October 2026

Listed for sale

Record ID 7f1fa3ef2904

2021 Toyota Sienna

2.5 L, 4 cylinders · 4WD · Minivan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5TD GSKFC 7 M S 012929

WMI 1-3

Toyota Motor Manufacturi...

DESCRIPTOR 4-8

Sienna · 2.5 L

CHECK 9

Verified

YEAR 10

2021

PLANT 11

Princeton

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	2.5 L, 4 cylinders
Make	Toyota	Fuel	Gasoline
Model	Sienna	Drive	4WD
Trim	Not in the decode	Maker	TOYOTA MOTOR MANUFACTURING, INDIANA, INC.
Body	Minivan	Plant	Princeton, Indiana, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/sienna/2021

4 recalls listed by Transport Canada for this model year

Seats and restraints 2026003 5 Jan 2026

Issue: On certain vehicles converted for wheelchair access by Vantage Mobility, the wheelchair tie-down retractors may not have been manufactured properly. As a result, the retractor(s) may not lock automatically. If this happens, the wheelchair may not be secured correctly and could move in a crash. Note: This recall only affects certain Q'Straint QRT-DELUXE and QRT-MAX wheelchair retractors with the part number Q8-6200 or Q8-6209. Safety Risk: A wheelchair that moves in a crash could increase the risk of injury. Corrective Actions: To reduce the safety risk, Vantage Mobility recommends you confirm the wheelchair is secured properly by attempting to move it before driving until the recall repairs have been completed. Vantage Mobility will notify owners by mail and advise you to take your vehicle to a Vantage Mobility service center to inspect and, if necessary, replace the wheelchair retractor(s).

Seats and restraints 2025070 13 Feb 2025

Issue: On certain vehicles, the bolts that secure the third-row seats may not have been tightened properly. As a result, the seats could move in a crash. Safety Risk: A seat that moves in a crash could increase the risk of injury. Corrective Action: Toyota will notify owners by mail and advise you to take your vehicle to a dealership to tighten the bolts for the third-row seats.

Airbag 2023684 20 Dec 2023

Issue: On certain vehicles, a sensor for the occupant classification system (OCS) may not have been manufactured properly. As a result, the sensor could short circuit and cause the airbag system to turn off the passenger-front airbag even when a passenger is seated. Note: This problem would cause a warning message to display on the instrument panel and the airbag indicator light would display "passenger airbag off". Safety Risk: An airbag that is turned off could increase the risk of injury to a passenger in a crash. Corrective Actions: Toyota will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the OCS sensor.



Brakes

2022179 13 Apr 2022

Issue: Under certain conditions, the vehicle stability control (VSC) system may not switch on when the ignition is restarted. This can happen if the driver manually turns off the VSC, depresses the brake pedal, and then turns off and restarts the vehicle while continuously depressing the brake pedal. Canadian regulations require the stability control system to be active each time that you start the vehicle. Safety Risk: A stability control system that is switched off could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to update the skid control ECU software.

Listed for the model year, not checked against your VIN. Toyota confirms which apply.
Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
www.toyota.ca/en/owners/recalls/

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$28,888^[5], \$12,051 under the median of \$40,939^[4].



Lowest ask	\$28,888
Middle half	\$37,995 – \$43,940
Median ask	\$40,939
This car	\$28,888

Same configuration · 14 live listings · as of 29 Oct 2026

OTHER 2021 TOYOTA SIENNA LISTINGS [5]

Sudbury, ON · 113,502 km	\$39,966
Rouyn-Noranda, QC · 102,547 km	\$39,995
ST. JOHN&s;s, NL · 53,822 km	\$42,988
Sault Ste. Marie, ON · 120,025 km	\$38,995
Lethbridge, AB · 76,447 km	\$48,890
Stettler, AB · 76,447 km	\$48,890

§4 EVENTS

2021	Model year 2021 ^[1] Assembly plant Princeton, Indiana, United States
13 Apr 2022	Transport Canada recall 2022179 ^[2] Issued for the model year · Brakes
20 Dec 2023	Transport Canada recall 2023684 ^[2] Issued for the model year · Airbag
13 Feb 2025	Transport Canada recall 2025070 ^[2] Issued for the model year · Seats and restraints
5 Jan 2026	Transport Canada recall 2026003 ^[2] Issued for the model year · Seats and restraints



15 Sep 2026 Listed for sale, Concord, ON^[5]
Toronto Autohaus Ltd. · asking \$28,888

29 Oct 2026 Listing last updated^[5]
asking \$28,888

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same configuration, 14 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 29 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

