

Register entry, as of 29 October 2026

Listed for sale

Record ID f40213f3933e

2015 Toyota Highlander Base/Hybrid

3.5 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5TD JKRFH 9 F S 205371

WMI 1-3

Toyota Motor Manufacturi...

DESCRIPTOR 4-8

Highlander · 3.5 L

CHECK 9

Verified

YEAR 10

2015

PLANT 11

Princeton

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	3.5 L, 6 cylinders
Make	Toyota	Fuel	Gasoline
Model	Highlander	Drive	4WD
Trim	Base/Hybrid	Maker	TOYOTA MOTOR MANUFACTURING, INDIANA, INC.
Body	Sport Utility Vehicle	Plant	Princeton, Indiana, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/highlander/2015

3 recalls listed by Transport Canada for this model year

Electrical	2021723 24 Nov 2021
Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.	
Accessories	2019428 23 Aug 2019
Issue: On certain vehicles, the hook and loop material used to attach the carpet to its underpadding may not be flame resistant. As a result, when it is tested alone, the loop fasteners do not meet the requirements of Canadian regulations. Safety Risk: As the carpet is always assembled, and the loop fasteners are very small, this problem does not create a safety risk. Corrective Action: This is not a recall. The company has made production changes to ensure that all new vehicles meet the requirements of Canadian regulations.	



Steering

2015103 11 Mar 2015

On certain vehicles, the circuit board for the electric power steering electronic control unit may be damaged. A damaged circuit board could result in sudden loss of steering power assist and would trigger a warning lamp to illuminate. A vehicle experiencing a loss of steering power assist would revert to a manual steering mode which would require greater driver effort, especially at low vehicle speeds. A loss of steering power assist could ultimately result in a crash causing property damage and/or personal injury. Correction: Dealers will replace inspect the electric power steering electronic control unit and, if affected, replace the electronic control unit with a new one.

Listed for the model year, not checked against your VIN. Toyota confirms which apply.

Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.

www.toyota.ca/en/owners/recalls/

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$17,999^[5], \$2,991 under the median of \$20,990^[4].



Lowest ask	\$9,999
Middle half	\$17,999 – \$22,246
Median ask	\$20,990
This car	\$17,999

Same model year · 23 live listings · as of 29 Oct 2026

OTHER 2015 TOYOTA HIGHLANDER LISTINGS [5]

Prince George, BC · 157,607 km	\$22,497
Kelowna, BC · 158,317 km	\$23,995
Kelowna, BC · 158,317 km	\$23,995
Cranbrook, BC · 151,878 km	\$26,737
Chilliwack, BC · 231,697 km	\$21,900
Cranbrook, BC · 151,878 km	\$26,737

§4 EVENTS

2015	Model year 2015 ^[1] Assembly plant Princeton, Indiana, United States
11 Mar 2015	Transport Canada recall 2015103 ^[2] Issued for the model year · Steering
23 Aug 2019	Transport Canada recall 2019428 ^[2] Issued for the model year · Accessories
24 Nov 2021	Transport Canada recall 2021723 ^[2] Issued for the model year · Electrical
15 Oct 2026	Listed for sale, Kitchener, ON ^[5] Fahad Khan United Motorz Inc. · asking \$17,999



29 Oct 2026 Listing last updated^[5]
asking \$17,999

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 23 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 29 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

