

Register entry, as of 27 October 2026

Listed for sale

Record ID cefaf721a785

2025 Toyota Highlander LE, XLE, XSE, Platinum, Limited

2.4 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5TD

WMI 1-3

Toyota Motor Manufacturi...

KDRBH

DESCRIPTOR 4-8

Highlander · 2.4 L

7

CHECK 9

Verified

S

YEAR 10

2025

S

PLANT 11

Princeton

576544

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2025	Engine	2.4 L, 4 cylinders
Make	Toyota	Fuel	Gasoline
Model	Highlander	Drive	4WD
Trim	LE, XLE, XSE, Platinum, Limited	Maker	TOYOTA MOTOR MANUFACTURING, INDIANA, INC.
Body	Sport Utility Vehicle	Plant	Princeton, Indiana, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/highlander/2025

3

 recalls listed by Transport Canada for this model year

Seats and restraints

2026427 9 Sep 2026

Issue: On certain vehicles, the seatback recliners for the second-row seats may not have been manufactured properly. As a result, the seatback(s) may not lock in position and could move in a crash. Note: This recall replaces Transport Canada recall No. 2026-101. Safety Risk: A seatback that moves could increase the risk of injury in a crash. Corrective Action: To reduce the safety risk, Toyota recommends not using the second-row seats to transport passengers until the recall repairs have been completed. Toyota will notify owners by mail and advise you to take your vehicle to a dealership to replace the spring in the second-row seatback recliner assemblies.

Seats and restraints

2025694 17 Dec 2025

Issue: On a small number of vehicles, the bolt that secures the third-row center seat belt anchor to the roof may not have been installed properly. As a result, the seat belt could loosen or detach in a crash. Safety Risk: A seat belt that detaches in a crash could increase the risk of injury. Corrective Actions: To reduce the safety risk, Toyota advises that you shouldn't transport a passenger in the third-row center seat until the recall repairs are completed. Toyota will notify owners by mail and advise you to take your vehicle to a dealership to replace the third-row center seat belt upper anchor bolt.



Visual system

2025594 30 Oct 2025

Issue: Under certain conditions, a software problem could cause the rearview camera image to freeze or not to display. If this happens, the rearview image may not display when the transmission is shifted into reverse. Canadian regulations require the rearview image to display when the vehicle is reversing. Note: This recall only affects certain vehicles equipped with a panoramic view monitor system. Safety Risk: A rearview camera image that doesn't display correctly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: The company will notify owners in writing and advise you to take your vehicle to a dealership to update the parking assist ECU software.

Listed for the model year, not checked against your VIN. Toyota confirms which apply.
Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.

www.toyota.ca/en/owners/recalls/

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$51,777^[5], \$7,173 under the median of \$58,950^[4].



Lowest ask	\$51,777
Middle half	\$56,321 – \$62,922
Median ask	\$58,950
This car	\$51,777

Same model year · 25 live listings · as of 27 Oct 2026

OTHER 2025 TOYOTA HIGHLANDER LISTINGS [5]

Markham, ON · 22,006 km	\$62,888
Walkerton, ON · 43,155 km	\$55,900
Edmonton, AB · 30,076 km	\$58,950
Toronto, ON · 41,015 km	\$53,000
Calgary, AB · 26,625 km	\$56,321
Sherbrooke, QC · 45,200 km	\$65,987

§4 EVENTS

2025	Model year 2025 ^[1] Assembly plant Princeton, Indiana, United States
30 Oct 2025	Transport Canada recall 2025594 ^[2] Issued for the model year · Visual system
17 Dec 2025	Transport Canada recall 2025694 ^[2] Issued for the model year · Seats and restraints
31 Jul 2026	Listed for sale, Toronto, ON ^[5] LEXUS ON THE PARK · asking \$51,777
9 Sep 2026	Transport Canada recall 2026427 ^[2] Issued for the model year · Seats and restraints



27 Oct 2026 Listing last updated^[5]
asking \$51,777

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 25 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

