Register entry, as of 27 October 2026 Listed for sale Record ID 2c534fc82736

2016 Toyota Sienna

3.5 L, 6 cylinders · 4x2 · Minivan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5TD	XK3DC	2	G	S	697824
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Toyota Motor Manufacturi…	Sienna · 3.5 L	Verified	2016	Princeton	Build sequence

§1 IDENTITY [1]

Model year	2016	Engine	3.5 L, 6 cylinders
Make	Toyota	Fuel	Gasoline
Model	Sienna	Drive	4x2
Trim	Not in the decode	Maker	TOYOTA MOTOR MANUFACTURING, INDIANA, INC.
Body	Minivan	Plant	Princeton, Indiana, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/sienna/2016

4 recalls listed by Transport Canada for this model year

Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

Brakes

2019317 27 Jun 2019

Issue: On certain vans converted to a rear-entry mobility vehicle by BraunAbility, the fittings for the brake line extensions may be incorrect. This could cause a brake fluid leak that may result in reducing braking. Note: This problem affects conversions that were built between January 9, 2018, and May 20, 2019. Safety Risk: Reduced braking could cause extended stopping distances and increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a BraunAbility dealer to inspect the brake line connections. If necessary, an adapter fitting will be installed and the brake system will be bled.

Electrical

2017363 20 Jul 2017

On certain vehicles, the electrical power cords of some dealer installed block heaters may have been improperly manufactured, causing the wires to contact each other, resulting in a short circuit. A short circuit could lead to a fire which would increase the risk of injury and/or damage to property. Correction: For vehicles where the subject block heater was approved for installation, the dealer will replace the block heater assembly with a new one of an improved design. For vehicles where the subject block heater was not approved for installation, dealers will remove the block heater assembly. In the interim, until the remedy can be performed, dealers will cut the plug end from the block heater cord to disable the block heater's operation.

Structure

2016586 22 Nov 2016

On certain vehicles equipped with power sliding doors, under certain conditions which impede the opening of the door (such as if the door becomes frozen with ice), the sliding door motor could stall when the door is operated. If the motor stalls, high current in the door motor circuit could be generated, operating the circuit protection for the door motor. If this occurs with the sliding door latch mechanism in an unlatched position, the door could open while driving, increasing the risk of injury to a vehicle occupant. Correction: Dealers will replace the existing junction block and the rear sliding door wire harnesses with newly designed ones. The dealer will also install two sub wire harnesses to connect the junction block to the two rear door wire harnesses.

Listed for the model year, not checked against your VIN. Toyota confirms which apply.
Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
www.toyota.ca/en/owners/recalls/

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $26,995[5], $5,747 over the median of $21,248[4].



Lowest ask	$16,995
Middle half	$19,245 – $22,871
Median ask	$21,248
This car	$26,995

Same model year · 6 live listings · as of 27 Oct 2026

OTHER 2016 TOYOTA SIENNA LISTINGS [5]

Orillia, ON · 182,200 km	$16,995
Acton, ON · 165,724 km	$19,995
Airdrie, AB · 180,647 km	$22,500
Toronto, ON · 186,569 km	$22,995
Toronto, ON · 229,980 km	$18,995

§4 EVENTS

2016	Model year 2016[1] Assembly plant Princeton, Indiana, United States
22 Nov 2016	Transport Canada recall 2016586[2] Issued for the model year · Structure

20 Jul 2017	Transport Canada recall 2017363[2] Issued for the model year · Electrical
27 Jun 2019	Transport Canada recall 2019317[2] Issued for the model year · Brakes
24 Nov 2021	Transport Canada recall 2021723[2] Issued for the model year · Electrical
13 Jun 2026	Listed for sale, Ottawa, ON[5] Streetside Motors · asking $26,995
27 Oct 2026	Listing last updated[5] asking $26,995

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 6 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.