Register entry, as of 28 October 2026 Listed for sale Record ID 89b1ed3527d8

2015 Toyota Tundra Limited Grade

5.7 L, 8 cylinders · 4WD · Pickup · Ethanol (E85)

VEHICLE IDENTIFICATION NUMBER [1]

5TF	BY5F1	7	F	X	421468
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Toyota Motor Manufacturi…	Tundra · 5.7 L	Verified	2015	San Antonio	Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	5.7 L, 8 cylinders
Make	Toyota	Fuel	Ethanol (E85)
Model	Tundra	Drive	4WD
Trim	Limited Grade	Maker	TOYOTA MOTOR MANUFACTURING, TEXAS, INC.
Body	Pickup	Plant	San Antonio, Texas, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/tundra/2015

3 recalls listed by Transport Canada for this model year

Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

Steering

2021718 23 Nov 2021

Issue: On certain vehicles, a defect in the steering gear assembly could cause it to leak power steering fluid. If this happens, there could be a loss of power steering assist. Note: For 2007-2020 models, this recall only affects 41 vehicles that had a replacement steering gear installed in 2021. Safety Risk: A loss of power steering assist may result in a sudden increase in steering effort, especially at low speeds. This could increase the risk of a crash. Corrective Actions: Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to inspect, and if necessary, replace power steering gear assembly.

Label

2015454 7 Oct 2015

Certain vehicles fail to comply with the requirements of Canada Motor Vehicle Safety Standard 110 - Tire Selection and Rims. Certain compliance labels were misprinted and omitted the French translation of the word 'RIMS' (JANTES). As such, these labels do not meet the requirements of CMVSS 110, specifically TSD 110 S4.3.3. The numerical designation of the rim size is correctly printed and it is only the French translation of the word "RIMS" that has been omitted. Correction: A production change has been undertaken to remedy this technical non-compliance condition. No corrective recall action is required as the technical non-compliance conditions are deemed to be non-safety related.

Listed for the model year, not checked against your VIN. Toyota confirms which apply.
Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
www.toyota.ca/en/owners/recalls/

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $27,995[5], the median[4].



Lowest ask	$18,450
Middle half	$24,999 – $33,274
Median ask	$27,995
This car	$27,995

Same model year · 11 live listings · as of 28 Oct 2026

OTHER 2015 TOYOTA TUNDRA LISTINGS [5]

Moosomin, SK · 218,763 km	$29,995
Esterhazy, SK · 218,763 km	$29,995
Weyburn, SK · 218,763 km	$29,995
Québec, QC · 189,000 km	$27,995
Toronto, ON · 61,143 km	$37,990
St. Catharines, ON · 305,962 km	$24,999

§4 EVENTS

2015	Model year 2015[1] Assembly plant San Antonio, Texas, United States
7 Oct 2015	Transport Canada recall 2015454[2] Issued for the model year · Label
23 Nov 2021	Transport Canada recall 2021718[2] Issued for the model year · Steering
24 Nov 2021	Transport Canada recall 2021723[2] Issued for the model year · Electrical
6 Oct 2026	Listed for sale, St-Hyacinthe, QC[5] Angers Toyota · asking $27,995

28 Oct 2026 Listing last updated[5]
asking $27,995

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 11 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.