Register entry, as of 28 October 2026 Listed for sale Record ID 0ab31bd973a9

# 2020 Toyota Tundra SR5 Grade

5.7 L, 8 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 5TF | DY5F1 | 1 | L | X | 911778 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Toyota Motor Manufacturi… | Tundra · 5.7 L | Verified | 2020 | San Antonio | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2020 | Engine | 5.7 L, 8 cylinders |
| Make | Toyota | Fuel | Gasoline |
| Model | Tundra | Drive | 4WD |
| Trim | SR5 Grade | Maker | TOYOTA MOTOR MANUFACTURING, TEXAS, INC. |
| Body | Pickup | Plant | San Antonio, Texas, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/tundra/2020

**4** recalls listed by Transport Canada for this model year

### Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

### Lights and instruments

2021544 2 Sep 2021

Issue: On certain trucks equipped with halogen headlamps, when the high beams are switched on, both the high and low beam lights turn on. Under certain conditions, this could cause the headlamps and wiring to overheat. Safety Risk: A headlamp that overheats can cause a loss of lighting and could create a fire risk. Corrective Actions: Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to modify the engine wire harness assembly. The dealer will also inspect the headlamp assemblies, bulbs and bulb connectors for damage. The dealer will replace parts damaged by this problem.

### Lights and instruments

2020321 15 Jul 2020

Issue: On certain vehicles, the wire harness for the front turn signal lights was assembled incorrectly. As a result, the turn signals and hazard warning lights are not bright enough to meet Canadian regulations. This could cause other road users not to notice when the signal or hazard warning lights are turned on. Safety Risk: Signal lights that are not bright enough could make the vehicle less visible to others, and could increase the risk of a crash. Corrective Actions: Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to modify the wire harness for the front turn signal lights.

### Label

2019651 20 Dec 2019

Issue: On certain vehicles, the spare tire size is listed as P275/65R18, whereas the actual installed spare tire size is P255/70R18. Canadian regulations require companies correct tire information on the tire information label. Safety Risk: This small error is unlikely to affect safety. Corrective Action: This is not a recall. This notice is for information only. The company has made changes to correct this label on all new vehicles.

Listed for the model year, not checked against your VIN. Toyota confirms which apply.
Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
www.toyota.ca/en/owners/recalls/

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $32,495[5], $12,925 under the median of $45,420[4].

| | |
|---|---|
| Lowest ask | $32,495 |
| Middle half | $41,749 – $48,647 |
| Median ask | $45,420 |
| This car | $32,495 |

Same configuration · 8 live listings · as of 28 Oct 2026

### OTHER 2020 TOYOTA TUNDRA LISTINGS [5]

| | |
|---|---|
| Milton, ON · 126,434 km | $51,488 |
| Sudbury, ON · 122,276 km | $43,991 |
| Kelowna, BC · 110,001 km | $44,980 |
| Winnipeg, MB · 144,052 km | $42,999 |
| Guelph, ON · 201,700 km | $37,999 |
| Ottawa, ON · 101,957 km | $46,952 |

## §4 EVENTS

| | |
|---|---|
| 2020 | Model year 2020[1]<br>Assembly plant San Antonio, Texas, United States |
| 20 Dec 2019 | Transport Canada recall 2019651[2]<br>Issued for the model year · Label |
| 15 Jul 2020 | Transport Canada recall 2020321[2]<br>Issued for the model year · Lights and instruments |

| | |
|---|---|
| 2 Sep 2021 | Transport Canada recall 2021544[2]<br>Issued for the model year · Lights and instruments |
| 24 Nov 2021 | Transport Canada recall 2021723[2]<br>Issued for the model year · Electrical |
| 22 Aug 2026 | Listed for sale, Stellarton, NS[5]<br>Anchor Toyota · asking $32,495 |
| 27 Oct 2026 | Listing last updated[5]<br>asking $32,495 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 8 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.