

Register entry, as of 27 October 2026

Listed for sale

Record ID c28d69bcbb5

# 2016 Toyota Tundra SR5/TRD Pro

5.7 L, 8 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**5TF** **DY5F1** **X** **G** **X** **544739**

WMI 1-3

Toyota Motor Manufacturi...

DESCRIPTOR 4-8

Tundra · 5.7 L

CHECK 9

Verified

YEAR 10

2016

PLANT 11

San Antonio

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |             |        |                                         |
|------------|-------------|--------|-----------------------------------------|
| Model year | 2016        | Engine | 5.7 L, 8 cylinders                      |
| Make       | Toyota      | Fuel   | Gasoline                                |
| Model      | Tundra      | Drive  | 4WD                                     |
| Trim       | SR5/TRD Pro | Maker  | TOYOTA MOTOR MANUFACTURING, TEXAS, INC. |
| Body       | Pickup      | Plant  | San Antonio, Texas, United States       |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/tundra/2016

## 3 recalls listed by Transport Canada for this model year

### Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

### Electrical

2017363 20 Jul 2017

On certain vehicles, the electrical power cords of some dealer installed block heaters may have been improperly manufactured, causing the wires to contact each other, resulting in a short circuit. A short circuit could lead to a fire which would increase the risk of injury and/or damage to property. Correction: For vehicles where the subject block heater was approved for installation, the dealer will replace the block heater assembly with a new one of an improved design. For vehicles where the subject block heater was not approved for installation, dealers will remove the block heater assembly. In the interim, until the remedy can be performed, dealers will cut the plug end from the block heater cord to disable the block heater's operation.



## Structure

2017036 24 Jan 2017

On certain vehicles equipped with the plastic rear step bumper, the resin reinforcement brackets that secure the step corners of the bumper could become damaged after a rear impact. If a person were to use the rear bumper steps with damaged resin reinforcement brackets, part of the bumper could break off which could cause the person to fall, increasing the risk of injury. Correction: Dealers will replace the resin reinforcement brackets with steel reinforcement brackets. In addition, the rear bumper tread covers will also be replaced.

Listed for the model year, not checked against your VIN. Toyota confirms which apply.  
Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.  
[www.toyota.ca/en/owners/recalls/](http://www.toyota.ca/en/owners/recalls/)

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

§3 VALUE <sup>[4]</sup>

This car asks \$34,995<sup>[5]</sup>, \$995 over the median of \$34,000<sup>[4]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$12,300            |
| Middle half | \$30,722 – \$34,653 |
| Median ask  | \$34,000            |
| This car    | \$34,995            |

Same model year · 7 live listings · as of 27 Oct 2026

OTHER 2016 TOYOTA TUNDRA LISTINGS <sup>[5]</sup>

|                              |          |
|------------------------------|----------|
| Thunder Bay, ON · 126,382 km | \$34,000 |
| Newmarket, ON · 76,748 km    | \$47,499 |
| Winnipeg, MB · 91,007 km     | \$34,311 |
| Mississauga, ON · 427,100 km | \$12,300 |
| Laval, QC · 99,708 km        | \$33,450 |
| Lachute, QC · 220,784 km     | \$27,995 |

## §4 EVENTS

|             |                                                                                          |
|-------------|------------------------------------------------------------------------------------------|
| 2016        | Model year 2016 <sup>[1]</sup><br>Assembly plant San Antonio, Texas, United States       |
| 24 Jan 2017 | Transport Canada recall 2017036 <sup>[2]</sup><br>Issued for the model year · Structure  |
| 20 Jul 2017 | Transport Canada recall 2017363 <sup>[2]</sup><br>Issued for the model year · Electrical |
| 24 Nov 2021 | Transport Canada recall 2021723 <sup>[2]</sup><br>Issued for the model year · Electrical |
| 20 Oct 2026 | Listed for sale, Miramichi, NB <sup>[5]</sup><br>Roussel Toyota · asking \$34,995        |



27 Oct 2026      Listing last updated<sup>[5]</sup>  
asking \$34,995

## §5 DOCUMENTS

Window sticker      We have not collected this label yet.

## SOURCES

- |                                                                     |                                                                              |
|---------------------------------------------------------------------|------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same model year, 7 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     |                                                                              |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026                 |

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

