Register entry, as of 29 October 2026 Listed for sale Record ID d3c34061bb1a

# 2019 Toyota Tacoma SR5

3.5 L, 6 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 5TF | DZ5BN | 3 | K | X | 046302 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Toyota Motor Manufacturi… | Tacoma · 3.5 L | Verified | 2019 | San Antonio | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2019 | Engine | 3.5 L, 6 cylinders |
| Make | Toyota | Fuel | Gasoline |
| Model | Tacoma | Drive | 4WD |
| Trim | SR5 | Maker | TOYOTA MOTOR MANUFACTURING, TEXAS, INC. |
| Body | Pickup | Plant | San Antonio, Texas, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/tacoma/2019

**5** recalls listed by Transport Canada for this model year

### Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

### Fuel system

2020514 28 Oct 2020

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall is an expansion of recalls SRC R95/SRC R96 and SRC RA2/SRC RA3 (Transport Canada Recall Numbers 2020-005 and 2020-088). Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump.

### Fuel system
2020088 4 Mar 2020

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall is an expansion of recall SRC R95/SRC R96 (Transport Canada Recall No. 2020-005) Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump.

### Fuel system
2020005 13 Jan 2020

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump.

### Brakes
2018705 13 Dec 2018

On certain vehicles, the brake master cylinder may contain a defect which could allow an internal brake fluid leak. This could reduce the performance of the front brakes, increasing stopping distances, which could result in a crash causing injury and/or damage to property. Correction: Dealers will replace the defective brake master cylinder.

> Listed for the model year, not checked against your VIN. Toyota confirms which apply.
> Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
> www.toyota.ca/en/owners/recalls/

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $44,995[5], $8,003 over the median of $36,992[4].




| | |
|---|---|
| Lowest ask | $27,995 |
| Middle half | $34,365 – $39,982 |
| Median ask | $36,992 |
| This car | $44,995 |

Same configuration · 24 live listings · as of 29 Oct 2026

### OTHER 2019 TOYOTA TACOMA LISTINGS [5]

| | |
|---|---|
| Longueuil, QC · 102,947 km | $33,995 |
| Sault Ste. Marie, ON · 133,283 km | $27,995 |
| Winnipeg, MB · 192,000 km | $29,999 |
| Kelowna, BC · 73,335 km | $44,980 |
| Toronto, ON · 133,775 km | $35,000 |
| Smiths Falls, ON · 122,525 km | $36,998 |

## §4 EVENTS

| | |
|---|---|
| 2019 | Model year 2019[1]<br>Assembly plant San Antonio, Texas, United States |
| 13 Dec 2018 | Transport Canada recall 2018705[2]<br>Issued for the model year · Brakes |

| | |
|---|---|
| 13 Jan 2020 | Transport Canada recall 2020005[2]<br>Issued for the model year · Fuel system |
| 4 Mar 2020 | Transport Canada recall 2020088[2]<br>Issued for the model year · Fuel system |
| 28 Oct 2020 | Transport Canada recall 2020514[2]<br>Issued for the model year · Fuel system |
| 24 Nov 2021 | Transport Canada recall 2021723[2]<br>Issued for the model year · Electrical |
| 19 Mar 2025 | Listed for sale, North Vancouver, BC[5]<br>North Vancouver Nissan · asking $44,995 |
| 28 Oct 2026 | Listing last updated[5]<br>asking $44,995 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 24 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.