Register entry, as of 28 October 2026 Listed for sale Record ID a903f20b4afc

2024 Toyota Tundra Limited

3.4 L, 6 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5TF	JA5DB	8	R	X	151246
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Toyota Motor Manufacturi…	Tundra · 3.4 L	Verified	2024	San Antonio	Build sequence

§1 IDENTITY [1]

Model year	2024	Engine	3.4 L, 6 cylinders
Make	Toyota	Fuel	Gasoline
Model	Tundra	Drive	4WD
Trim	Limited	Maker	TOYOTA MOTOR MANUFACTURING, TEXAS, INC.
Body	Pickup	Plant	San Antonio, Texas, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/tundra/2024

7 recalls listed by Transport Canada for this model year

Engine — 2026241 — 20 May 2026

Issue: On certain vehicles, the engine may not have been manufactured properly. As a result, metal debris could cause the crankshaft bearings to fail. If this happens, the engine may run rough or may not start. This could also cause the engine to stall while driving. Note: This recall only affects certain vehicles equipped with a 3.4L twin-turbo engine. This recall replaces Transport Canada recall No. 2025-614. Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to inspect the No. 1 main bearing for abnormal wear and, if necessary, replace the engine.

Visual system — 2026026 — 23 Jan 2026

Issue: Under certain conditions, a software problem could cause the rearview camera image to freeze or not to display when the transmission is shifted into reverse. Canadian regulations require the rearview image to display when the vehicle is reversing. Note: This recall affects both Tundra and Tundra hybrid models equipped with a panoramic view monitor system. Safety Risk: A rearview camera image that doesn't display correctly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Toyota will notify owners by mail and advise you to take your vehicle to a dealership to update the parking assist electronic control unit software.

Engine — 2025614 — 6 Nov 2025

This recall was replaced by Transport Canada recall no. 2026-241. Issue: On certain vehicles, the engine may not have been manufactured properly. As a result, metal debris could cause the crankshaft bearings to fail. If this happens, the engine may run rough or may not start. This could also cause the engine to stall while driving. Note: This recall only affects certain vehicles equipped with a 3.4L twin-turbo engine. This recall is an expansion of Transport Canada Recall No. 2024-304. Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. Corrective Actions: The company will notify owners by mail. The corrective actions for this recall are under development.

Visual system

2025522 1 Oct 2025

Issue: Under certain conditions, a problem with the rearview camera could cause the rearview camera image not to display correctly or at all. Canadian regulations require the rearview image to display when the vehicle is reversing. Note: This recall only affects vehicles equipped with a 14-inch multimedia display. For the Tundra model, this recall affects both Tundra and Tundra hybrid models. Safety Risk: A rearview camera image that doesn't display correctly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Toyota will notify owners in writing and advise you to take your vehicle to a dealership to update the multimedia display software.

Lights and instruments

2025263 15 May 2025

Issue: On certain trucks, the reverse lamp assemblies may not be sealed correctly. As a result, over time, water could leak into the lamp(s) and cause them not to work. Note: This recall affects both Tundra and Tundra Hybrid models. Safety Risk: Reverse lamps that don't work could cause others not to recognize when a vehicle is backing up, and increase the risk of a crash. Corrective Actions: Toyota will notify owners by mail and advise you to take your truck to a dealership to inspect and, if necessary, replace both reverse lamp assemblies. Additionally, the dealer will inspect and, if necessary, repair the wiring for the reverse lamps.

Tires

2024607 15 Oct 2024

Issue: On certain vehicles, the passenger-side front and rear tires may have been damaged during vehicle assembly. This could cause a sudden loss of air pressure and result in a tire failure. Note: For the Tundra model, this recall affects both Tundra and Tundra hybrid models. Safety Risk: A tire failure could cause a loss of control and increase the risk of a crash. Corrective Actions: Toyota will notify owners by mail and advise you to take your vehicle to a dealership to inspect and replace the affected tires.

1 more on the model-year record, cardog.app/tools/recalls/toyota/tundra/2024

> Listed for the model year, not checked against your VIN. Toyota confirms which apply.
> Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
> www.toyota.ca/en/owners/recalls/

United States: 10 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $57,995[5], $7 over the median of $57,988[4].

Lowest ask	$55,400
Middle half	$57,123 – $58,746
Median ask	$57,988
This car	$57,995

Same configuration · 10 live listings · as of 28 Oct 2026

OTHER 2024 TOYOTA TUNDRA LISTINGS [5]

Calgary, AB · 46,851 km	$59,883
Calgary, AB · 120,742 km	$54,883
Peterborough, ON · 66,095 km	$51,392
Pitt Meadows, BC · 0 km	$59,995
Pitt Meadows, BC · 0 km	$59,995
Pitt Meadows, BC · 0 km	$59,995

§4 EVENTS

2024	Model year 2024[1] Assembly plant San Antonio, Texas, United States
21 Feb 2024	Transport Canada recall 2024109[2] Issued for the model year · Powertrain
15 Oct 2024	Transport Canada recall 2024607[2] Issued for the model year · Tires
15 May 2025	Transport Canada recall 2025263[2] Issued for the model year · Lights and instruments
1 Oct 2025	Transport Canada recall 2025522[2] Issued for the model year · Visual system
6 Nov 2025	Transport Canada recall 2025614[2] Issued for the model year · Engine
23 Jan 2026	Transport Canada recall 2026026[2] Issued for the model year · Visual system
20 May 2026	Transport Canada recall 2026241[2] Issued for the model year · Engine
26 Oct 2026	Listed for sale, Calgary, AB[5] Jack Carter Chevrolet Cadillac Buick GMC · asking $57,995
28 Oct 2026	Listing last updated[5] asking $57,995

§5 DOCUMENTS

Window sticker — We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 10 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.