Register entry, as of 27 November 2026 Listed for sale Record ID 39588d418da9

# 2025 Toyota Tundra SR5

3.4 L, 6 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 5TF | LA5EC | 9 | S | X | 047919 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Toyota Motor Manufacturi… | Tundra · 3.4 L | Verified | 2025 | San Antonio | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2025 | Engine | 3.4 L, 6 cylinders |
| Make | Toyota | Fuel | Gasoline |
| Model | Tundra | Drive | 4WD |
| Trim | SR5 | Maker | TOYOTA MOTOR MANUFACTURING, TEXAS, INC. |
| Body | Pickup | Plant | San Antonio, Texas, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/tundra/2025

**3** recalls listed by Transport Canada for this model year

### Visual system

2026026 23 Jan 2026

Issue: Under certain conditions, a software problem could cause the rearview camera image to freeze or not to display when the transmission is shifted into reverse. Canadian regulations require the rearview image to display when the vehicle is reversing. Note: This recall affects both Tundra and Tundra hybrid models equipped with a panoramic view monitor system. Safety Risk: A rearview camera image that doesn't display correctly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Toyota will notify owners by mail and advise you to take your vehicle to a dealership to update the parking assist electronic control unit software.

### Visual system

2025522 1 Oct 2025

Issue: Under certain conditions, a problem with the rearview camera could cause the rearview camera image not to display correctly or at all. Canadian regulations require the rearview image to display when the vehicle is reversing. Note: This recall only affects vehicles equipped with a 14-inch multimedia display. For the Tundra model, this recall affects both Tundra and Tundra hybrid models. Safety Risk: A rearview camera image that doesn't display correctly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Toyota will notify owners in writing and advise you to take your vehicle to a dealership to update the multimedia display software.

### Lights and instruments

2025263 15 May 2025

Issue: On certain trucks, the reverse lamp assemblies may not be sealed correctly. As a result, over time, water could leak into the lamp(s) and cause them not to work. Note: This recall affects both Tundra and Tundra Hybrid models. Safety Risk: Reverse lamps that don't work could cause others not to recognize when a vehicle is backing up, and increase the risk of a crash. Corrective Actions: Toyota will notify owners by mail and advise you to take your truck to a dealership to inspect and, if necessary, replace both reverse lamp assemblies. Additionally, the dealer will inspect and, if necessary, repair the wiring for the reverse lamps.

> Listed for the model year, not checked against your VIN. Toyota confirms which apply.
> Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
> www.toyota.ca/en/owners/recalls/

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $55,814[5], $90 under the median of $55,904[4].




| | |
|---|---|
| Lowest ask | $49,890 |
| Middle half | $54,039 – $57,475 |
| Median ask | $55,904 |
| This car | $55,814 |

Same configuration · 10 live listings · as of 27 Nov 2026

### OTHER 2025 TOYOTA TUNDRA LISTINGS [5]

| | |
|---|---|
| London, ON · 22,350 km | $65,995 |
| Vancouver, BC · 25,147 km | $70,999 |
| London, ON · 40,707 km | $63,998 |
| Hamilton, ON · 40,923 km | $62,116 |
| Midland, ON · 111,025 km | $49,000 |
| Ottawa, ON · 47,398 km | $79,368 |

## §4 EVENTS

| | |
|---|---|
| 2025 | **Model year 2025**[1]<br>Assembly plant San Antonio, Texas, United States |
| 15 May 2025 | **Transport Canada recall 2025263**[2]<br>Issued for the model year · Lights and instruments |
| 1 Oct 2025 | **Transport Canada recall 2025522**[2]<br>Issued for the model year · Visual system |
| 23 Jan 2026 | **Transport Canada recall 2026026**[2]<br>Issued for the model year · Visual system |
| 19 Nov 2026 | **Listed for sale, Edmonton, AB**[5]<br>Crosstown Chrysler Dodge Jeep Ram · asking $55,814 |
| 27 Nov 2026 | **Listing last updated**[5]<br>asking $55,814 |

## §5 DOCUMENTS

| | |
|---|---|
| Window sticker | We have not collected this label yet. |

## SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 10 live listings, as of 27 Nov 2026

[5] Live public dealer listings on Cardog, as of 27 Nov 2026

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.