Register entry, as of 29 October 2026 Listed for sale Record ID f0e062d2e6f2

2023 Toyota Tundra 1794

3.4 L, 6 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5TF	MC5DB	5	P	X	026189
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Toyota Motor Manufacturi…	Tundra · 3.4 L	Verified	2023	San Antonio	Build sequence

§1 IDENTITY [1]

Model year	2023	Engine	3.4 L, 6 cylinders
Make	Toyota	Fuel	Gasoline
Model	Tundra	Drive	4WD
Trim	1794	Maker	TOYOTA MOTOR MANUFACTURING, TEXAS, INC.
Body	Pickup	Plant	San Antonio, Texas, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/tundra/2023

10 recalls listed by Transport Canada for this model year

Engine

2026241 20 May 2026

Issue: On certain vehicles, the engine may not have been manufactured properly. As a result, metal debris could cause the crankshaft bearings to fail. If this happens, the engine may run rough or may not start. This could also cause the engine to stall while driving. Note: This recall only affects certain vehicles equipped with a 3.4L twin-turbo engine. This recall replaces Transport Canada recall No. 2025-614. Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to inspect the No. 1 main bearing for abnormal wear and, if necessary, replace the engine.

Engine

2025614 6 Nov 2025

This recall was replaced by Transport Canada recall no. 2026-241. Issue: On certain vehicles, the engine may not have been manufactured properly. As a result, metal debris could cause the crankshaft bearings to fail. If this happens, the engine may run rough or may not start. This could also cause the engine to stall while driving. Note: This recall only affects certain vehicles equipped with a 3.4L twin-turbo engine. This recall is an expansion of Transport Canada Recall No. 2024-304. Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. Corrective Actions: The company will notify owners by mail. The corrective actions for this recall are under development.

Visual system

2025522 1 Oct 2025

Issue: Under certain conditions, a problem with the rearview camera could cause the rearview camera image not to display correctly or at all. Canadian regulations require the rearview image to display when the vehicle is reversing. Note: This recall only affects vehicles equipped with a 14-inch multimedia display. For the Tundra model, this recall affects both Tundra and Tundra hybrid models. Safety Risk: A rearview camera image that doesn't display correctly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Toyota will notify owners in writing and advise you to take your vehicle to a dealership to update the multimedia display software.

Lights and instruments

2025263 15 May 2025

Issue: On certain trucks, the reverse lamp assemblies may not be sealed correctly. As a result, over time, water could leak into the lamp(s) and cause them not to work. Note: This recall affects both Tundra and Tundra Hybrid models. Safety Risk: Reverse lamps that don't work could cause others not to recognize when a vehicle is backing up, and increase the risk of a crash. Corrective Actions: Toyota will notify owners by mail and advise you to take your truck to a dealership to inspect and, if necessary, replace both reverse lamp assemblies. Additionally, the dealer will inspect and, if necessary, repair the wiring for the reverse lamps.

Engine

2024304 30 May 2024

Issue: On certain vehicles, the engine may not have been manufactured properly. As a result, metal debris could cause the crankshaft bearings to fail. If this happens, the engine may run rough or may not start. This could also cause the engine to stall while driving. Note: This recall only affects certain vehicles equipped with a 3.4L twin-turbo engine. Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the engine.

Powertrain

2024109 21 Feb 2024

Issue: On certain vehicles, a problem with the transmission could cause the vehicle to move forward when the driver shifts to the "N"(Neutral) position and the brakes or parking brake aren't applied. Note: For the Tundra model, this recall affects both Tundra and Tundra Hybrid models. For the Sequoia model, only the Sequoia Hybrid model is affected by this recall. Safety Risk: A vehicle that moves suddenly could create the risk of an injury or a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to update the transmission control unit software.

4 more on the model-year record, cardog.app/tools/recalls/toyota/tundra/2023

> Listed for the model year, not checked against your VIN. Toyota confirms which apply.
> Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
> www.toyota.ca/en/owners/recalls/

United States: 13 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $60,995[5], $8,000 over the median of $52,995[4].

Lowest ask	$36,990
Middle half	$48,690 – $57,998
Median ask	$52,995
This car	$60,995

Same model year · 147 live listings · as of 29 Oct 2026

OTHER 2023 TOYOTA TUNDRA LISTINGS [5]

Laval, QC · 81,397 km	$51,795
Oakville, ON · 95,230 km	$60,888
Edmonton, AB · 64,624 km	$74,749
Winnipeg, MB · 64,624 km	$64,999
Regina, SK · 64,624 km	$64,999
Winnipeg, MB · 64,624 km	$64,999

§4 EVENTS

2023	Model year 2023[1] Assembly plant San Antonio, Texas, United States
22 Feb 2023	Transport Canada recall 2023084[2] Issued for the model year · Visual system
3 Mar 2023	Transport Canada recall 2023112[2] Issued for the model year · Accessories
7 Jul 2023	Transport Canada recall 2023373[2] Issued for the model year · Accessories
10 Aug 2023	Transport Canada recall 2023445[2] Issued for the model year · Fuel system
21 Feb 2024	Transport Canada recall 2024109[2] Issued for the model year · Powertrain
30 May 2024	Transport Canada recall 2024304[2] Issued for the model year · Engine
15 May 2025	Transport Canada recall 2025263[2] Issued for the model year · Lights and instruments
1 Oct 2025	Transport Canada recall 2025522[2] Issued for the model year · Visual system
6 Nov 2025	Transport Canada recall 2025614[2] Issued for the model year · Engine
20 May 2026	Transport Canada recall 2026241[2] Issued for the model year · Engine
14 Oct 2026	Listed for sale, Kingston, ON[5] Carloft.Ca · asking $60,995
29 Oct 2026	Listing last updated[5] asking $60,995

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 147 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.