Register entry, as of 29 November 2026 Listed for sale Record ID 977779cb7c92

2013 Toyota Tacoma Delux

4.0 L, 6 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5TF	MU4FN	1	D	X	015569
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Toyota Motor Manufacturi…	Tacoma · 4.0 L	Verified	2013	San Antonio	Build sequence

§1 IDENTITY [1]

Model year	2013	Engine	4.0 L, 6 cylinders
Make	Toyota	Fuel	Gasoline
Model	Tacoma	Drive	4WD
Trim	Delux	Maker	TOYOTA MOTOR MANUFACTURING, TEXAS, INC.
Body	Pickup	Plant	San Antonio, Texas, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/tacoma/2013

4 recalls listed by Transport Canada for this model year

Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

Brakes

2014043 12 Feb 2014

On certain vehicles, a manufacturing defect could affect the functioning of the electric brake actuator, illuminating various warning lights in the instrument panel of the vehicle and disabling the antilock braking system (ABS), traction control and vehicle stability control systems. This could increase the risk of a crash causing injury and/or property damage. Correction: Dealers will update the vehicle stability control ECU software and affect repairs as necessary.

Engine

2013392 7 Nov 2013

On certain vehicles equipped with four-cylinder engines, a manufacturing defect could cause the engine valve springs to break, potentially causing abnormal noise, rough engine performance, and in some cases, a sudden loss of motive power while driving. This could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the valve springs.

Accessories

2013353 10 Oct 2013

On certain vehicles equipped with an optional tonneau cover where the front-most panel can be opened with the vehicle ignition key, the lock cylinder could bind. If the lock cylinder were to bind in the open position, the panel may not remain closed and the tonneau cover assembly could separate from the vehicle while it is being driven. This could potentially result in property damage and pose a hazard to other road users. Correction: Dealers will affect repairs when service parts become available. In the interim, the panel release mechanism will be disabled or the tonneau cover removed, at the owner's choice.

> Listed for the model year, not checked against your VIN. Toyota confirms which apply.
> Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
> www.toyota.ca/en/owners/recalls/

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $21,995[5], $5,770 over the median of $16,225[4].



Lowest ask	$10,500
Middle half	$14,115 – $20,985
Median ask	$16,225
This car	$21,995

Same model year · 6 live listings · as of 29 Nov 2026

OTHER 2013 TOYOTA TACOMA LISTINGS [5]

Halifax, NS · 217,109 km	$17,955
Sherbrooke, QC · 201,059 km	$13,988
Montreal, QC · 247,929 km	$14,495
Thetford Mines, QC · 148,732 km	$25,995
Ottawa, ON · 262,058 km	$10,500

§4 EVENTS

2013	Model year 2013[1] Assembly plant San Antonio, Texas, United States
10 Oct 2013	Transport Canada recall 2013353[2] Issued for the model year · Accessories
7 Nov 2013	Transport Canada recall 2013392[2] Issued for the model year · Engine
12 Feb 2014	Transport Canada recall 2014043[2] Issued for the model year · Brakes

24 Nov 2021	Transport Canada recall 2021723[2] Issued for the model year · Electrical
14 Sep 2026	Listed for sale, Hebbville, NS[5] Bridgewater Mazda · asking $21,995
29 Nov 2026	Listing last updated[5] asking $21,995

§5 DOCUMENTS

Window sticker	We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 6 live listings, as of 29 Nov 2026

[5] Live public dealer listings on Cardog, as of 29 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.