

Register entry, as of 27 October 2026

Listed for sale

Record ID f4ec20d04e1a

# 2023 BMW X4 M40i

3.0 L, 6 cylinders · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER <sup>[1]</sup>**5UX**

WMI 1-3

Bmw Manufacturer Corpor...

**43DT0**

DESCRIPTOR 4-8

X4·3.0 L

**0**

CHECK 9

Verified

**P**

YEAR 10

2023

**9**

PLANT 11

Greer

**P65578**

SERIAL 12-17

Build sequence

## §1 IDENTITY <sup>[1]</sup>

|            |                       |        |                                                     |
|------------|-----------------------|--------|-----------------------------------------------------|
| Model year | 2023                  | Engine | 3.0 L, 6 cylinders                                  |
| Make       | BMW                   | Fuel   | Gasoline                                            |
| Model      | X4                    | Drive  | Not in the decode                                   |
| Trim       | M40i                  | Maker  | BMW MANUFACTURER CORPORATION /<br>BMW NORTH AMERICA |
| Body       | Sport Utility Vehicle | Plant  | Greer, South Carolina, United States                |

## §2 OBLIGATIONS <sup>[2]</sup>

[cardog.app/tools/recalls/bmw/x4/2023](https://cardog.app/tools/recalls/bmw/x4/2023)

### 4 recalls listed by Transport Canada for this model year

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   |         |             |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|-------------|
| Engine                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            | 2026331 | 8 Jul 2026  |
| Issue: On certain vehicles, the engine starter may not have been manufactured properly. As a result, the starter could overheat. Note: This recall is an expansion of Transport Canada recall no. 2026-040. Safety Risk: A starter that overheats can create the risk of a fire. Corrective Actions: To reduce the safety risk, BMW recommends not using the remote start function and not leaving the vehicle unattended with the engine running until the recall repairs have been completed. BMW will notify owners by mail and advise you to take your vehicle to a dealership to replace the engine starter. |         |             |
| Engine                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            | 2026040 | 30 Jan 2026 |
| Issue: On certain vehicles, the engine starter may not have been manufactured properly. As a result, the starter could overheat. Safety Risk: A starter that overheats can create the risk of a fire. Corrective Actions: To reduce the safety risk, BMW recommends not using the remote start function and not leaving the vehicle unattended with the engine running until the recall repairs have been completed. BMW will notify owners by mail and advise you to take your vehicle to a dealership to replace the engine starter.                                                                            |         |             |
| Label                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             | 2024544 | 15 Aug 2024 |
| Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.                                                                                                             |         |             |



## Powertrain

2023646 6 Dec 2023

Issue: On certain vehicles, the integrated transmission control unit (ITCU) may not be sealed properly. As a result, transmission oil could leak into the unit and cause the transmission gears to seize. If this happens, there could be a loss of power to the wheels. Safety Risk: A loss of power to the wheels could increase the risk of a crash. Corrective Actions: BMW will notify owners by mail and advise you to take your vehicle to a dealership to replace the ITCU. The dealer will also inspect the transmission fluid and replace it, if necessary.

Listed for the model year, not checked against your VIN. BMW confirms which apply.

Check your VIN with BMW Canada or call a BMW dealer with your VIN.

[crm.bmw.ca/en-CA/VehicleRecall](http://crm.bmw.ca/en-CA/VehicleRecall)

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

## §3 VALUE [4]

This car asks \$58,998<sup>[5]</sup>, \$746 over the median of \$58,252<sup>[4]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$51,995            |
| Middle half | \$56,545 – \$60,247 |
| Median ask  | \$58,252            |
| This car    | \$58,998            |

Same configuration · 8 live listings · as of 27 Oct 2026

## OTHER 2023 BMW X4 LISTINGS [5]

|                          |          |
|--------------------------|----------|
| Toronto, ON · 37,892 km  | \$63,995 |
| Kingston, ON · 58,086 km | \$45,998 |
| Toronto, ON · 57,963 km  | \$56,895 |
| Toronto, ON · 37,892 km  | \$63,995 |
| Aurora, ON · 57,963 km   | \$56,895 |
| Lévis, QC · 58,164 km    | \$58,995 |

## §4 EVENTS

|             |                                                                                          |
|-------------|------------------------------------------------------------------------------------------|
| 2023        | Model year 2023 <sup>[1]</sup><br>Assembly plant Greer, South Carolina, United States    |
| 6 Dec 2023  | Transport Canada recall 2023646 <sup>[2]</sup><br>Issued for the model year · Powertrain |
| 15 Aug 2024 | Transport Canada recall 2024544 <sup>[2]</sup><br>Issued for the model year · Label      |
| 30 Jan 2026 | Transport Canada recall 2026040 <sup>[2]</sup><br>Issued for the model year · Engine     |
| 8 Jul 2026  | Transport Canada recall 2026331 <sup>[2]</sup><br>Issued for the model year · Engine     |



26 Oct 2026      Listed for sale, Mississauga, ON<sup>[5]</sup>  
Pfaff BMW · asking \$58,998

27 Oct 2026      Listing last updated<sup>[5]</sup>  
asking \$58,998

## §5 DOCUMENTS

Window sticker      We do not collect window stickers for this manufacturer.

## SOURCES

- |                                                                     |                                                                                 |
|---------------------------------------------------------------------|---------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same configuration, 8 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     | [5] Live public dealer listings on Cardog, as of 27 Oct 2026                    |
| [3] NHTSA recall records (United States), listed for the model year |                                                                                 |

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

