Register entry, as of 27 October 2026 Listed for sale Record ID 835e8edbc03d

# 2025 BMW X3 M50

3.0 L, 6 cylinders · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 5UX | 73GP0 | 9 | S | 9 | Z40735 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Bmw Manufacturer Corpor… | X3 · 3.0 L | Verified | 2025 | Greer | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2025 | Engine | 3.0 L, 6 cylinders |
| Make | BMW | Fuel | Gasoline |
| Model | X3 | Drive | Not in the decode |
| Trim | M50 | Maker | BMW MANUFACTURER CORPORATION / BMW NORTH AMERICA |
| Body | Sport Utility Vehicle | Plant | Greer, South Carolina, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/bmw/x3/2025

**4** recalls listed by Transport Canada for this model year

### Steering

2025682 12 Dec 2025

Issue: On certain vehicles, a software problem could cause the steering wheel to move suddenly. Safety Risk: A steering wheel that moves suddenly could increase the risk of a crash and/or injury. Corrective Actions: BMW will notify owners by mail and send a wireless over-the-air software update to eligible vehicles to update the steering system software. Alternatively, you may schedule an appointment to have the update performed at a BMW dealership.

### Electrical

2025168 1 Apr 2025

Issue: On certain vehicles, the power connector for the starter-generator may not have been manufactured properly. As a result, the connection between the connector and the positive battery cable may be loose. If this happens, there could be a loss of power to the wheels and/or the connection could overheat. Safety Risk: A loss of power to the wheels could increase the risk of a crash. Wiring that overheats could increase the risk of a fire. Corrective Actions: BMW will notify owners by mail and advise you to take your vehicle to a dealership. For certain vehicles, the dealer will replace the starter-generator and positive battery cable. For other vehicles, the dealer will inspect and, if necessary, replace the starter-generator and positive battery cable.

### Electrical

2025096 21 Feb 2025

Issue: On certain vehicles, the connection securing the cable from the 48 V battery to the starter-generator may not have been tightened properly. As a result, the connection could loosen and cause a short circuit and/or a loss of power to the wheels. Note: This recall only affects certain vehicles equipped with a 2.0L engine. Safety Risk: A short circuit could increase the risk of a fire. A loss of power to the wheels could increase the risk of a crash. Corrective Actions: BMW will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, tighten the nuts. The dealer will replace the 48 V battery cable and/or the starter-generator, as necessary.

### Label

2024544 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

> Listed for the model year, not checked against your VIN. BMW confirms which apply.
> Check your VIN with BMW Canada or call a BMW dealer with your VIN.
> crm.bmw.ca/en-CA/VehicleRecall

United States: 9 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $73,883[5], $1,984 over the median of $71,899[4].

| | |
|---|---|
| Lowest ask | $67,499 |
| Middle half | $69,595 – $72,395 |
| Median ask | $71,899 |
| This car | $73,883 |

Same configuration · 12 live listings · as of 27 Oct 2026

#### OTHER 2025 BMW X3 LISTINGS [5]

| | |
|---|---|
| Kingston, ON · 44,579 km | $52,995 |
| Niagara Falls, ON · 22,081 km | $69,795 |
| London, ON · 10,141 km | $57,896 |
| Lévis, QC · 36,115 km | $54,995 |
| Lévis, QC · 31,425 km | $54,995 |
| Lévis, QC · 19,365 km | $53,995 |

## §4 EVENTS

| | |
|---|---|
| 2025 | Model year 2025[1]<br>Assembly plant Greer, South Carolina, United States |
| 15 Aug 2024 | Transport Canada recall 2024544[2]<br>Issued for the model year · Label |
| 21 Feb 2025 | Transport Canada recall 2025096[2]<br>Issued for the model year · Electrical |
| 12 Mar 2025 | Listed for sale, Nanaimo, BC[5]<br>BMW Nanaimo · asking $73,883 |
| 1 Apr 2025 | Transport Canada recall 2025168[2]<br>Issued for the model year · Electrical |

| | |
|---|---|
| 12 Dec 2025 | Transport Canada recall 2025682[2]<br>Issued for the model year · Steering |
| 27 Oct 2026 | Listing last updated[5]<br>asking $73,883 |

## §5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 12 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.