Register entry, as of 27 October 2026 Listed for sale Record ID 46500112f67a

# 2023 BMW X5 xDrive40i

3.0 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 5UX | CR6C0 | 5 | P | 9 | R89807 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Bmw Manufacturer Corpor… | X5 · 3.0 L | Verified | 2023 | Greer | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2023 | Engine | 3.0 L, 6 cylinders |
| Make | BMW | Fuel | Gasoline |
| Model | X5 | Drive | AWD |
| Trim | xDrive40i | Maker | BMW MANUFACTURER CORPORATION / BMW NORTH AMERICA |
| Body | Sport Utility Vehicle | Plant | Greer, South Carolina, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/bmw/x5/2023

**3** recalls listed by Transport Canada for this model year

### Label

2024544 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

### Powertrain

2023646 6 Dec 2023

Issue: On certain vehicles, the integrated transmission control unit (ITCU) may not be sealed properly. As a result, transmission oil could leak into the unit and cause the transmission gears to seize. If this happens, there could be a loss of power to the wheels. Safety Risk: A loss of power to the wheels could increase the risk of a crash. Corrective Actions: BMW will notify owners by mail and advise you to take your vehicle to a dealership to replace the ITCU. The dealer will also inspect the transmission fluid and replace it, if necessary.

### Seats and restraints

2023208 6 Apr 2023

Issue: On certain vehicles, incorrect head restraint guide sleeves may have been installed on the second-row outboard seats. As a result, the head restraints may not lock in place and could move in a crash. Safety Risk: Head restraints that move in a crash could increase the risk of an injury. Corrective Actions: BMW will notify owners by mail and instruct you to take your vehicle to a dealership to inspect the second-row outboard seat head restraint guide sleeves, and replace them if necessary. To minimize the safety risk, BMW recommends not to transport people in the second-row outboard seats until the recall repairs are completed.

> Listed for the model year, not checked against your VIN. BMW confirms which apply.
> Check your VIN with BMW Canada or call a BMW dealer with your VIN.
> crm.bmw.ca/en-CA/VehicleRecall

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $49,498[5], $246 under the median of $49,744[4].




| | |
|---|---|
| Lowest ask | $42,999 |
| Middle half | $45,993 – $53,598 |
| Median ask | $49,744 |
| This car | $49,498 |

Same configuration · 28 live listings · as of 27 Oct 2026

### OTHER 2023 BMW X5 LISTINGS [5]

| | |
|---|---|
| Ottawa, ON · 109,338 km | $43,999 |
| Woodbridge, ON · 79,650 km | $69,995 |
| Manotick, ON · 109,338 km | $43,999 |
| London, ON · 54,051 km | $53,419 |
| London, ON · 84,389 km | $49,587 |
| London, ON · 80,733 km | $52,896 |

## §4 EVENTS

| | |
|---|---|
| 2023 | Model year 2023[1]<br>Assembly plant Greer, South Carolina, United States |
| 6 Apr 2023 | Transport Canada recall 2023208[2]<br>Issued for the model year · Seats and restraints |
| 6 Dec 2023 | Transport Canada recall 2023646[2]<br>Issued for the model year · Powertrain |
| 15 Aug 2024 | Transport Canada recall 2024544[2]<br>Issued for the model year · Label |
| 12 Sep 2026 | Listed for sale, Brossard, QC[5]<br>Park Avenue Honda · asking $49,498 |
| 27 Oct 2026 | Listing last updated[5]<br>asking $49,498 |

## §5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

## SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 28 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.