Register entry, as of 27 October 2026 Listed for sale Record ID cdd198929442

# 2019 BMW X5 xDrive40i

3.0 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 5UX | CR6C5 | 4 | K | L | L01710 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Bmw Manufacturer Corpor… | X5 · 3.0 L | Verified | 2019 | United States | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2019 | Engine | 3.0 L, 6 cylinders |
| Make | BMW | Fuel | Gasoline |
| Model | X5 | Drive | AWD |
| Trim | xDrive40i | Maker | BMW MANUFACTURER CORPORATION / BMW NORTH AMERICA |
| Body | Sport Utility Vehicle | Plant | United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/bmw/x5/2019

**12** recalls listed by Transport Canada for this model year

### Lights and instruments

2026285 9 Jun 2026

Issue: Under certain conditions, the windshield wiping system may not meet certain requirements of Canadian regulations. Safety Risk: This small error does not affect safety. Corrective Actions: This is not a recall. BMW has made changes to ensure that all new vehicles meet Canadian regulations.

### Engine

2025514 25 Sep 2025

Issue: On certain vehicles, the recall repairs completed by a BMW dealer during recall 12 83 24RC (Transport Canada recall no. 2024-444) may not be effective. As a result, certain vehicles require a second repair. On certain vehicles, if you try to start the engine repeatedly, the starter could overheat. If this happens, and nearby components contact the starter, it could cause a fire. Safety Risk: A fire can create the risk of injury. Corrective Actions: BMW will notify owners by mail and advise you to take your vehicle to a dealership to replace the engine starter.

### Label

2024544 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

### Electrical

2024444 1 Aug 2024

Issue: On certain vehicles, if you try to start the engine repeatedly, the starter could overheat. If this happens, and nearby components contact the starter, it could cause a fire. Safety Risk: A fire can create the risk of injury. Corrective Actions: BMW will notify owners by mail and advise you to take your vehicle to a dealership to update the vehicle software.

### Structure

2022202 20 Apr 2022

Issue: On certain vehicles, a software problem could allow you to close the sunroof remotely without the key fob inside the vehicle. Canadian regulations require the key fob to be in or near the vehicle when closing the sunroof. Safety Risk: A sunroof that can be closed without the key fob in or near the vehicle could create a risk of injury. Corrective Actions: BMW will notify owners by mail and instruct you to take your vehicle to a dealership to reprogram the roof function control unit. Alternatively, you can download an over-the-air update to fix this problem.

### Visual system

2021078 18 Feb 2021

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear correctly in the central display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that does not display correctly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: BMW will notify owners by mail and instruct you to take your vehicle to a dealer to update the rearview camera software, if necessary.

6 more on the model-year record, cardog.app/tools/recalls/bmw/x5/2019

> Listed for the model year, not checked against your VIN. BMW confirms which apply.
> Check your VIN with BMW Canada or call a BMW dealer with your VIN.
> crm.bmw.ca/en-CA/VehicleRecall

United States: 13 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $36,900[5], $1,952 over the median of $34,948[4].

| | |
|---|---|
| Lowest ask | $28,988 |
| Middle half | $31,871 – $37,995 |
| Median ask | $34,948 |
| This car | $36,900 |

Same configuration · 36 live listings · as of 27 Oct 2026

OTHER 2019 BMW X5 LISTINGS [5]

| | |
|---|---|
| Moose Jaw, SK · 86,960 km | $43,995 |
| Winnipeg, MB · 107,668 km | $32,977 |
| Surrey, BC · 123,000 km | $32,869 |
| North Vancouver, BC · 100,852 km | $34,900 |
| Kelowna, BC · 60,035 km | $39,422 |
| Brossard, QC · 136,342 km | $28,992 |

## §4 EVENTS

2019 Model year 2019[1]
Assembly plant United States

| | |
|---|---|
| 20 Dec 2018 | Transport Canada recall 2018721[2]<br>Issued for the model year · Label |
| 14 Feb 2019 | Transport Canada recall 2019070[2]<br>Issued for the model year · Seats and restraints |
| 24 May 2019 | Transport Canada recall 2019249[2]<br>Issued for the model year · Label |
| 4 Jul 2019 | Transport Canada recall 2019335[2]<br>Issued for the model year · Fuel system |
| 24 Jul 2019 | Transport Canada recall 2019358[2]<br>Issued for the model year · Wheels |
| 1 Oct 2019 | Transport Canada recall 2019480[2]<br>Issued for the model year · Visual system |
| 18 Feb 2021 | Transport Canada recall 2021078[2]<br>Issued for the model year · Visual system |
| 20 Apr 2022 | Transport Canada recall 2022202[2]<br>Issued for the model year · Structure |
| 1 Aug 2024 | Transport Canada recall 2024444[2]<br>Issued for the model year · Electrical |
| 15 Aug 2024 | Transport Canada recall 2024544[2]<br>Issued for the model year · Label |
| 25 Sep 2025 | Transport Canada recall 2025514[2]<br>Issued for the model year · Engine |
| 12 May 2026 | Listed for sale, Vaughan, ON[5]<br>Toronto Auto Brokers · asking $36,900 |
| 9 Jun 2026 | Transport Canada recall 2026285[2]<br>Issued for the model year · Lights and instruments |
| 26 Oct 2026 | Listing last updated[5]<br>asking $36,900 |

## §5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

### SOURCES


[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 36 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.