Register entry, as of 17 November 2026 Listed for sale Record ID eee335a51cad

2018 BMW X5 xDrive35d

3.0 L, 6 cylinders · AWD · Sport Utility Vehicle · Diesel

VEHICLE IDENTIFICATION NUMBER [1]

5UX	KS4C5	4	J	0	Y18090
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Bmw Manufacturer Corpor…	X5 · 3.0 L	Verified	2018	United States	Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	3.0 L, 6 cylinders
Make	BMW	Fuel	Diesel
Model	X5	Drive	AWD
Trim	xDrive35d	Maker	BMW MANUFACTURER CORPORATION / BMW NORTH AMERICA
Body	Sport Utility Vehicle	Plant	United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/bmw/x5/2018

6 recalls listed by Transport Canada for this model year

Label

2024544 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

Engine

2024468 13 Aug 2024

Issue: On certain vehicles, fluid from the positive crankcase ventilation (PCV) system could leak on the intake air hose. As a result, the fluid could enter the electrical connector for the water pump and cause a short circuit. Safety Risk: A short circuit can create the risk of a fire, even while the vehicle is parked and turned off. Corrective Actions: To reduce the safety risk, BMW advises you to park your vehicle outdoors and away from other vehicles or structures until the recall repairs are completed. BMW will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the water pump and electrical connector. The dealer will also install a shield on the connector.

Engine

2021711 19 Nov 2021

Issue: On certain vehicles, the exhaust gas recirculation (EGR) cooler could crack internally and leak. If this happens, you may notice the following symptoms: a warning symbol in the instrument cluster displaying a loss of coolant, reduced engine power, an unpleasant exhaust odour, an unusual noise from the engine and/or smoke from the engine compartment. Note: This recall replaces Transport Canada Recall no. 2018-587. Safety Risk: A cracked EGR cooler could create the risk of an engine fire. Corrective Actions: BMW will notify owners by mail and instruct you to take your vehicle to a dealer to replace the EGR cooler. The dealer will also inspect the intake manifold, and replace it, if necessary.

Fuel system

2021469 29 Jul 2021

Issue: On certain vehicles equipped with a diesel engine, the high-pressure fuel pump may wear prematurely. This can cause reduced engine performance and could lead to a sudden engine stall. Note: A warning lamp on the instrument cluster will turn on if the fuel pressure drops. Safety Risk: A loss of engine power could increase the risk of a crash. Corrective Actions: BMW will notify owners by mail and instruct you to take your vehicle to a dealer to replace the high-pressure fuel pump.

Suspension

2018353 28 Jun 2018

On certain vehicles, the front left lower control arm pivot bolt may not have been properly hardened during the manufacturing process. This could cause the front left lower control arm pivot bolt to break, which could affect vehicle handling and control, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect the front left lower control arm and replace it as necessary.

Suspension

2017568 17 Nov 2017

On certain vehicles, the lower control arm suspension bolts may not have been tightened properly during the manufacturing process. Loose lower control arm suspension bolts could affect vehicle handling, which would increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect the lower control arm suspension bolts and tighten them to specification.

> Listed for the model year, not checked against your VIN. BMW confirms which apply.
> Check your VIN with BMW Canada or call a BMW dealer with your VIN.
> crm.bmw.ca/en-CA/VehicleRecall

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $19,995[5], $2,505 under the median of $22,500[4].



Lowest ask	$17,990
Middle half	$19,997 – $29,300
Median ask	$22,500
This car	$19,995

Same model year · 31 live listings · as of 17 Nov 2026

OTHER 2018 BMW X5 LISTINGS [5]

Calgary, AB · 137,735 km	$24,000
Richmond, BC · 91,235 km	$27,095
Toronto, ON · 157,982 km	$17,999
North York, ON · 114,000 km	$20,900
Acton, ON · 113,507 km	$18,995
Richmond, BC · 99,469 km	$28,800

§4 EVENTS

2018	Model year 2018[1] Assembly plant United States
17 Nov 2017	Transport Canada recall 2017568[2] Issued for the model year · Suspension

28 Jun 2018	Transport Canada recall 2018353[2]	Issued for the model year · Suspension
29 Jul 2021	Transport Canada recall 2021469[2]	Issued for the model year · Fuel system
19 Nov 2021	Transport Canada recall 2021711[2]	Issued for the model year · Engine
13 Aug 2024	Transport Canada recall 2024468[2]	Issued for the model year · Engine
15 Aug 2024	Transport Canada recall 2024544[2]	Issued for the model year · Label
14 Nov 2026	Listed for sale, Sherbrooke, QC[5]	Autos Evasion · asking $19,995

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 31 live listings, as of 17 Nov 2026

[5] Live public dealer listings on Cardog, as of 17 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.