Register entry, as of 28 October 2026 Listed for sale Record ID 1e5300e50d0d

2018 BMW X3 sDrive30i

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5UX	TR9C5	4	J	L	C83311
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Bmw Manufacturer Corpor…	X3 · 2.0 L	Verified	2018	United States	Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	2.0 L, 4 cylinders
Make	BMW	Fuel	Gasoline
Model	X3	Drive	AWD
Trim	sDrive30i	Maker	BMW MANUFACTURER CORPORATION / BMW NORTH AMERICA
Body	Sport Utility Vehicle	Plant	United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/bmw/x3/2018

12 recalls listed by Transport Canada for this model year

Structure

2024609 15 Oct 2024

Issue: On certain vehicles, the recall repairs completed by a BMW dealer during recall 51 84 24RC (Transport Canada recall no. 2024-410) may not be effective. As a result, a second repair is required. On certain vehicles, the cargo area tie down rails could detach in a rear crash. Safety Risk: A cargo rail that detaches in a crash could create a risk of injury to rear passengers. Corrective Actions: BMW will notify owners by mail and advise you to take your vehicle to a dealership to replace the fasteners that secure the cargo rails to the body.

Label

2024544 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

Structure

2024410 17 Jul 2024

Issue: On certain vehicles, the cargo area tie down rails could detach in a rear crash. Safety Risk: A cargo rail that detaches in a crash could create a risk of injury to rear passengers. Corrective Actions: BMW will notify owners by mail and advise you to take your vehicle to a dealership to replace the fasteners that secure the cargo rails to the body.

Airbag

2021419 8 Jul 2021

Issue: On certain vehicles, the seat trim may not be properly attached to the front passenger seat. Over time, this could cause the occupant classification system (OCS) not to work properly. If this happens, the airbag system can turn off the passenger-front airbag even when an adult is sitting in the seat. Safety Risk: In a crash where an airbag is required, an airbag that does not inflate could increase the risk of injury for an adult passenger. Corrective Action: BMW will notify owners by mail and instruct you to make an appointment with a dealer to replace the front passenger seat cushion (including the occupant classification system).

Visual system

2019480 1 Oct 2019

Issue: On certain vehicles, the rearview camera does not return to the default settings when it turns on. This could make the rearview image difficult to see if a driver had previously adjusted the camera display brightness at or near the lowest setting, and contrast at or near the highest setting. Canadian regulations require that the rearview display returns to the default view each time the camera is turned on. Safety Risk: Reduced rear visibility could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to update the software for the rearview camera. Drivers are recommended not to adjust the display brightness at or near the lowest setting, and contrast at or near the highest setting, until this recall is completed.

Seats and restraints

2019373 31 Jul 2019

Issue: On one vehicle, the front passenger seatback frame may not have been properly welded. This could cause the seatback to fail if it is loaded heavily (like in a crash). Safety Risk: A seatback that fails in a crash could create an increased risk of injury. Corrective Actions: The company will notify the owner by mail and instruct them to take their vehicle to a dealer to replace the front passenger seat structure.

6 more on the model-year record, cardog.app/tools/recalls/bmw/x3/2018

> Listed for the model year, not checked against your VIN. BMW confirms which apply.
> Check your VIN with BMW Canada or call a BMW dealer with your VIN.
> crm.bmw.ca/en-CA/VehicleRecall

United States: 11 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $27,480[5], $7,481 over the median of $19,999[4].

Lowest ask	$16,400
Middle half	$18,993 – $21,940
Median ask	$19,999
This car	$27,480

Same configuration · 27 live listings · as of 28 Oct 2026

OTHER 2018 BMW X3 LISTINGS [5]

Vaughan, ON · 94,400 km	$21,995
Sarnia, ON · 77,178 km	$31,999
Ottawa, ON · 122,021 km	$19,588
Calgary, AB · 107,837 km	$23,998
Chilliwack, BC · 113,806 km	$19,998
Calgary, AB · 91,957 km	$26,888

§4 EVENTS

2018	Model year 2018[1] Assembly plant United States
15 Nov 2017	Transport Canada recall 2017561[2] Issued for the model year · Lights and instruments
24 Jan 2018	Transport Canada recall 2018048[2] Issued for the model year · Seats and restraints
7 Mar 2018	Transport Canada recall 2018117[2] Issued for the model year · Structure
7 Jun 2018	Transport Canada recall 2018297[2] Issued for the model year · Steering
22 Jun 2018	Transport Canada recall 2018340[2] Issued for the model year · Lights and instruments
6 Jul 2018	Transport Canada recall 2018366[2] Issued for the model year · Brakes
31 Jul 2019	Transport Canada recall 2019373[2] Issued for the model year · Seats and restraints
1 Oct 2019	Transport Canada recall 2019480[2] Issued for the model year · Visual system
8 Jul 2021	Transport Canada recall 2021419[2] Issued for the model year · Airbag
17 Jul 2024	Transport Canada recall 2024410[2] Issued for the model year · Structure
15 Aug 2024	Transport Canada recall 2024544[2] Issued for the model year · Label
15 Oct 2024	Transport Canada recall 2024609[2] Issued for the model year · Structure
16 Dec 2025	Listed for sale, Oakville, ON[5] Medallion Motors Inc · asking $27,480
27 Oct 2026	Listing last updated[5] asking $27,480

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 27 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.