

Register entry, as of 28 October 2026

Listed for sale

Record ID c312acb6d3d2

2015 BMW X3 xDrive28i

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5UX **WX9C5** **6** **F** **0** **D58649**

WMI 1-3

Bmw Manufacturer Corpor...

DESCRIPTOR 4-8

X3 · 2.0 L

CHECK 9

Verified

YEAR 10

2015

PLANT 11

United States

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	2.0 L, 4 cylinders
Make	BMW	Fuel	Gasoline
Model	X3	Drive	AWD
Trim	xDrive28i	Maker	BMW MANUFACTURER CORPORATION / BMW NORTH AMERICA
Body	Sport Utility Vehicle	Plant	United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/bmw/x3/2015

10 recalls listed by Transport Canada for this model year

Label	2024544	15 Aug 2024
Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.		
Engine	2024468	13 Aug 2024
Issue: On certain vehicles, fluid from the positive crankcase ventilation (PCV) system could leak on the intake air hose. As a result, the fluid could enter the electrical connector for the water pump and cause a short circuit. Safety Risk: A short circuit can create the risk of a fire, even while the vehicle is parked and turned off. Corrective Actions: To reduce the safety risk, BMW advises you to park your vehicle outdoors and away from other vehicles or structures until the recall repairs are completed. BMW will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the water pump and electrical connector. The dealer will also install a shield on the connector.		



Airbag

2024392 3 Jul 2024

Issue: This recall applies to vehicles that may be equipped with a replacement sport or M-sport steering wheel that has a Takata airbag. Long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, may eventually degrade the propellant contained in the driver-front airbag. This could cause the airbag to deploy with more force than normal. If the airbag inflator ruptures, fragments could be propelled toward vehicle occupants or cause damage to the airbag assembly, preventing its proper function. Safety Risk: If the vehicle is involved in a crash requiring an airbag deployment, the airbag inflator could rupture and create a risk of injury. Corrective Actions: BMW will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the driver-front airbag module. To learn if your vehicle is affected by this recall, owners may: • Visit <https://www.bmw.ca/en/ssl/VehicleRecall.html> • Contact your preferred or local BMW Retailer • Call BMW Customer Relations Recall Services at 1-855-217-3002

Engine

2021711 19 Nov 2021

Issue: On certain vehicles, the exhaust gas recirculation (EGR) cooler could crack internally and leak. If this happens, you may notice the following symptoms: a warning symbol in the instrument cluster displaying a loss of coolant, reduced engine power, an unpleasant exhaust odour, an unusual noise from the engine and/or smoke from the engine compartment. Note: This recall replaces Transport Canada Recall no. 2018-587. Safety Risk: A cracked EGR cooler could create the risk of an engine fire. Corrective Actions: BMW will notify owners by mail and instruct you to take your vehicle to a dealer to replace the EGR cooler. The dealer will also inspect the intake manifold, and replace it, if necessary.

Fuel system

2021469 29 Jul 2021

Issue: On certain vehicles equipped with a diesel engine, the high-pressure fuel pump may wear prematurely. This can cause reduced engine performance and could lead to a sudden engine stall. Note: A warning lamp on the instrument cluster will turn on if the fuel pressure drops. Safety Risk: A loss of engine power could increase the risk of a crash. Corrective Actions: BMW will notify owners by mail and instruct you to take your vehicle to a dealer to replace the high-pressure fuel pump.

Engine

2018587 26 Oct 2018

This recall was replaced by Transport Canada Recall No. 2021-711. On certain vehicles, the cooler for Exhaust Gas Recirculation (EGR) module may develop an internal leak and coolant could mix with diesel engine soot/sediment. In rare circumstances, this condition could result in smouldering particles and lead to the melting of the intake manifold, increasing the risk of a fire causing injury and/or damage to property. Correction: Dealers will inspect the EGR cooler, and if necessary, replace it. If it is determined that the EGR cooler has leaked internally, the intake manifold will also be replaced. The EGR pipe connecting the cooler to the manifold will be cleaned. Note: An operator may be alerted to this condition by one or more of the following symptoms: A warning symbol in the instrument cluster displaying a loss of engine coolant, a reduction in engine power, an unpleasant odour (exhaust gas), an unusual noise from the engine compartment, and/or smoke from the engine compartment.

4 more on the model-year record, cardog.app/tools/recalls/bmw/x3/2015

Listed for the model year, not checked against your VIN. BMW confirms which apply.
Check your VIN with BMW Canada or call a BMW dealer with your VIN.
crm.bmw.ca/en-CA/VehicleRecall

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$12,499^[5], \$557 over the median of \$11,942^[4].



Lowest ask	\$7,900
Middle half	\$9,843 – \$12,875
Median ask	\$11,942
This car	\$12,499

Same configuration · 18 live listings · as of 28 Oct 2026



OTHER 2015 BMW X3 LISTINGS ^[5]

Stouffville, ON · 207,710 km	\$8,790
Airdrie, AB · 225,622 km	\$7,900
Lethbridge, AB · 219,207 km	\$13,995
Scarborough, ON · 144,751 km	\$11,888
Calgary, AB · 225,622 km	\$7,900
L'Ancienne-Lorette, QC · 122,124 km	\$12,990

§4 EVENTS

2015	Model year 2015 ^[1] Assembly plant United States
16 Oct 2014	Transport Canada recall 2014459 ^[2] Issued for the model year · Visual system
20 May 2016	Transport Canada recall 2016242 ^[2] Issued for the model year · Seats and restraints
21 Sep 2016	Transport Canada recall 2016461 ^[2] Issued for the model year · Airbag
17 Nov 2016	Transport Canada recall 2016579 ^[2] Issued for the model year · Steering
26 Oct 2018	Transport Canada recall 2018587 ^[2] Issued for the model year · Engine
29 Jul 2021	Transport Canada recall 2021469 ^[2] Issued for the model year · Fuel system
19 Nov 2021	Transport Canada recall 2021711 ^[2] Issued for the model year · Engine
3 Jul 2024	Transport Canada recall 2024392 ^[2] Issued for the model year · Airbag
13 Aug 2024	Transport Canada recall 2024468 ^[2] Issued for the model year · Engine
15 Aug 2024	Transport Canada recall 2024544 ^[2] Issued for the model year · Label
25 Oct 2026	Listed for sale, Oshawa, ON ^[5] Oshawa Fine Auto Sales · asking \$12,499
28 Oct 2026	Listing last updated ^[5] asking \$12,499



§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same configuration, 18 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

