Register entry, as of 29 October 2026 Listed for sale Record ID 659c79d7c195

# 2021 Kia K5 LX

1.6 L, 4 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 5XX | G24J2 | 9 | M | G | 053994 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Kia Georgia, Inc | K5 · 1.6 L | Verified | 2021 | Georgia | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2021 | Engine | 1.6 L, 4 cylinders |
| Make | Kia | Fuel | Gasoline |
| Model | K5 | Drive | Not in the decode |
| Trim | LX | Maker | KIA GEORGIA, INC |
| Body | Sedan | Plant | Georgia, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/kia/k5/2021

**5** recalls listed by Transport Canada for this model year

### Fuel system

2025638 18 Nov 2025

Issue: On certain vehicles, the check valve for the purge control system could wear and cause the fuel tank to expand. As a result, the fuel tank could contact hot components and fuel could leak. Note: This recall only affects certain vehicles equipped with a 1.6 L turbocharged engine. Safety Risk: A fuel leak can create the risk of a fire. Corrective Actions: Kia will notify owners by mail and advise you to take your vehicle to a dealership to replace the check valve and update the electronic control unit (ECU) software. The dealer will also inspect and, if necessary, replace the fuel tank.

### Airbag

2023124 8 Mar 2023

Issue: On certain vehicles, the side curtain airbag(s) may not have been installed correctly. As a result, the side curtain airbag(s) may not inflate properly in a crash. Safety Risk: A side curtain airbag that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Kia will notify owners by mail and instruct you to take your vehicle to a dealership to inspect the installation of the side curtain airbags, and reinstall them correctly if necessary.

### Powertrain

2022580 12 Oct 2022

Issue: On certain vehicles, a fault in the transmission oil pump can cause the vehicle to enter "fail-safe mode". When this happens, a programming error can cause a sudden loss of power to the wheels after 20-30 seconds. Note: This recall only affects vehicles equipped with a 2.5 L turbo gasoline (T-GDI) engine and an 8-speed dual-clutch transmission (DCT). Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. Corrective Actions: Kia will notify owners by mail and instruct you to take your vehicle to a dealership to inspect and, if necessary, replace the transmission. The dealer will also update the transmission control unit software.

### Fuel system

2021421 9 Jul 2021

Issue: On certain vehicles, the connection between the high-pressure fuel pipe and fuel pump may not be properly sealed. As a result, a fuel leak could occur. Safety Risk: A fuel leak can create the risk of a fire. Corrective Action: KIA will notify owners by mail and instruct you to bring your vehicle to a dealer to inspect and replace the high-pressure fuel pipe, as required.

### Steering

2021374 15 Jun 2021

Issue: Under certain driving conditions, a fault in the power steering system could cause reduced power assist when the lane following assist (LFA) system is used. This can cause a sudden change in steering feel and an increase in steering effort. Note: This problem only affects certain models equipped with a 2.5 L T-GDI engine. Safety Risk: A sudden change in steering effort could increase the risk of a crash. Corrective Action: Kia Canada will notify owners by mail and instruct you to bring your vehicle to a dealer to update the motor driven power steering system (MDPS) software.

Listed for the model year, not checked against your VIN. Kia confirms which apply.
Check your VIN with Kia Canada or call a Kia dealer with your VIN.
www.kia.ca/en/owners/recalls

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $24,995[5], $5,009 over the median of $19,986[4].

| | |
|---|---|
| Lowest ask | $16,349 |
| Middle half | $17,995 – $21,649 |
| Median ask | $19,986 |
| This car | $24,995 |

Same model year · 12 live listings · as of 29 Oct 2026

### OTHER 2021 KIA K5 LISTINGS [5]

| | |
|---|---|
| Québec, QC · 95,912 km | $19,977 |
| Blainville, QC · 100,384 km | $17,987 |
| Kitchener, ON · 109,363 km | $20,977 |
| London, ON · 109,363 km | $20,977 |
| Kentville, NS · 107,617 km | $18,900 |
| Québec, QC · 95,912 km | $19,977 |

## §4 EVENTS

| | |
|---|---|
| 2021 | Model year 2021[1]<br>Assembly plant Georgia, United States |
| 15 Jun 2021 | Transport Canada recall 2021374[2]<br>Issued for the model year · Steering |
| 9 Jul 2021 | Transport Canada recall 2021421[2]<br>Issued for the model year · Fuel system |

| | |
|---|---|
| 12 Oct 2022 | Transport Canada recall 2022580[2]<br>Issued for the model year · Powertrain |
| 8 Mar 2023 | Transport Canada recall 2023124[2]<br>Issued for the model year · Airbag |
| 18 Nov 2025 | Transport Canada recall 2025638[2]<br>Issued for the model year · Fuel system |
| 28 Oct 2026 | Listed for sale, Longueuil, QC[5]<br>Les Specialistes du Financement · asking $24,995 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

### SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 12 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.