Register entry, as of 27 October 2026 Listed for sale Record ID fd5bb2a24b23

2018 Kia Optima SXL

2.0 L, 4 cylinders · FWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5XX	GV4L2	6	J	G	192187
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Kia Georgia, Inc	Optima · 2.0 L	Verified	2018	Georgia	Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	2.0 L, 4 cylinders
Make	Kia	Fuel	Gasoline
Model	Optima	Drive	FWD
Trim	SXL	Maker	KIA GEORGIA, INC
Body	Sedan	Plant	Georgia, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/kia/optima/2018

5 recalls listed by Transport Canada for this model year

Structure

2023476 28 Aug 2023

Issue: On certain vehicles, a part in the trunk release latch could fail. If this happens, the emergency trunk release located inside the trunk compartment may not work properly. This could prevent a person that is trapped inside the trunk from opening it. Safety Risk: If a person is closed inside the trunk compartment, they may not be able to get out. This could create a risk of injury. Corrective Actions: Kia will notify owners by mail and advise you to take your vehicle to a dealership to replace the trunk latch base subassembly.

Engine

2021666 1 Nov 2021

Issue: On certain vehicles equipped with a 2.0 L Nu GDI engine, the connecting rod bearings can become damaged. If this happens, the engine could make abnormal knocking noises and/or the oil pressure warning light may turn on. If you continue to drive the vehicle with these symptoms, the engine could fail and/or a fire could occur. An engine failure can cause a sudden loss of power with an inability to restart. Note: Only the Optima Hybrid and Plug-In Hybrid (PHEV) models are affected by this recall. Safety Risk: A sudden loss of engine power could increase the risk of a crash. An engine failure could also create the risk of a fire. Corrective Actions: Kia will notify owners by mail and instruct you to take your vehicle to a dealer for an engine inspection test, to determine if there is bearing damage. If damage is found, the engine will be replaced. Dealers will also install a knock sensor detection system (KSDS) software that will prevent engine damage from potential excessive connecting rod bearing wear. Note: Kia recommends that you should always follow the correct vehicle maintenance schedule, which is printed in the Owner's Manual. If you experience unusual engine noise, reduced power, or a check engine/oil warning light, Kia advises you to immediately visit a Kia dealership to have your vehicle diagnosed.

Engine

2019143 18 Mar 2019

Issue: Kia Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure may cause a sudden loss of power with an inability to restart. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to update the software for the engine control module. Note: Vehicles repaired under Service Campaign SC023 already have this software update.

Fuel system

2019098 27 Feb 2019

Issue: When the engine was replaced under warranty or under Kia's Product Improvement Campaign SC023, the high pressure fuel pipe may not have been properly installed on the fuel pump outlet. A fuel leak could occur if the pipe was damaged, misaligned or improperly torqued during the recall repair. Safety Risk: Leaking fuel in the presence of an ignition source could increase the risk of a fire. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer for an inspection. If fuel leakage is detected, the fuel pipe will be replaced with a new one.

Powertrain

2018132 15 Mar 2018

On certain plug-in hybrid vehicles, the battery Voltage Protection Device (VPD) switch could inadvertently activate. If the VPD switch is activated, electricity to the vehicle's electric motor may be disconnected. If this occurs while the vehicle is driven under Electric Vehicle (EV) mode, the vehicle may experience a loss of motive power, which could increase the risk of a crash causing injury and/or property damage. Correction: Dealers will remove the current VPD switch and install two newly designed battery management systems containing new overvoltage protection devices. The corresponding wiring harness will also be installed. Note: This condition would result in the of the “Check Hybrid System" warning light illuminating.

Listed for the model year, not checked against your VIN. Kia confirms which apply.
Check your VIN with Kia Canada or call a Kia dealer with your VIN.
www.kia.ca/en/owners/recalls

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $11,950[5], $1,045 under the median of $12,995[4].

Lowest ask	$6,900
Middle half	$8,905 – $13,999
Median ask	$12,995
This car	$11,950

Same model year · 13 live listings · as of 27 Oct 2026

OTHER 2018 KIA OPTIMA LISTINGS [5]

Val-David, QC · 116,873 km	$12,997
Red Deer, AB · 197,000 km	$8,905
Warman, SK · 124,466 km	$12,995
Calgary, AB · 144,673 km	$14,998
Airdrie, AB · 199,021 km	$6,900
Sherbrooke, QC · 224,924 km	$8,485

§4 EVENTS

2018	Model year 2018[1] Assembly plant Georgia, United States
15 Mar 2018	Transport Canada recall 2018132[2] Issued for the model year · Powertrain
27 Feb 2019	Transport Canada recall 2019098[2] Issued for the model year · Fuel system
18 Mar 2019	Transport Canada recall 2019143[2] Issued for the model year · Engine
1 Nov 2021	Transport Canada recall 2021666[2] Issued for the model year · Engine
28 Aug 2023	Transport Canada recall 2023476[2] Issued for the model year · Structure
26 Oct 2026	Listed for sale, Quebec, QC[5] autojeanvezina.com · asking $11,950
27 Oct 2026	Listing last updated[5] asking $11,950

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 13 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.