Register entry, as of 27 October 2026 Listed for sale Record ID c456fea26186

# 2015 Kia Sorento Base/ LX

3.3 L, 6 cylinders · 4x2 · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 5XY | KT4A7 | 2 | F | G | 635372 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Kia Georgia, Inc | Sorento · 3.3 L | Verified | 2015 | Georgia | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2015 | Engine | 3.3 L, 6 cylinders |
| Make | Kia | Fuel | Gasoline |
| Model | Sorento | Drive | 4x2 |
| Trim | Base/ LX | Maker | KIA GEORGIA, INC |
| Body | Sport Utility Vehicle | Plant | Georgia, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/kia/sorento/2015

**5** recalls listed by Transport Canada for this model year

### Label

2024549 15 Aug 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Kia has corrected the compliance label for all new vehicles.

### Brakes

2021278 12 May 2021

Issue: On certain vehicles, brake fluid can enter the brake Hydraulic Electronic Control Unit (HECU) and cause a short circuit. Note: This recall replaces RC138 (Transport Canada recall 2020-405). Vehicles that were repaired under that recall also require this repair. Safety Risk: A short circuit could create a fire risk. Corrective Actions: Kia will notify owners by mail and instruct you to take your vehicle to a dealer to have the HECU inspected and replaced if necessary. The dealer will also replace the ABS multi-fuse. Kia recommends that you should park your vehicle outdoors, and away from other vehicles or structures until the recall repairs have been completed.

### Brakes

2020405 31 Aug 2020

This recall was replaced by Transport Canada Recall No. 2021-278. Issue: On certain vehicles, brake fluid can enter the brake Hydraulic Electronic Control Unit (HECU) and cause a short circuit. Note: This problem may cause the ABS warning light to turn on. Safety Risk: A short circuit could create a fire risk. Corrective Actions: Kia will notify owners by mail and instruct you to take your vehicle to a dealer for an inspection. If there is a brake fluid leak in the HECU, it will be replaced. Kia recommends that you should park your vehicle outdoors, and away from other vehicles or structures until the recall repairs have been completed.

### Engine

2019143 18 Mar 2019

Issue: Kia Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure may cause a sudden loss of power with an inability to restart. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to update the software for the engine control module. Note: Vehicles repaired under Service Campaign SC023 already have this software update.

### Fuel system

2019098 27 Feb 2019

Issue: When the engine was replaced under warranty or under Kia's Product Improvement Campaign SC023, the high pressure fuel pipe may not have been properly installed on the fuel pump outlet. A fuel leak could occur if the pipe was damaged, misaligned or improperly torqued during the recall repair. Safety Risk: Leaking fuel in the presence of an ignition source could increase the risk of a fire. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer for an inspection. If fuel leakage is detected, the fuel pipe will be replaced with a new one.

> Listed for the model year, not checked against your VIN. Kia confirms which apply.
> Check your VIN with Kia Canada or call a Kia dealer with your VIN.
> www.kia.ca/en/owners/recalls

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $6,344[5], $3,630 under the median of $9,974[4].

| | |
|---|---|
| Lowest ask | $4,520 |
| Middle half | $7,234 – $11,873 |
| Median ask | $9,974 |
| This car | $6,344 |

Same model year · 30 live listings · as of 27 Oct 2026

#### OTHER 2015 KIA SORENTO LISTINGS [5]

| | |
|---|---|
| Québec, QC · 142,594 km | $12,107 |
| Québec, QC · 142,594 km | $12,107 |
| Prince Albert, SK · 125,171 km | $12,989 |
| Sarnia, ON · 130,461 km | $15,989 |
| Ottawa, ON · 151,468 km | $10,998 |
| Sault Ste Marie, ON · 165,631 km | $6,994 |

## §4 EVENTS

| | |
|---|---|
| 2015 | Model year 2015[1]<br>Assembly plant Georgia, United States |
| 27 Feb 2019 | Transport Canada recall 2019098[2]<br>Issued for the model year · Fuel system |
| 18 Mar 2019 | Transport Canada recall 2019143[2]<br>Issued for the model year · Engine |

| | |
|---|---|
| 31 Aug 2020 | Transport Canada recall 2020405[2]<br>Issued for the model year · Brakes |
| 12 May 2021 | Transport Canada recall 2021278[2]<br>Issued for the model year · Brakes |
| 15 Aug 2024 | Transport Canada recall 2024549[2]<br>Issued for the model year · Label |
| 26 Oct 2026 | Listed for sale, Longueuil, QC[5]<br>Longueuil Kia · asking $6,344 |
| 27 Oct 2026 | Listing last updated[5]<br>asking $6,344 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

### SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 30 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.