Register entry, as of 28 October 2026 Listed for sale Record ID ef8a53e4f984

2014 Kia Sorento SX

3.3 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5XY	KWDA7	4	E	G	482225
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Kia Georgia, Inc	Sorento · 3.3 L	Verified	2014	Georgia	Build sequence

§1 IDENTITY [1]

Model year	2014	Engine	3.3 L, 6 cylinders
Make	Kia	Fuel	Gasoline
Model	Sorento	Drive	4WD
Trim	SX	Maker	KIA GEORGIA, INC
Body	Sport Utility Vehicle	Plant	Georgia, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/kia/sorento/2014

8 recalls listed by Transport Canada for this model year

Label — 2024549 — 15 Aug 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Kia has corrected the compliance label for all new vehicles.

Brakes — 2023529 — 26 Sep 2023

Issue: On certain vehicles, the brake hydraulic electronic control unit (HECU) could short circuit. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Kia will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuse(s) for the HECU. Kia recommends that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.

Brakes — 2021278 — 12 May 2021

Issue: On certain vehicles, brake fluid can enter the brake Hydraulic Electronic Control Unit (HECU) and cause a short circuit. Note: This recall replaces RC138 (Transport Canada recall 2020-405). Vehicles that were repaired under that recall also require this repair. Safety Risk: A short circuit could create a fire risk. Corrective Actions: Kia will notify owners by mail and instruct you to take your vehicle to a dealer to have the HECU inspected and replaced if necessary. The dealer will also replace the ABS multi-fuse. Kia recommends that you should park your vehicle outdoors, and away from other vehicles or structures until the recall repairs have been completed.

Brakes

2020405 31 Aug 2020

This recall was replaced by Transport Canada Recall No. 2021-278. Issue: On certain vehicles, brake fluid can enter the brake Hydraulic Electronic Control Unit (HECU) and cause a short circuit. Note: This problem may cause the ABS warning light to turn on. Safety Risk: A short circuit could create a fire risk. Corrective Actions: Kia will notify owners by mail and instruct you to take your vehicle to a dealer for an inspection. If there is a brake fluid leak in the HECU, it will be replaced. Kia recommends that you should park your vehicle outdoors, and away from other vehicles or structures until the recall repairs have been completed.

Engine

2019153 21 Mar 2019

Issue: Kia Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure may cause a sudden loss of power with an inability to restart. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to update the software for the engine control module. Note: Vehicles repaired under Service Campaign SC025 already have this software update.

Fuel system

2018742 28 Dec 2018

On certain vehicles, when repairs were completed under recall campaign 2017-199 (Kia RC109), the high pressure fuel pipe may not have been properly installed on the fuel pump outlet. A fuel leak could occur if the pipe was damaged, misaligned or improperly torqued during the recall repair. A fuel leak, in the presence of an ignition source, could create the risk of a fire causing injury and/or damage to property. Correction: Dealers will inspect the connections of the high pressure fuel pipe to the fuel pump outlet for leaking fuel. If leaking fuel is detected, the fuel pipe will be replaced with a new one.

2 more on the model-year record, cardog.app/tools/recalls/kia/sorento/2014

> Listed for the model year, not checked against your VIN. Kia confirms which apply.
> Check your VIN with Kia Canada or call a Kia dealer with your VIN.
> www.kia.ca/en/owners/recalls

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $9,779[5], $2,125 over the median of $7,654[4].



Lowest ask	$3,895
Middle half	$6,870 – $10,984
Median ask	$7,654
This car	$9,779

Same model year · 20 live listings · as of 28 Oct 2026

OTHER 2014 KIA SORENTO LISTINGS [5]

Chilliwack, BC · 145,691 km	$12,999
Chilliwack, BC · 145,691 km	$12,999
Sherwood Park, AB · 150,514 km	$10,980
Sherwood Park, AB · 150,514 km	$10,980
Trois-Rivières, QC · 187,400 km	$6,995
Edmonton, AB · 150,514 km	$10,980

§4 EVENTS

2014	Model year 2014[1] Assembly plant Georgia, United States
9 Aug 2013	Transport Canada recall 2013277[2] Issued for the model year · Powertrain
7 Apr 2017	Transport Canada recall 2017199[2] Issued for the model year · Engine
28 Dec 2018	Transport Canada recall 2018742[2] Issued for the model year · Fuel system
21 Mar 2019	Transport Canada recall 2019153[2] Issued for the model year · Engine
31 Aug 2020	Transport Canada recall 2020405[2] Issued for the model year · Brakes
12 May 2021	Transport Canada recall 2021278[2] Issued for the model year · Brakes
26 Sep 2023	Transport Canada recall 2023529[2] Issued for the model year · Brakes
15 Aug 2024	Transport Canada recall 2024549[2] Issued for the model year · Label
5 Nov 2025	Listed for sale, Calgary, AB[5] Fine Auto Zone · asking $9,779
24 Oct 2026	Listing last updated[5] asking $9,779

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 20 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.