Register entry, as of 29 October 2026 Listed for sale Record ID 2302e7ae1ab5

2024 Kia Telluride SX, SX X-LINE / X-PRO / PRESTIGE / PRESTIGE X-LINE / PRESTIGE X-PRO

3.8 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5XY	P5DGC	8	R	G	433869
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Kia Georgia, Inc	Telluride · 3.8 L	Verified	2024	West Point	Build sequence

§1 IDENTITY [1]

Model year	2024	Engine	3.8 L, 6 cylinders
Make	Kia	Fuel	Gasoline
Model	Telluride	Drive	4WD
Trim	SX, SX X-LINE / X-PRO / PRESTIGE / PRESTIGE X-LINE / PRESTIGE X-PRO	Maker	KIA GEORGIA, INC
Body	Sport Utility Vehicle	Plant	West Point, Georgia, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/kia/telluride/2024

6 recalls listed by Transport Canada for this model year

Electrical

2026327 3 Jul 2026

Issue: On certain vehicles, the recall repairs completed by a Kia dealer during service campaign RC207 (Transport Canada recall number 2024-323) may not have been done correctly. As a result, a second repair is required. Under certain conditions, the switch for the driver- and/or passenger-front power seat motor(s) could become stuck and cause the seat motor(s) not to stop. If this happens, the motor(s) could overheat. Safety Risk: A seat motor that overheats can create a fire risk, even while the vehicle is parked and turned off. Corrective actions: To reduce the safety risk, Kia advises that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed. Kia will notify owners by mail and advise you to take your vehicle to a dealership to install an electronic fuse for the power seats.

Structure

2025400 30 Jul 2025

Issue: On certain vehicles, the exterior trim piece below the window on each door may not be properly attached. As a result, the face plate could loosen from the exterior trim pieces and separate from the vehicle. Safety Risk: Parts that detach from the vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: Kia will notify owners by mail and advise you to take your vehicle to a dealership to replace the exterior trim piece below the window on each door.

Label

2024549 15 Aug 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Kia has corrected the compliance label for all new vehicles.

Electrical

2024323 6 Jun 2024

Issue: Under certain conditions, the switch for the driver- and/or passenger-front power seat motor(s) could become stuck and cause the seat motor(s) not to stop. If this happens, the motor(s) could overheat. Safety Risk: A seat motor that overheats can create a fire risk, even while the vehicle is parked and turned off. Corrective actions: Kia advises that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed. Kia will notify owners by mail and advise you to take your vehicle to a dealership to install a bracket for the power seat switch cover(s). The dealer will also replace the seat adjustment knob(s).

Powertrain

2024187 22 Mar 2024

Issue: On certain vehicles, the axle shaft(s) may not have been manufactured properly. As a result, the axle shaft(s) splines could become damaged. If this happens, the vehicle could move when it's parked and the parking brake isn't applied. Safety Risk: A parked vehicle that moves suddenly could create the risk of an injury or a crash. Corrective Actions: Kia will notify owners by mail and advise you to take your vehicle to a dealership to update the electronic parking brake software. To reduce the safety risk, Kia recommends that you should always use the parking brake when you park.

Powertrain

2024072 8 Feb 2024

Issue: On certain vehicles, the engine valve springs could break. As a result, the engine could fail and oil could leak onto hot components in the engine compartment. Safety Risk: An engine failure can cause a sudden loss of power to the wheels and could increase the risk of a crash. Additionally, oil that leaks onto hot components can create the risk of a fire. Corrective Actions: Kia will notify owners by mail and advise you to take your vehicle to a dealership to replace the engine.

> Listed for the model year, not checked against your VIN. Kia confirms which apply.
> Check your VIN with Kia Canada or call a Kia dealer with your VIN.
> www.kia.ca/en/owners/recalls

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $44,999[5], $1,996 under the median of $46,995[4].



Lowest ask	$37,986
Middle half	$44,888 – $49,985
Median ask	$46,995
This car	$44,999

Same configuration · 57 live listings · as of 29 Oct 2026

OTHER 2024 KIA TELLURIDE LISTINGS [5]

Kelowna, BC · 80,730 km	$48,999
Mission, BC · 75,239 km	$43,888
Edmonton, AB · 114,970 km	$45,988
Winnipeg, MB · 53,297 km	$42,283
Winnipeg, MB · 114,970 km	$45,988
Regina, SK · 53,297 km	$42,283

§4 EVENTS

2024	Model year 2024[1] Assembly plant West Point, Georgia, United States
8 Feb 2024	Transport Canada recall 2024072[2] Issued for the model year · Powertrain
22 Mar 2024	Transport Canada recall 2024187[2] Issued for the model year · Powertrain
6 Jun 2024	Transport Canada recall 2024323[2] Issued for the model year · Electrical
15 Aug 2024	Transport Canada recall 2024549[2] Issued for the model year · Label
30 Jul 2025	Transport Canada recall 2025400[2] Issued for the model year · Structure
3 Jul 2026	Transport Canada recall 2026327[2] Issued for the model year · Electrical
26 Oct 2026	Listed for sale, Sarnia, ON[5] Lambton Kia · asking $44,999
28 Oct 2026	Listing last updated[5] asking $44,999

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 57 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.