Register entry, as of 27 October 2026 Listed for sale Record ID 880f8d181ce6

2020 Kia Telluride SX

3.8 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5XY	P5DHC	9	L	G	005895
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Kia Georgia, Inc	Telluride · 3.8 L	Verified	2020	Georgia	Build sequence

§1 IDENTITY [1]

Model year	2020	Engine	3.8 L, 6 cylinders
Make	Kia	Fuel	Gasoline
Model	Telluride	Drive	4WD
Trim	SX	Maker	KIA GEORGIA, INC
Body	Sport Utility Vehicle	Plant	Georgia, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/kia/telluride/2020

8 recalls listed by Transport Canada for this model year

Electrical — 2026327 — 3 Jul 2026

Issue: On certain vehicles, the recall repairs completed by a Kia dealer during service campaign RC207 (Transport Canada recall number 2024-323) may not have been done correctly. As a result, a second repair is required. Under certain conditions, the switch for the driver- and/or passenger-front power seat motor(s) could become stuck and cause the seat motor(s) not to stop. If this happens, the motor(s) could overheat. Safety Risk: A seat motor that overheats can create a fire risk, even while the vehicle is parked and turned off. Corrective actions: To reduce the safety risk, Kia advises that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed. Kia will notify owners by mail and advise you to take your vehicle to a dealership to install an electronic fuse for the power seats.

Label — 2024549 — 15 Aug 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Kia has corrected the compliance label for all new vehicles.

Electrical — 2024323 — 6 Jun 2024

Issue: Under certain conditions, the switch for the driver- and/or passenger-front power seat motor(s) could become stuck and cause the seat motor(s) not to stop. If this happens, the motor(s) could overheat. Safety Risk: A seat motor that overheats can create a fire risk, even while the vehicle is parked and turned off. Corrective actions: Kia advises that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed. Kia will notify owners by mail and advise you to take your vehicle to a dealership to install a bracket for the power seat switch cover(s). The dealer will also replace the seat adjustment knob(s).

Powertrain

2024187 22 Mar 2024

Issue: On certain vehicles, the axle shaft(s) may not have been manufactured properly. As a result, the axle shaft(s) splines could become damaged. If this happens, the vehicle could move when it's parked and the parking brake isn't applied. Safety Risk: A parked vehicle that moves suddenly could create the risk of an injury or a crash. Corrective Actions: Kia will notify owners by mail and advise you to take your vehicle to a dealership to update the electronic parking brake software. To reduce the safety risk, Kia recommends that you should always use the parking brake when you park.

Accessories

2022468 16 Aug 2022

Issue: Certain vehicles may be equipped with a 4-pin accessory trailer wiring harness kit that could fail. Over time, this could result in a short circuit that can cause the control module to overheat. Note: This recall only affects Kia Genuine 4-pin tow hitch wiring harness kits with the part number S9F67AC000. These kits may have been ordered at the time of a vehicle purchase, or purchased separately from a dealer as an aftermarket accessory. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Kia will notify owners by mail and instruct you to inspect if your vehicle has a trailer wiring harness installed. If it does, Kia advises that you should park your vehicle outdoors, and away from other vehicles or structures until the recall repairs have been completed. The corrective actions for this recall are under development. As an interim repair, Kia will advise you to make an appointment at your local dealership to replace the 30 A "TRAILER" fuse with a 15 A fuse.

Lights and instruments

2020351 30 Jul 2020

Issue: While towing a trailer, the trailer brake lights do not turn on when the Smart Cruise Control (SCC) slows the vehicle. Note: The vehicle's brake lights continue to function normally. Safety Risk: Brake lights that do not work could cause a following driver not to recognize that a vehicle ahead is braking. This could increase the risk of a crash. Corrective Actions: Kia will notify owners by mail and instruct you to take your vehicle to a dealer to install an additional wire harness to the main fuse box.

2 more on the model-year record, cardog.app/tools/recalls/kia/telluride/2020

> Listed for the model year, not checked against your VIN. Kia confirms which apply.
> Check your VIN with Kia Canada or call a Kia dealer with your VIN.
> www.kia.ca/en/owners/recalls

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $24,900[5], $2,095 under the median of $26,995[4].

Lowest ask	$15,995
Middle half	$24,879 – $27,900
Median ask	$26,995
This car	$24,900

Same configuration · 21 live listings · as of 27 Oct 2026

OTHER 2020 KIA TELLURIDE LISTINGS [5]

Stettler, AB · 172,577 km	$24,995
Lethbridge, AB · 112,680 km	$28,998
Edmonton, AB · 125,800 km	$26,997
Vaudreuil-Dorion, QC · 90,011 km	$26,252
Winnipeg, MB · 62,751 km	$33,749
Campbell River, BC · 108,764 km	$28,995

§4 EVENTS

2020	Model year 2020[1] Assembly plant Georgia, United States
10 Jun 2019	Transport Canada recall 2019278[2] Issued for the model year · Label
20 Aug 2019	Transport Canada recall 2019416[2] Issued for the model year · Seats and restraints
30 Jul 2020	Transport Canada recall 2020351[2] Issued for the model year · Lights and instruments
16 Aug 2022	Transport Canada recall 2022468[2] Issued for the model year · Accessories
22 Mar 2024	Transport Canada recall 2024187[2] Issued for the model year · Powertrain
6 Jun 2024	Transport Canada recall 2024323[2] Issued for the model year · Electrical
15 Aug 2024	Transport Canada recall 2024549[2] Issued for the model year · Label
3 Jul 2026	Transport Canada recall 2026327[2] Issued for the model year · Electrical
26 Oct 2026	Listed for sale, Ottawa, ON[5] CarCity · asking $24,900
27 Oct 2026	Listing last updated[5] asking $24,900

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 21 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.