Register entry, as of 28 October 2026 Listed for sale Record ID d7148827e945

2016 Kia Sorento L / LX

2.4 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5XY	PGDA3	5	G	G	176105
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Kia Georgia, Inc	Sorento · 2.4 L	Verified	2016	Georgia	Build sequence

§1 IDENTITY [1]

Model year	2016	Engine	2.4 L, 4 cylinders
Make	Kia	Fuel	Gasoline
Model	Sorento	Drive	4WD
Trim	L / LX	Maker	KIA GEORGIA, INC
Body	Sport Utility Vehicle	Plant	Georgia, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/kia/sorento/2016

8 recalls listed by Transport Canada for this model year

Label

2024549 15 Aug 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Kia has corrected the compliance label for all new vehicles.

Lights and instruments

2023449 11 Aug 2023

Issue: On certain vehicles, wear inside the multi-function switch could cause the headlights to turn off suddenly when the switch is in the AUTO mode. Safety Risk: A loss of headlights would reduce visibility and could increase the risk of a crash. Corrective Actions: Kia will notify owners by mail and advise you to take your vehicle to a dealership to replace certain parts in the multi-function switch. To reduce the safety risk, Kia recommends not to use the AUTO mode until the recall repairs have been completed.

Powertrain

2022453 10 Aug 2022

Issue: On certain vehicles, a problem with the transmission shifter assembly may allow you to shift out of the Park position (P) without pressing the brake pedal. If the transmission is shifted without applying the brakes and the parking brake isn't used, the vehicle could move suddenly or roll away. Safety Risk: A vehicle that moves suddenly or that rolls away could create the risk of an injury or a crash. Corrective Actions: Kia will notify owners by mail and instruct you to take your vehicle to a dealership to inspect the shift lever assembly. The shift lock lever and holder will be replaced, if necessary. To reduce the safety risk, Kia recommends that you should always use the parking brake when you park.

Electrical

2021680 5 Nov 2021

Issue: Certain vehicles may be equipped with an accessory trailer wiring harness that could fail. Over time, water could leak into the control module and cause a short circuit. If this happens, there could be loss of the trailer lights. Note: This recall affects trailer wiring harness kits that may have been ordered at the time of a vehicle purchase, or purchased separately from a dealer as an aftermarket accessory. Safety Risk: A loss of trailer lights could make the trailer less visible. In addition, other drivers may not recognize that the vehicle ahead is braking or intends to turn. This could increase the risk of a crash. Corrective Actions: Kia will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the trailer wiring harness. If the harness is from the lot (batch) affected by this problem, the dealer will replace it. Kia recommends that you should always check to ensure that trailer lights work properly before towing.

Engine

2019143 18 Mar 2019

Issue: Kia Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure may cause a sudden loss of power with an inability to restart. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to update the software for the engine control module. Note: Vehicles repaired under Service Campaign SC023 already have this software update.

Fuel system

2019098 27 Feb 2019

Issue: When the engine was replaced under warranty or under Kia's Product Improvement Campaign SC023, the high pressure fuel pipe may not have been properly installed on the fuel pump outlet. A fuel leak could occur if the pipe was damaged, misaligned or improperly torqued during the recall repair. Safety Risk: Leaking fuel in the presence of an ignition source could increase the risk of a fire. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer for an inspection. If fuel leakage is detected, the fuel pipe will be replaced with a new one.

2 more on the model-year record, cardog.app/tools/recalls/kia/sorento/2016

> Listed for the model year, not checked against your VIN. Kia confirms which apply.
> Check your VIN with Kia Canada or call a Kia dealer with your VIN.
> www.kia.ca/en/owners/recalls

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $5,495[5], $4,500 under the median of $9,995[4].

Lowest ask	$4,999
Middle half	$8,995 – $12,999
Median ask	$9,995
This car	$5,495

Same configuration · 9 live listings · as of 28 Oct 2026

OTHER 2016 KIA SORENTO LISTINGS [5]

Ottawa, ON · 170,550 km	$8,988
Whitby, ON · 97,821 km	$12,595
Thetford-Mines, QC · 148,437 km	$10,995
London, ON · 131,376 km	$25,001
Lévis, QC · 136,400 km	$9,594
Lévis, QC · 117,600 km	$10,994

§4 EVENTS

2016	Model year 2016[1] Assembly plant Georgia, United States
5 Jul 2016	Transport Canada recall 2016346[2] Issued for the model year · Structure
1 Nov 2016	Transport Canada recall 2016540[2] Issued for the model year · Seats and restraints
27 Feb 2019	Transport Canada recall 2019098[2] Issued for the model year · Fuel system
18 Mar 2019	Transport Canada recall 2019143[2] Issued for the model year · Engine
5 Nov 2021	Transport Canada recall 2021680[2] Issued for the model year · Electrical
10 Aug 2022	Transport Canada recall 2022453[2] Issued for the model year · Powertrain
11 Aug 2023	Transport Canada recall 2023449[2] Issued for the model year · Lights and instruments
15 Aug 2024	Transport Canada recall 2024549[2] Issued for the model year · Label
25 Oct 2026	Listed for sale, Komoka, ON[5] Cars in Lobo · asking $5,495
28 Oct 2026	Listing last updated[5] asking $5,495

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 9 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.