Register entry, as of 7 November 2026 Listed for sale Record ID 4621e96d5631

2018 Kia Sorento EX

3.3 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5XY	PHDA5	9	J	G	399706
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Kia Georgia, Inc	Sorento · 3.3 L	Verified	2018	West Point	Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	3.3 L, 6 cylinders
Make	Kia	Fuel	Gasoline
Model	Sorento	Drive	4WD
Trim	EX	Maker	KIA GEORGIA, INC
Body	Sport Utility Vehicle	Plant	West Point, Georgia, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/kia/sorento/2018

7 recalls listed by Transport Canada for this model year

Label

2024549 15 Aug 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Kia has corrected the compliance label for all new vehicles.

Lights and instruments

2023449 11 Aug 2023

Issue: On certain vehicles, wear inside the multi-function switch could cause the headlights to turn off suddenly when the switch is in the AUTO mode. Safety Risk: A loss of headlights would reduce visibility and could increase the risk of a crash. Corrective Actions: Kia will notify owners by mail and advise you to take your vehicle to a dealership to replace certain parts in the multi-function switch. To reduce the safety risk, Kia recommends not to use the AUTO mode until the recall repairs have been completed.

Electrical

2021680 5 Nov 2021

Issue: Certain vehicles may be equipped with an accessory trailer wiring harness that could fail. Over time, water could leak into the control module and cause a short circuit. If this happens, there could be loss of the trailer lights. Note: This recall affects trailer wiring harness kits that may have been ordered at the time of a vehicle purchase, or purchased separately from a dealer as an aftermarket accessory. Safety Risk: A loss of trailer lights could make the trailer less visible. In addition, other drivers may not recognize that the vehicle ahead is braking or intends to turn. This could increase the risk of a crash. Corrective Actions: Kia will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the trailer wiring harness. If the harness is from the lot (batch) affected by this problem, the dealer will replace it. Kia recommends that you should always check to ensure that trailer lights work properly before towing.

Engine

2019143 18 Mar 2019

Issue: Kia Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure may cause a sudden loss of power with an inability to restart. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to update the software for the engine control module. Note: Vehicles repaired under Service Campaign SC023 already have this software update.

Fuel system

2019098 27 Feb 2019

Issue: When the engine was replaced under warranty or under Kia's Product Improvement Campaign SC023, the high pressure fuel pipe may not have been properly installed on the fuel pump outlet. A fuel leak could occur if the pipe was damaged, misaligned or improperly torqued during the recall repair. Safety Risk: Leaking fuel in the presence of an ignition source could increase the risk of a fire. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer for an inspection. If fuel leakage is detected, the fuel pipe will be replaced with a new one.

Steering

2018533 26 Sep 2018

On certain vehicles, the bracket that secures the steering column assembly may have been improperly welded and could separate. If this occurs, a driver may notice a loose feeling and/or a loud clunking noise from the steering column while turning the steering wheel. Ultimately, this could cause a loss of steering control, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the cross cowl bar assembly to ensure the steering column assembly is properly secured.

1 more on the model-year record, cardog.app/tools/recalls/kia/sorento/2018

> Listed for the model year, not checked against your VIN. Kia confirms which apply.
> Check your VIN with Kia Canada or call a Kia dealer with your VIN.
> www.kia.ca/en/owners/recalls

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $15,981[5], $1,986 over the median of $13,995[4].



Lowest ask	$7,900
Middle half	$11,995 – $16,434
Median ask	$13,995
This car	$15,981

Same configuration · 11 live listings · as of 6 Nov 2026

OTHER 2018 KIA SORENTO LISTINGS [5]

Toronto, ON · 177,720 km	$11,995
Gatineau, QC · 139,347 km	$15,544
Vancouver, BC · 78,380 km	$18,995
Brantford, ON · 129,740 km	$18,481
Saskatoon, SK · 148,577 km	$16,995
Langley, BC · 78,380 km	$18,995

§4 EVENTS

2018	Model year 2018[1] Assembly plant West Point, Georgia, United States
21 Dec 2017	Transport Canada recall 2017657[2] Issued for the model year · Airbag
26 Sep 2018	Transport Canada recall 2018533[2] Issued for the model year · Steering
27 Feb 2019	Transport Canada recall 2019098[2] Issued for the model year · Fuel system
18 Mar 2019	Transport Canada recall 2019143[2] Issued for the model year · Engine
5 Nov 2021	Transport Canada recall 2021680[2] Issued for the model year · Electrical
11 Aug 2023	Transport Canada recall 2023449[2] Issued for the model year · Lights and instruments
15 Aug 2024	Transport Canada recall 2024549[2] Issued for the model year · Label
28 Oct 2026	Listed for sale, Bowmanville, ON[5] Next Gen Auto · asking $15,981
6 Nov 2026	Listing last updated[5] asking $15,981

§5 DOCUMENTS

Window sticker	We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 11 live listings, as of 6 Nov 2026

[5] Live public dealer listings on Cardog, as of 7 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.