Register entry, as of 28 October 2026 Listed for sale Record ID 59496c3d2f77

# 2019 Kia Sorento SX, SXL

3.3 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 5XY | PKDA5 | 5 | K | G | 491365 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Kia Georgia, Inc | Sorento · 3.3 L | Verified | 2019 | West Point | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2019 | Engine | 3.3 L, 6 cylinders |
| Make | Kia | Fuel | Gasoline |
| Model | Sorento | Drive | 4WD |
| Trim | SX, SXL | Maker | KIA GEORGIA, INC |
| Body | Sport Utility Vehicle | Plant | West Point, Georgia, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/kia/sorento/2019

**4** recalls listed by Transport Canada for this model year

### Label

2024549 15 Aug 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Kia has corrected the compliance label for all new vehicles.

### Visual system

2023516 18 Sep 2023

Issue: On certain vehicles, water could leak into the rearview camera and cause the rearview camera image not to display. Canadian regulations require the rearview image to display when reversing. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Kia will notify owners by mail and advise you to take your vehicle to a dealership to inspect the rearview camera. The dealer will replace the rearview camera if necessary, and apply additional water proofing to the rearview camera wiring harness.

### Electrical

2021680 5 Nov 2021

Issue: Certain vehicles may be equipped with an accessory trailer wiring harness that could fail. Over time, water could leak into the control module and cause a short circuit. If this happens, there could be loss of the trailer lights. Note: This recall affects trailer wiring harness kits that may have been ordered at the time of a vehicle purchase, or purchased separately from a dealer as an aftermarket accessory. Safety Risk: A loss of trailer lights could make the trailer less visible. In addition, other drivers may not recognize that the vehicle ahead is braking or intends to turn. This could increase the risk of a crash. Corrective Actions: Kia will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the trailer wiring harness. If the harness is from the lot (batch) affected by this problem, the dealer will replace it. Kia recommends that you should always check to ensure that trailer lights work properly before towing.

### Engine

2019639 17 Dec 2019

Issue: Kia Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure may cause a sudden loss of power with an inability to restart. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to update the software for the engine control module.

Listed for the model year, not checked against your VIN. Kia confirms which apply.
Check your VIN with Kia Canada or call a Kia dealer with your VIN.
www.kia.ca/en/owners/recalls

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $19,798[5], $698 under the median of $20,496[4].

| | |
|---|---|
| Lowest ask | $15,990 |
| Middle half | $18,754 – $22,068 |
| Median ask | $20,496 |
| This car | $19,798 |

Same configuration · 12 live listings · as of 28 Oct 2026

OTHER 2019 KIA SORENTO LISTINGS [5]

| | |
|---|---|
| Kamloops, BC · 120,343 km | $14,865 |
| Kingston, ON · 49,308 km | $22,991 |
| Kamloops, BC · 120,343 km | $15,365 |
| Tillsonburg, ON · 0 km | $22,588 |
| Church Point, NS · 73,511 km | $21,895 |
| Nipawin, SK · 168,910 km | $16,998 |

## §4 EVENTS

| | |
|---|---|
| 2019 | Model year 2019[1]<br>Assembly plant West Point, Georgia, United States |
| 17 Dec 2019 | Transport Canada recall 2019639[2]<br>Issued for the model year · Engine |
| 5 Nov 2021 | Transport Canada recall 2021680[2]<br>Issued for the model year · Electrical |
| 18 Sep 2023 | Transport Canada recall 2023516[2]<br>Issued for the model year · Visual system |
| 15 Aug 2024 | Transport Canada recall 2024549[2]<br>Issued for the model year · Label |

| | |
|---|---|
| 20 Oct 2026 | Listed for sale, Brossard, QC[5]<br>Park Avenue Honda · asking $19,798 |
| 27 Oct 2026 | Listing last updated[5]<br>asking $19,798 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 12 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.