Register entry, as of 29 October 2026 Listed for sale Record ID 32392522695d

# 2021 Kia Sorento LX

2.5 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 5XY | RGDLC | 6 | M | G | 005963 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Kia Georgia, Inc | Sorento · 2.5 L | Verified | 2021 | Georgia | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2021 | Engine | 2.5 L, 4 cylinders |
| Make | Kia | Fuel | Gasoline |
| Model | Sorento | Drive | 4WD |
| Trim | LX | Maker | KIA GEORGIA, INC |
| Body | Sport Utility Vehicle | Plant | Georgia, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/kia/sorento/2021

**5** recalls listed by Transport Canada for this model year

### Heater and defroster

2025516 26 Sep 2025

Issue: On certain vehicles, the wiring harness for the blower motor may not have been manufactured properly. As a result, the wiring could overheat and melt. Note: This recall only affects Sorento LX+ models. Safety Risk: Wiring that overheats and melts can create the risk of a fire. Corrective Actions: Kia will notify owners by mail and advise you to take your vehicle to a dealership to replace the blower motor wiring harness and the blower motor resistor.

### Label

2024549 15 Aug 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Kia has corrected the compliance label for all new vehicles.

### Powertrain

2022580 12 Oct 2022

Issue: On certain vehicles, a fault in the transmission oil pump can cause the vehicle to enter "fail-safe mode". When this happens, a programming error can cause a sudden loss of power to the wheels after 20-30 seconds. Note: This recall only affects vehicles equipped with a 2.5 L turbo gasoline (T-GDI) engine and an 8-speed dual-clutch transmission (DCT). Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. Corrective Actions: Kia will notify owners by mail and instruct you to take your vehicle to a dealership to inspect and, if necessary, replace the transmission. The dealer will also update the transmission control unit software.

### Accessories

2022531 20 Sep 2022

Issue: Certain vehicles may be equipped with an accessory trailer wiring harness kit that could fail. Over time, this could result in a short circuit that can cause the control module to overheat. Note: This recall only affects Kia Genuine tow hitch wiring harness kits with the part number R5F03AP100 or R5F03AP200. These kits may have been ordered at the time of a vehicle purchase, or purchased separately from a dealer as an aftermarket accessory. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Kia will notify owners by mail and instruct you to inspect if your vehicle has a trailer wiring harness installed. If it does, Kia advises that you should park your vehicle outdoors, and away from other vehicles or structures until the recall repairs have been complete. The corrective actions for this recall are under development. As an interim repair, Kia will advise you to make an appointment at your local dealership to replace the 30 A "TRAILER" fuse with a 15 A fuse.

### Fuel system

2021421 9 Jul 2021

Issue: On certain vehicles, the connection between the high-pressure fuel pipe and fuel pump may not be properly sealed. As a result, a fuel leak could occur. Safety Risk: A fuel leak can create the risk of a fire. Corrective Action: KIA will notify owners by mail and instruct you to bring your vehicle to a dealer to inspect and replace the high-pressure fuel pipe, as required.

> Listed for the model year, not checked against your VIN. Kia confirms which apply.
> Check your VIN with Kia Canada or call a Kia dealer with your VIN.
> www.kia.ca/en/owners/recalls

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $23,499[5], $1,505 over the median of $21,994[4].

| | |
|---|---|
| Lowest ask | $13,000 |
| Middle half | $19,599 – $23,500 |
| Median ask | $21,994 |
| This car | $23,499 |

Same configuration · 30 live listings · as of 29 Oct 2026

### OTHER 2021 KIA SORENTO LISTINGS [5]

| | |
|---|---|
| Winnipeg, MB · 95,405 km | $27,900 |
| Mirabel, QC · 113,176 km | $21,490 |
| Kitchener, ON · 75,679 km | $30,697 |
| Toronto, ON · 137,988 km | $20,995 |
| Sudbury, ON · 115,787 km | $24,718 |
| Ottawa, ON · 68,164 km | $23,988 |

## §4 EVENTS

| | |
|---|---|
| 2021 | Model year 2021[1]<br>Assembly plant Georgia, United States |
| 9 Jul 2021 | Transport Canada recall 2021421[2]<br>Issued for the model year · Fuel system |

| | |
|---|---|
| 20 Sep 2022 | Transport Canada recall 2022531[2]<br>Issued for the model year · Accessories |
| 12 Oct 2022 | Transport Canada recall 2022580[2]<br>Issued for the model year · Powertrain |
| 15 Aug 2024 | Transport Canada recall 2024549[2]<br>Issued for the model year · Label |
| 26 Sep 2025 | Transport Canada recall 2025516[2]<br>Issued for the model year · Heater and defroster |
| 12 May 2026 | Listed for sale, Milton, ON[5]<br>MILTON KIA · asking $23,499 |
| 28 Oct 2026 | Listing last updated[5]<br>asking $23,499 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 30 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.