

Register entry, as of 28 October 2026

Listed for sale

Record ID 45c12c86e211

2022 Kia Sorento SX/SX-P

2.5 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5XY RKDLF 3 N G 139081

WMI 1-3

Kia Georgia, Inc

DESCRIPTOR 4-8

Sorento · 2.5 L

CHECK 9

Verified

YEAR 10

2022

PLANT 11

Georgia

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2022	Engine	2.5 L, 4 cylinders
Make	Kia	Fuel	Gasoline
Model	Sorento	Drive	4WD
Trim	SX/SX-P	Maker	KIA GEORGIA, INC
Body	Sport Utility Vehicle	Plant	Georgia, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/kia/sorento/2022

7 recalls listed by Transport Canada for this model year

Heater and defroster

2025516 26 Sep 2025

Issue: On certain vehicles, the wiring harness for the blower motor may not have been manufactured properly. As a result, the wiring could overheat and melt. Note: This recall only affects Sorento LX+ models. Safety Risk: Wiring that overheats and melts can create the risk of a fire. Corrective Actions: Kia will notify owners by mail and advise you to take your vehicle to a dealership to replace the blower motor wiring harness and the blower motor resistor.

Label

2024549 15 Aug 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Kia has corrected the compliance label for all new vehicles.

Visual system

2023494 1 Sep 2023

Issue: On certain vehicles, the rearview camera mounting clips could fail. If this happens, the rearview camera could fall out of position and cause the rearview image not to display correctly. Safety Risk: A rearview camera image that doesn't display correctly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Kia will notify owners by mail and advise you to take your vehicle to a dealership to inspect the rearview camera housing, and replace it as necessary.



Powertrain

2022580 12 Oct 2022

Issue: On certain vehicles, a fault in the transmission oil pump can cause the vehicle to enter "fail-safe mode". When this happens, a programming error can cause a sudden loss of power to the wheels after 20-30 seconds. Note: This recall only affects vehicles equipped with a 2.5 L turbo gasoline (T-GDI) engine and an 8-speed dual-clutch transmission (DCT). Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. Corrective Actions: Kia will notify owners by mail and instruct you to take your vehicle to a dealership to inspect and, if necessary, replace the transmission. The dealer will also update the transmission control unit software.

Accessories

2022531 20 Sep 2022

Issue: Certain vehicles may be equipped with an accessory trailer wiring harness kit that could fail. Over time, this could result in a short circuit that can cause the control module to overheat. Note: This recall only affects Kia Genuine tow hitch wiring harness kits with the part number R5F03AP100 or R5F03AP200. These kits may have been ordered at the time of a vehicle purchase, or purchased separately from a dealer as an aftermarket accessory. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Kia will notify owners by mail and instruct you to inspect if your vehicle has a trailer wiring harness installed. If it does, Kia advises that you should park your vehicle outdoors, and away from other vehicles or structures until the recall repairs have been complete. The corrective actions for this recall are under development. As an interim repair, Kia will advise you to make an appointment at your local dealership to replace the 30 A "TRAILER" fuse with a 15 A fuse.

Seats and restraints

2022333 24 Jun 2022

Issue: On certain vehicles, there may be a problem with the front seat belt pretensioners. As a result, the driver and/or passenger seat belt pretensioners could explode in a crash. If this happens, small pieces of metal could hit people in the vehicle. Note: This recall replaces RC160 (Transport Canada recall 2022-102) and only affects Sorento Hybrid (HEV) and Sorento Plug-In Hybrid (PHEV) models. Safety Risk: A seat belt pretensioner that explodes could create a risk of injury. Corrective Actions: Kia will notify owners by mail and instruct you to bring your vehicle to a dealership to install protective caps over the driver and front passenger's seat belt pretensioners.

1 more on the model-year record, cardog.app/tools/recalls/kia/sorento/2022

Listed for the model year, not checked against your VIN. Kia confirms which apply.

Check your VIN with Kia Canada or call a Kia dealer with your VIN.

www.kia.ca/en/owners/recalls

United States: 9 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$32,888^[5], \$1,246 over the median of \$31,642^[4].



Lowest ask	\$28,484
Middle half	\$28,998 – \$32,914
Median ask	\$31,642
This car	\$32,888

Same configuration · 16 live listings · as of 28 Oct 2026

OTHER 2022 KIA SORENTO LISTINGS [5]

Kamloops, BC · 90,064 km	\$26,808
Corner Brook, NL · 97,127 km	\$23,595
Kamloops, BC · 90,064 km	\$26,808
Petrolia, ON · 91,940 km	\$28,999
Mirabel, QC · 54,362 km	\$24,992
Drayton Valley, AB · 75,106 km	\$29,178



§4 EVENTS

2022	Model year 2022 ^[1] Assembly plant Georgia, United States
7 Mar 2022	Transport Canada recall 2022102 ^[2] Issued for the model year · Seats and restraints
24 Jun 2022	Transport Canada recall 2022333 ^[2] Issued for the model year · Seats and restraints
20 Sep 2022	Transport Canada recall 2022531 ^[2] Issued for the model year · Accessories
12 Oct 2022	Transport Canada recall 2022580 ^[2] Issued for the model year · Powertrain
1 Sep 2023	Transport Canada recall 2023494 ^[2] Issued for the model year · Visual system
15 Aug 2024	Transport Canada recall 2024549 ^[2] Issued for the model year · Label
26 Sep 2025	Transport Canada recall 2025516 ^[2] Issued for the model year · Heater and defroster
22 Aug 2026	Listed for sale, Pickering, ON ^[5] Bessada Kia Of Ajax & Pickering · asking \$32,888
28 Oct 2026	Listing last updated ^[5] asking \$32,888

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same configuration, 16 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

