Register entry, as of 28 October 2026 Listed for sale Record ID 88bb6ea330b4

# 2017 Hyundai Santa Fe POPULAR, Premium, TECH, 2.0T, Limited, Ultimate

2.4 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 5XY | ZUDLB | 4 | H | G | 461689 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Hyundai · KIA GEORGIA, INC | Santa Fe · 2.4 L | Verified | 2017 | Georgia | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2017 | Engine | 2.4 L, 4 cylinders |
| Make | Hyundai | Fuel | Gasoline |
| Model | Santa Fe | Drive | 4WD |
| Trim | POPULAR, Premium, TECH, 2.0T, Limited, Ultimate | Maker | KIA GEORGIA, INC |
| Body | Sport Utility Vehicle | Plant | Georgia, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/santa-fe/2017

**5** recalls listed by Transport Canada for this model year

### Label

2024552 23 Sep 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the compliance label for all new vehicles.

### Brakes

2023125 8 Mar 2023

Issue: Hyundai is conducting a special service campaign that provides anti-corrosion treatment to certain underbody components. Over time, components under the vehicle, including brake lines could corrode. If this happens, a brake line could fail and leak. A brake fluid leak can result in reduced braking. Safety Risk: Reduced braking can cause an extended stopping distance and increase the risk of a crash. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to inspect the underbody, including the brake lines. The dealer will apply an anti-corrosion treatment to certain parts, and replace the brake lines if necessary.

### Brakes

2022616 27 Oct 2022

Issue: On certain vehicles, the control module for the antilock brake system (ABS) could short circuit. Note: This recall doesn't affect vehicles equipped with smart cruise control (SCC). This recall replaces Transport Canada recall 2022-046. Vehicles that were already repaired under Hyundai recall R0208 don't require this repair. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealer to replace the ABS multi-fuse. Hyundai advises that you may continue to drive your vehicle, however recommends that you should park it outdoors and away from other vehicles or structures until the recall repairs have been completed.

### Brakes

2022046 3 Feb 2022

This recall was replaced by Transport Canada Recall No. 2022-616 due to increase in the number of recalled vehicles. Issue: On certain vehicles, the control module for the antilock brake system (ABS) could short circuit. Note: This recall does not affect vehicles equipped with smart cruise control (SCC). Safety Risk: A short circuit could create a fire risk. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealer to replace the ABS multi-fuse. Hyundai advises that you may continue to drive your vehicle, however recommends that you should park it outdoors and away from other vehicles or structures until the recall repairs have been completed.

### Structure

2017297 8 Jun 2017

On certain vehicles, the cable between the actuating lever for the secondary hood latch and the secondary latch may become corroded over time. This could cause the secondary hood latch to remain in the open position when the hood is closed. If the vehicle were to be driven with the primary hood latch disengaged, or primary hood latch is released while driving, the secondary hood latch may not hold the hood closed while the vehicle is in motion. If this were to occur, it could compromise the driver's ability to see the road and its users, as well as cause damage to the windshield. These issues could result in a crash causing injury and/or property damage. Correction: Dealers will replace the secondary hood latch cable.

> Listed for the model year, not checked against your VIN. Hyundai confirms which apply.
> Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.
> www.hyundaicanada.com/en/owners-section/recalls

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $14,799[5], $903 over the median of $13,896[4].

| | |
|---|---|
| Lowest ask | $9,116 |
| Middle half | $12,779 – $15,058 |
| Median ask | $13,896 |
| This car | $14,799 |

Same configuration · 52 live listings · as of 28 Oct 2026

### OTHER 2017 HYUNDAI SANTA FE LISTINGS [5]

| | |
|---|---|
| Sherwood Park, AB · 162,213 km | $13,980 |
| Sherwood Park, AB · 162,213 km | $13,980 |
| Vaudreuil-Dorion, QC · 146,357 km | $11,991 |
| Vaudreuil-Dorion, QC · 140,813 km | $11,495 |
| Montréal, QC · 127,652 km | $12,989 |
| Edmonton, AB · 162,213 km | $13,980 |

## §4 EVENTS

| | |
|---|---|
| 2017 | Model year 2017[1]<br>Assembly plant Georgia, United States |
| 8 Jun 2017 | Transport Canada recall 2017297[2]<br>Issued for the model year · Structure |
| 3 Feb 2022 | Transport Canada recall 2022046[2]<br>Issued for the model year · Brakes |
| 27 Oct 2022 | Transport Canada recall 2022616[2]<br>Issued for the model year · Brakes |
| 8 Mar 2023 | Transport Canada recall 2023125[2]<br>Issued for the model year · Brakes |
| 23 Sep 2024 | Transport Canada recall 2024552[2]<br>Issued for the model year · Label |
| 21 Sep 2026 | Listed for sale, Hamilton, ON[5]<br>Right Way Auto · asking $14,799 |
| 28 Oct 2026 | Listing last updated[5]<br>asking $14,799 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 52 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.